SECTION

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement For corners in	of Act 74, Mich. P.A	A. 1970	
Manistee (County)	Located In:	Corner Code #	REGISTER'S OFFICE MANISTEE COUNTY 99-227 at 1:45p
1. Public Land Survey	T_24N R_13W T_23 R_13 T R T R	K-13 Southeast Sec. Corner Sec. 35	JUL 22 1999 BEDSTAN DIX REGISTER OF DEEDS
2. Property Controlling S	T R T R T R T R R T R R T R R R R R R R	Northeast Sec- Cor- Sec. Z	Register of Deeds Stamp & File Number
1, Anthony M. Slawinski, in a field under requirements of P.A. 74, Michigan Rabove were in conformance with regulation survey instructions of the United States Day a decree of a Court of Law and /or the were in conformance with the rules of the Court of Law; established, re-established,	P.A. of 1970, the corner ns and rules therefore as department of the Interior at the corner points mer e Michigan Board of Lar	points mentioned in lines 1 and 2 s required in the current manual of r, Bureau of Land Management of ntioned in lines 3, 4 and 5 above nd Surveyors or by a Decree of a	3 4 7 8 9 10 11
NOTE: Not more than 2 corners, all on this certificate.	in the same town and	d range, may be recorded	7 16 15 14 7 7 8 19 20 21 22 23
A. Description of original monument K-13 Southeast Section Corner, Secti T24N, R13W		•	1 30 29 28 27 26
Set by John Brink in 1838 1. Sugar 11"dia. N 38° E 1.34 links 2. Cherry 10" dia. N 71° W 30 links			12 31 32 33 34 35
Survey Certificate by Gourdie, Fraser & Associates 1973			
Survey Certificate by Gordon Bonney Fd Railroad Spike 3. S 35° W 70.50′ 8″ Pine 4. S 45° W 73.40′ 8″ Pine 5. N 26° W 106.6 Power Pole	(Good) a (Gone) a	ccording to the county plan a	ified by the Manistee County Peer Group dopted pursuant to P.A. 345 of 1990, rvey and Remonument Act, Mal. 54.261
Survey Certificate by Bonney, 1998		· kusum	JUL 6 1999
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: K-13 Southeast Section Corner, Section 35, T24N, R13W & Southwest of Section 36 T24N, R13W			
On June 4, 1999, I Anthony Slawinski, with a field crew from Abonmarche found a 12" cabin spike in a monument box. I found no other evidence to dispute this location for the corner.			
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: K-13 Southeast Section Corner, Section 35, T24N, R13W & Southwest of Section 36 T24N, R13W			
On June 4, 1999 I set a Manistee County Monument within a monument in the exact location of the above mentioned Cabin spike as a careful and faithful re-establishment of the position of the original corner and witnessed by:			
 S 28° W 70.40′ 8″ Jack Pine (Fd. Nail on East side of tree) N 26° W 106.52′ Power Pole (Fd. Nail on West side of pole) S 47° E 73.31′ 7″ Jack Pine (Fd. Nail on East side of tree unknown origin) N 25° E 86.72′ 6″ Jack Pine (Fd. Nail on West side of tree unknown origin) 			
Note: Corner is in the centerline of 13 Mile Rd. and Viaduct Rd. ANTHONY ANTHONY			
Signed by Anthony m.	Slawin	shi slawins surveyo	
Surveyor's Michigan License No. 135	<u>97</u>	(G) NO. 13597	[\$\varphi\]

PAND LAND

TE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT.. 1995