LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

For corners in	·		
Manistee (County)	Located in:	Corner Code #	REGISTER'S OFFICE MANISTEE COUNTY 00 - 293 p+ 11:08p-m
1. Public Land Survey	T <u>24N</u> R <u>14W</u> T R	C-13 SE Sec Corner	SEP 0 3 2000
	TR_ T_23N_R_14W	Sec 31 C-01	REGISTER OF DEEDS
2. Property Controlling in Section	S T R S T R	NE Sec Corner Sec 6	
3. Miscellaneous Property in Sec.	S T R		Register of Deeds Stamp & File Number

I, Anthony M. Slawinski , in a field survey on June 9 , 20 00 do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

- Description of original monument and accessories and/or subsequent restoration: Southeast Corner of Section 31 (24-14) & Northeast Corner of Section 6 (23-14) Set by John Brink in 1837.
- 1. Hemlock 14" in dia. N 71° E 42 links (27.72')
- 2. Hemlock 12" in dia. N 77½° W 80 links (52.80')

, Recorded Plat

P.A. 74 Form by Jerry L. Wilcox RLS #14102, 1974 Fd. 3/4" rod in E-W road. (74 - 41)

- 3. Birch 6" in dia. N 45° E 32.62'
- 4. Birch 6" in dia. N 25° W 44.20
- 5. Fence corner South 76.53'

4. Lot No. 5. Private Claims

OCT 03 2000

Survey Map by Wilcox & Associates in 1974 Fd. ¾" iron rod 2622.20' West of S ¼ corner of Section 32 (24-14)

SECTION

Description of corner evidence found and/or method applied in restoring or reestablishing corner: Southeast Sec. Corner Section 31 (24-14) & Northeast Corner of Section 6 (23-14) On June 9, 2000, I, Anthony M. Slawinski along with a field crew from Abonmarche found a 1 1/2" iron pipe ±16' North of the center line of 13 mile road. The distance between this corner and the South ¼ corner of Section 32 was checked against the Wilcox distance and it checked to be within 0.24'.

Condition of witnesses: #1 gone, #2 gone, #3 good, #4 gone, #5 gone

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Corner Common to Sections 31 + 32 (24-14) + Sections 5+ 6 (23-14) On June 9, 2000, I installed a Manistee County Monument in the exact location of the above mentioned 1 1/2" pipe as a careful and faithful re-establishment of the position of the original corner and witnessed by:
- 3. N 45° E 32.56' 12" Birch (Set 60d spike in S. side of tree)
- 6. N 34° E 24.83' 12" Maple (Fd. Nail & washer on W. side of tree)
- 7. S 10° E 97.25′ 18" Red Pine (Fd. 60d spike on W. side of tree) 8. South 49.41' Iron pipe w/survey cap #13597 on S.

Corner is set 6" below grade on the shoulder of 13 mile road, ±16' North of the center line of 13 mile road.

AWINSKI NO. 1359

Date

Surveyor's Michigan License No. 13597

IGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 197 REVISED MAY 14,197! REVISED JAN., 198:

18

REVISED OCT., 1991

State Survey and Remonument Act, pursuant to

. S