OCT 3 1 1994

## LAND CORNER RECORDATION CERTIFICATE

For corners in	COMMISSIO
FOCULIDATES III	en de resurrido dos dos

COMMISSION	Filing Requirement of Act 74, Mich	. <b>P.A.</b> 1970

1. Public Land Survey T <u>23N</u> R <u>15W</u> <u>C-03</u> T	manistee county #94-321 at 4:55pm. JUL 1 1 1994
T R	Penney a. Pepen
T R	REGISTER OF DEEDS  Register of Deeds Stamp & File Numbe
Property in Sec. S T R L  4. Lot No, Recorded Plat  5. Private Claims	A B C D E F G H   J K
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points ment in lines 1 and 2 above were in conformance with regulations and rules therefore as required current manual of survey instructions of the United States Department of the Interior, Bureau of Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree Court of Law; established, re-established, monumented, re-monumented, recovered, four expressed below:	in the factor of
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.  A Description of original monument and accessories and/or subsequent restoration	12 31 32 33 34 35- 13

C-03 SE cor sec 6

T23N R15W

1839 James Higbee D.S. G.L.O. Page 235. Set post cor to sec's 5-6-7 & 8

Manistee County Road Commissign

Beech 10" N63°W 43 1ks. (28.38) #1

#3 NW 44.1 22" Maple

Beech 12" S81°E 64 1ks. (42.24)

#4 NE 45.5 20" Walnut

#2 SW 42.6 21" Maple

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

C-03 SE cor sec 6

T23N R15W

On June 30, 1994 found P.K. Nail, under P.K. nail found a 3/4" iron rod 18" long.

Condition of record witnesses are; #1, #2, #4 are gone #3 and #5 are in fair condition.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: C-03 SE cor sec 6 T23N R15W

Replaced P.K. nail with a Manistee County monument placed in a monument box, and is accepted as a careful and faithful reestablishment of the position of the original cor.

N35°W 56.65 09" Fir N60°W 45.23 24" Maple. S60°W 43.44 24" Maple N53°E 62.05 29" Maple

Surveyor's Michigan License No.

Date

ratified by the Manistee County Peer C

2

according