Signed by <u>Awthony m.</u>
Surveyor's Michigan License No. <u>13597</u>

OCT 0 3 2000

LAND CORNER RECORDATION CERTIFICATE

CECTION

Filing Requirement of Act 74, Mich. P.A. 1970 For corners in			2 2 M 6 1 15 18 18 18 18
Manistee (County)	Located In:	Corner Code #	REGISTER'S OFFICE MANISTEE COUNTY
 Public Land Survey Property Controlling Section Miscellaneous Property in Sec. Lot No	T 24N R 14W T R T R T R T 24N R 13W S T R S T R S T R S T R S T R	M-03 SE Sec Corner Sec 1 A-03 SW Sec Cor Sec. 6	SEP U 3 2000 SEP U 3 2000 Penny Or Papera REGISTER OF DEEDS Register of Deeds Stamp & File Number
I, Anthony M. Slawinski, under requirements of P.A. 74, Mabove were in conformance with survey instructions of the United by a decree of a Court of Law were in conformance with the recourt of Law; established, re-est	Michigan P.A. of 1970, the corner regulations and rules therefore a States Department of the Interic and /or that the corner points me		A B C D E F G H I J K 2 6 5 4 3 2 3 4 7 8 9 1.0 11 5 6 18 17 16 15 14 7 8 9 20 21 22 23
			10 30 29 28 27 26 11 31 32 33 34 35
Copy of Minutes of Survey in 19 Fd. Decays of Stake and Bearing 3. Cedar Telephone Pole 10" in c4. White Pine Stumps 36" in dia.	Tree stumps, Set Bottles. lia. S 40° E 54 links (35.64')		13
Manistee County Surveyor's Rec Fd. ½" Iron Rod 5. Stump. 6" in dia. N 75° E 63 8. Poplar 5" in dia. East 44.34' 9. Iron wood 10" in dia. S 80° E 10. Iron wood 10" in dia. S 40°	.28' .56 85'	and the county plan added, (being the State Survey). Date of Peer Reviews	fied by the Manistee County Peer Group opted pursuant to P.A. 345 of 1990, rey and Remonument Act, MCL 54.261 1-31-00
5. Poplar 8" in dia. N 75° E 63. 6. Telephone Riser Post S 20° E	nbacher RLS #18990 in 1977, (-) 28'	4	Grothay m. Glownski
Certificate of Survey by Anthony Fd. Stake and Bearing Tree stum 3. Cedar Telephone Pole 10" in c 4. White Pine stump 36" in dia.	ps & bottles lia. S 40° E 54 links (35.64')	M.D.O.T. R/W Map No iron stated, no witnes undated	sses
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Southeast Section Corner Section 1 (24-14) & Southwest Section Corner Section 6 (24-13) On June 2, 2000, I Anthony Slawinski, along with a field crew from the Abonmarche Group found ½"x24" iron rod over a 2" pipe (2" pipe +/- 39" deep). The crew found no other evidence to dispute this location for the corner.			
Condition of witnesses: #1 gone, #2 gone, #3 gone, #4 gone, #5 gone, #6 gone, #7 good, #8 gone #9 good, #10 good			
Southeast Section Corner Section On June 2, 2000, I placed a Mar	n 1 (24-14) & Southwest Section listee County Monument, over a t	ed to perpetuate locating the position Corner Section 6 (24-13) the existing 2" pipe, in the exact loc of the original corner, and witnessed	atio n as t he above
10. S 40° E 60.35′ 12″)ronwo 11. N 51° E 64.48′ 9″ Poplar (ood (fd. spike in N side of tree) ood (fd. spike in N side of tree)	(P) S	LAWINSKI CONTROLL OF THE PROPERTY OF THE PROPE

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1976 REVISED JAN., 1983 REVISED OCT., 1995

Date