OCT Va 2000

the social

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mlch. P.A. 1970

Manistee (County)		Located In:	Corner Code #	REGISTER'S OFFICE MANISTEE COUNTY
1. Public Land Survey		T 24N R 14W T R R	M-06 E½ Sec 13	SEP 0 3 2000 Penny a Repera
 Property Controlling in Section Miscellaneous 	s s s_	TR TR TR		REGISTER OF DEEDS
Property in Sec. 4. Lot No, Rec 5. Private Claims	S_ corded	TR Plat		Number
under requirements of P.A. 74, above were in conformance with	Michigan regulati	P.A. of 1970, the corne ions and rules therefore a	6 , 20 00 do hereby state the repoints mentioned in lines 1 and its required in the current manual of Purcey of Land Management.	2 of 2 6 5 4 3 2 1

by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration: East 1/4 Corner Section 13 (24-14)

Set by John Brink in 1837.

For corners in

1. Beech 10" in dia. S 461/2" W 22 links (14.52')

2. Hemlock11" in dia. N 331/2° W 40 links (26.40')

Manistee County Surveyor's Record By Millard in 1909, found gas pipe No witnesses

Land Corner Record by Kenneth Ostling RLS #10068, in1960. (Rec. 70-31)

Fd. 1" Pipe in line with fence east.

Jack Pine 5" in dia. N 66° W 119 links (78.54')

Red Pine 8" in dia. S 26° W 1351/2 links (89.43')

Fence Corner East 50 links (33.00')

Description of corner evidence found and/or method applied in restoring or reestablishing corner: B.

East ¼ Corner Section 13 (24-14)

On June 6, 2000, I, Anthony M. Slawinski, along with a field crew from Abonmarche found a 1/2" iron rod. We found no other evidence to dispute this location for the corner.

Condition of witnesses: #1 gone, #2 gone, #3 gone, #4 good, #5 remains of fence found.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: East 1/4 Corner Section 13 (24-14)

On June 6, 2000, I placed a Manistee County Monument, in the exact location as the above mentioned ½" iron rod as a careful and faithful re-establishment of the position of the original corner, and witnessed by:

4. S 26° W 89.62' 17" Red Pine (set 60d on E. side of tree)

6. S 54° W 33.18′ 6″ Jack Pine (fd. 60d on SE side of tree) 7. S 77° W 40.99′ 8″ Jack Pine (fd nail on N side of tree)

8. S 21° E 53.46′ 10″ Cherry (set 60d on SW side of tree)
9. S 30° W 56.67′ 8″ Jack Pine (set spike on NW side of tree)

Corner is 3' West of centerline of Thompsonville Road and 6" below grade. Corner fits occupation, fence line runs East.



ratified by the Manistee County Peer Group Corner 1 - 0 6 according to the county plan adopted pursuant to P.A. 345 of 1990, as amended, (being the State Survey and Remonument Act, MCL 54.261 et seg.). Date of Peer Review: 7-31-00

Slawinski 7-26-00 Surveyor's Michigan License No. 13597