00	n A	A E		5 h	£ 22.70	8.1
31 x 5 6	1500	5 46	# L 13	6 737	8 .	

LAND CORNER RECORDATION CERTIFICATE

For corners in		Filing Requi	. 1970 AT <u> </u>	AT 2:35 O'CLOCK P			
	MASQNunty	Located In:	Corner Code ≠≠		OCT I	3 1993	!
	Public Land Survey	T <u>17</u> NR <u>16W</u> T R T R T R	<u></u>	<u> </u>	MARY GOLD Mason Register	COUNTY	
	Property Controlling in Section Miscellaneous Property in Sec.	S T R S T R S T R		Register of D	eeds Stamp	& File Nur	nber
4.	Lot No	Recorded Plat		A B	CDEF	G, H I J	KLM
5 .	Private Claims			<u>ji ji</u>	TITI		
		•		2 8	1 5 1 - f	 - - - -	¦- - -
				3	++++	╂╌┼╌┼╌	
				⁴┝╌┆─	├ ─ ह ─ ├─	 101	1
1, _		, in a field survey onOCT			 	╂┈╂┈┼┈┤	┢═╂═┼┈┤
		equirements of P.A. 74, Michigan P.a. in conformance with regulations a			1/71/8	 5 1	4
CUI	rrent manual of survey ins	tructions of the United States Dept	ariment of the Interior, Bureau of La	nd 7	╂╼╂═╂═╂	++-+-	│ —┃—┃
Ma	nagement or by a decree	of a Court of Law and/or that the core	ner points mentioned in lines 3, 4 an	d5 aa_	2021	222	324
abo	ove were in conformance	with the rules of the Michigan Board	of Land Surveyors or by a Decree of	of a			
	ਸ਼ਾਰ of Law; established, pressed below:	re-established, monumented, re	-monumented, recovered, tourid	10 _30_		272	B 25
		corners, all in the same town	and range may be recorded	11 1			
NC	on this certificat		and lange, may be recorded	1231	32 33	343	5 36
				13			
A.	Description of origina	al monument and accessories a	nd/or subsequent restoration:				
	F-3 1/4 Corner, Sec	s. 4 & 9	G-4 1/4 Corner,				
	1838 John Hodges			dgeson set Pos	t		•
	10" Hemlock for	corner	18" Beech S				•
	no witmess .	,	17" Beech N	45 E 33 lks		•	•

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

F-3 1/4 Corner, Secs. 4 & 9 Ross 1988 Fd 1/2" re-rod 24" Maple \$ 50 W 59.35' 28" Tw. Maple S 05 W 60.93' 28" W. Cak N 50 E 33.85' Fence to South Dist to NW cor = 2658.89' Dist to NE cor = 2666.17'

G-4 1/4 Corner, Secs. 9 & 10 Ross 1973 Fd nail on E-W fence line no witness Ross 1988 Fd 1/2" Iron on Pavement no witness

FILED

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

KAND

F-3 1/4 Corner, Secs. 4 & 9 Found 1/2" re-bar w/large piece of flat iron next to it in North 1/2 of dirt/gravel rd. Fd existing witness, replaced with 5/8" X 36" re-bar with 2 1/2" alum. cap set 0.8' below road surface 3' South of N. edge of road, and is accepted as the best available evidence of the original corner. 30" Maple N 07 W 66.66' 28" W. Oak N 53 E 33.66' 28" Tw. Maple S 14 W 60.88 24 Maple \$ 53 W 59.29' Signed by ____ Iron South 33.02

G-4 1/4 Corner, Secs. 9 & 10 Found 1/2° Iron rod in pavement, replaced with 5/8" X 24" re-bar with 2 1/2" alum. cap also placed monument box Iron set 0.3' below road surface in monument box, and is accepted as the best available evidence of the original corner P. Pole N 80 W 39.24'

P. Pole 5 06 w 430.10' 30" W. Pine S 72 E 142.48' 4" J. Pine S 73 W 153.79"

Date 10 -/2 -9=

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

3 PAGE 133

Surveyor's Michigan License No.

LIBER