IAN 2 3 2001

JAN 2 200:	LAND CORNER	RECORDATION	CERTIFICAT	E							
SECTION Filing Requirement of Act 74, Mich. P.A. 19			Mich. P.A. 197	70 FILED							
For corners In: Mason County	Located In:	Corner Code	#	\T <u></u>	1.15	0	CLOCK	<u> </u>	<u>P.</u> 1	М	
Public Land Survey .	T 17N R 17W_	I-6				O UI		000 (I ELLIO			
	TR TR					MAS0	N COU R OF C	NTY			
Property Controlling S S In Section S Miscellaneous S Property in Sec. S	T R T R T R T R T R		Re	giste				& File !	Numb	ər	
1. Lot No, Recorded					A B (C D	E F (Э H !	JK	LM	
5. Private Claims	· · · · · · · · · · · · · · · · · · ·	,		2	6	5	4	3	2	1	
, Kenneth L. Ross in a field survey on September 18, 2000, Do hereby certify that under equirements of P.A.74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2				3 4 5	7	8	9	10	11	12	
above were in conformance with regulations and rules therefore as required in the current manual survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: 'A corner common to sections 14 and 15 of T17N, R17W			e current manua Land	6	18	17	16	15 🕽	L 14	13	
			d Surveyors or by	, , , , ,	19	20	21	22	23	24	
				10 11	30	29	28	27	26	25	
				12	31	32	33	34	35	36	
A. Description of original monu		•									
GLO Hodgson 1838 Set qr. sec. post Seech 4" S53E 19 lks. (12.54') #1 Sugar 6" N17W 16 lks. (10.56') #2	Ross RLS 17634 LCRC & unit July 1974, L1 P196 Set ½" re-bar on E-W fen. 30" maple NW 54.78' #3 8" maple W. 34.93' #4 Dist. North to I-5 2608.52' Dist. South to I-7 2604.93'	ec. survey	Schulke RLS 30894 "found & Excepted existing iron as Public Land Corner" (I believe he meant accepted)								
John Mitchell B1 P86 & 87 March 1880 '1/2 post established by stone"	Ross RLS 17634, 1990 & 1990 Unrecorded surveys "reset 1" pipe"	3									
Griswold 1888 B1, P201 Nothing set	No witnesses										
B. Description of comer evidence	e found and/or method a	pplied in restorin	ng or reestablis	hing	comer	:					
found a 1" x 18" iron pipe 6" below the s	urface 1' west of the centerline	of a N-S gravel road.									

Condition of the witnesses are as follows: 1, 2, and 3 are gone, 4 is in good condition

3. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

replaced the 1" x 18" iron pipe with a Harrison monument stamped "Mason County Monument RLS 17634". I accepted this as a careful and faithful reestablishment of the position of the original corner.

PP S80W 34.36' (set mag. nail North side) #5 36" Maple N30W 54.85' (Ex. 60d spike West side) #3 PP N17E 96.68' (set mag. nail West side) #6 SE corner concrete block foundation N45W 164.74' #7

Surveyor's Michigan License No. 17634

-09-ZE00

FORM APPROVED BY MICHGAN STATE BOARD OF LAND SURVEYORS, JAN. 28,

KENNETH L. ROSS LAND SURVEYOR No. 6

1971 REVBED MAY 14, 1976 REVISED JAN., 1983 ADAPTED FOR WORD PROCESSING MARCH, 1943

LIBER PAGE