FEB 0 8 2000

rveyor's Michigan License No. 17634

•	LAND CO	RNER RECORDATION CERTIF	ICATE						
SECTION	√ Filing Requ	irement of Act 74, Mich. P.A	. 1970	1.1.2	FI	LED			
orners in			AT /	8:34	י חיר	LOCK_	_/[		
IASON	Located In:	Corner Code #	ے۔ ''ا	<u> </u>	0	LUUN_		·	_M
(County)		}	.50	- {					1
		Į.		_   N	10V		ng [		
	T 10M D 16M	ν <sub>-1</sub>		1 "		V 100	~		
ublic Land Survey	T 18N R 16W	<u>K-1</u>	. ]						- }
	Ţ R			MARG/	ARET KO	)LASKI	<b>ELLIOT</b>	T	
	T R R				Mason	COUN	ΓY		ŀ
asset Controlling S				RE	GISTER	OF DE	EDS		- 1
roperty Controlling SSection S	T	**************************************							
1iscellaneous	$-\dot{s}$ $\dot{r}$ $\dot{r}$ $\dot{r}$		Regist	ter of De	eds Si	tamp &	k File I	Numbe	er
	· · · · · · · · · · · · · · · · · · ·	<del></del>	<u></u>						
roperty in Sec. S	T R								
					• .:				
ot No, Record	led Plat		<del></del> ,	А В С	D 6	F 6	H I	JK	L M
rivate Claims									
			2	? 6	5	4	3	2	1
			3	·					
enneth L. Ross	in a fie	ld survey on September 10, 1999,	4	1 7.	8	9	10	11	12
entificity that under requirer	ments of P.A. 74. Michigan I	P.A. of 1970, the corner points mentione	ed g	,					<u></u>
es 1 and 2 above were in con	formance with regulations	and rules therefore as required in the	ne ,	1	1.7	14	15	1.4	13
nt manual of survey instructions	s of the United States Dep	artment of the Interior, Bureau of Lan	d c	'-	17	16	io :	1.4	13
gement or by a decree of a Cou	irt of Law and/or that the co	orner points mentioned in lines 3, 4 and rd of Land Surveyors or by a Decree of	5 7 a	1					
<ul> <li>of law established re-es</li> </ul>	stablished monumented.	re-monumented, recovered, found a	s s	19	20	21	22	23	24
ssed below:		•	۶	·					
			1	0 30	29	28	27	26	25
'E: Not more than 4 corne	ars, all in the same tow	n and range, may be recorded	1	,					<del> </del>
on this certificate.			1:	1	32	33	34	35	36
		es and/or subsequent restoration			UL.		-		
. Corner Common to Sect:	ions 1 and 2, T.18N.	. R.16W.,	'						
, Corner Common to Sect nd 4" % 25" rerod and So ker Road to West and 5'	links (11.88') Links, (11.88') , page 312 £313 s "Government new Witensess Given .08' 9.24'  dence found and/or met ions 1 and 2, T.18N. urveyors Cap (unread South of the center	hod applied in restoring or reesta	2632.08' 2638.02' 994. Act fied this 6W., sses give ablishing co	132, Toor. Son.	in the	f Corn , No o J-1, to K-2 e cent	er K-1 2639 , 2646 er-11; the	13, T. Litness .23' 0.72'	19N.,
Corner Common to Sect eplaced the '' re-rod a inty Monument" 1 foot be center-line of Decker	ions 1 and 2, T.18N.  Ind cap in the exact low the surface of D Road to the West pro best available ev  side of Guy Pole, S6 side of P.P. N45°W,	location with a Standard 3" ecker Road, in the center-li jected and 5' South of the C idence of the re-establi: 2°W, 40.28' 46.51'	Cast Iron ne of Reel enter-line	Harris k Road e of De	on Mon to the cker R	ument North	stamp proj	ected East.	and This
Existing 60d Nail in T						5°5.	,• 		
K-13, T.19N., R.16W.,	East 9.22'	•	• • • •		<u>.</u>		EHNETH		
TE: GLO set this corner	15.5' East of Corn	er K-13, T.19N., R.16W., but	, nistorio	carly 1t	. nas i	oeen u	_		1
					= =	*	SUR	VEYOR	٤
	_		1	ຼ ດ	ດດ້	*		10.	
/		LIBER	<b>4</b> PAG	t <b>2</b>	J 4	100	17	634	+ . (8)
		·	1			20/5	ege.		BACTE
<i>y</i> .						- 1/2	**F# 1	1933 1	4.7

Kenneth L. Fiss Maxon County Surveyor