

DEC 1 8 1995

	L	AND	CORNER	RECORDATION	CERTIFICATE
--	---	-----	--------	-------------	-------------

For corners in COMMIS	SSION Filing Requi	rement of Act 74, Mich. P.,	A. 1970 FILED
MASON (County)	Located In:	Corner Code ##	AT 9:28 0'CLOCK a M
1. Public Land Survey	T <u>18 N</u> R <u>17 W</u> T R	H-1	SEP 29 1995 Mary Golden Kolaski
2. Property Controlling in Section	T R S T R S T R		MASON COUNTY REGISTER OF DEEDS
3. Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
4. Lot No, R 5. Private Claims	Recorded Plat		A B C D E F G H I J K I
do hereby certify that under req in lines 1 and 2 above were in current manual of survey instru Management or by a decree of a above were in conformance wit	in a field survey on Septe quirements of P.A. 74, Michigan P.A. conformance with regulations a actions of the United States Depart Court of Law and/or that the corn the rules of the Michigan Board e-established, monumented, re-	of 1970, the corner points mention of 1970, the corner points mention of the Interior, Bureau of Lerpoints mentioned in lines 3, 4 arous fand Surveyors or by a Decree	oned 6 18 17 16 15 14 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
NOTE: Not more than 4 co on this certificate.	orners, all in the same town a	nd range, may be recorded	11 12 31 32 33 34 35
A. Description of original r	monument and accessories an	d/or subsequent restoration:	13

- H-1
- North 1/4 Corner for Section 3, T18N, R17W, on the township line

Note; This Corner was not set by original G.L.O. survey.

1902 R.O. Towns, MCS

Identified corner as a stone

no witnesses taken

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- North 1/4 Corner for Section 3, T18N, R17W, on the township line

ON September 14, 1995, I found a 1/2" Re-rod 5' North of the center-line of Decker Road(gravel), just below the surface, I also found 3 old witness trees, that fit this location, but at this time I have not recovered a writen record of this witnesses, I also found a concrete monument(plat type) South, @ 33.38 feet(Ross RLS Cap) and the South 1/4 Corner for Section 34, T19N, R17W, (1/2 Re-rod), I found no other evidence to dispute this location for the Corner.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- H_1 North 1/4 Corner for Section 3, I18N, R17W, on the township line

I replaced 1/2" Re-rod with a 5/8" Re-rod, 24 long, stamped MASON COUNTY MONUMENT, aluminum cap($2\frac{1}{2}$ in dia.) placed 0.5 feet below gravel road, and is accepted as a careful and faithful reestablishment of the position of the original corner. E OF MICH

S 42° E 43.38'(60d spike in SW side of tree) White Pine 14" OBT White Pine 28" N 62° W 29.17'(60d spike in NE side of tree) S 38° W 36.65'(60d spike in NW side of tree)S. Maple 18" S, Maple 7" S 26° W 51.43'(60d spike in SE side of tree) White Pine

N 18° W 50.37'(60d spike in NE side of tree)

Sammy & Barett

and Approved

FORM APPROVED BY MICHIGAN STATE BOARD

OFE SSION AND THE EVERS, JAN. 28, 1971 REVISED MAY 14, 1975

REVISED JAN., 1983

SAMMY S.

BARNETT

PROFESSIONAL SURVEYOR

No.

16923

Surveyor's Michigan License No. 16923

3PAGE 300

Kenneth L. Ross Mason County Surveyor