## **SURVEY &** REMONUMENTATION

JAN 2 3 2001

SECTIO	Filing Requi	Filing Requirement of Act 74, Mich. P.A. 197							
For corners In:	Located In:	Corner Code #	AT_	9:3	<u>'</u>	O'CLOC	К	1.	M
Mason County								7	
Public Land Survey	T 18N R 17W T R R	L-3		MAF	RGARET	KOLAS	KI ELLI	TTO	
Property Controlling S S     in Section S     Miscellaneous S S     Property in Sec. S	T R T R T R T R T R T R T R T R T R T R		Regist		REGIS!	<u>:R 07  </u>	<u> </u>	*********	er
4. Lot No, Records 5. Private Claims	ed Plat		,	A - B	C D	E F (	э н	I J K	L A
				6	5	4	3	2	1
I, Kenneth L. Ross in a field survey on June 8, 2000, Do hereby certify that under requirements of P.A.74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as				7	8	9	10	11	12
				18	17	16	15	14	13
				19	20	21	22	23	24
expressed below:  % corner common to sections	1 and 12 of T18N, R17W.		9 10 11	30	29	28	27	26	25
A. Description of original monument and accessories and/or subsequent restoration:				31	32	33	34	35	36
GLO Sibley 1839 Set gr. post Beech 12 N81E 16 lks (10.56') #1 Beech 12 S61W 8 lks (5.28') #2 Stephens RLS 7318 unrecorded 1968 Set 1" pipe	Ross RLS 17634 Unrecord Ex. 1° pipe No witnesses taken Bonney RLS 12016 L2, P57 Oct. 1978 30" Maple N10E 42,70' #4	Fd. 1* iron bar flush with 30" Maple N10E 42.70' Cor. Fence post Due So	surface of #4 uth 37.32' #5	Hanser					

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

8" Maple N30W 35.25' #5 Fence post South 37.25' #6

I found a 1° pipe in a monument box 1 ft. North of the centerline of E-W Road.

Condition of the accessories are as follows: 1, 2, and 7 are gone. 4, 5, 6, and 7 are in good condition. I found no spikes or nails in 4, 5, 6 or 7.

I found nothing to dispute the location of this corner.

3 Maples N18E 42.83' #4 Fence to South Centerline Hansen Rd.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I replaced the 1" pipe in the monument box with a 4" x 18 ½" Harrison Monument stamped " Mason County Monument 17634" and accepted this as a careful and faithful reestablishment of the position of the original corner.

P. Pole S65E 82.03' Set mag. nail NE side P. Pole S78W 131.17' Set mag. nail N side 10' Maple N26W 35.40' Set 60d spike E side #5 15' Tw. Maple N15E 42.93' Set 60d spike E side #4

KENNETH L. ROSS LAND SURVEYOR No. 7 6 3 4

Surveyor's Michigan License No. 17634

Kenneth L. Ross, County Representative

FORM APPROVED BY MICHGAN STATE BOARD OF LAND SURVEYORS, JAN. 25,

ţ

1971 REVISED MAY 14, 1976 REVISED JAN, 1943 ADAPTED FOR WORD PROCESSING MARCH, 1983

R

8-10-2000

Approved by Peer Review Group on