OCT 2 9 1995

COMMISSION	LAND COR	NER RECORDATION CE	ERTIFICATI	=			_			
	Filing Requ	irement of Act 74, Mich	n. P.A. 197 0		FIL	ED				
FOR COUNTY (County)	Located in:	Corner Code #	AT 9:	٢		LOCK		<u>a_</u>	M	
1. Public Land Survey	T 19N. R 18W. T R T R	M-10	 	MAR'	y GOL	5 ig	OLAS	KI		
Property Controlling S	T R T R T R T R T R		Re	RE	GISTE		DEEDS		ımber	
4. Lot No, Recorded	d Plat			1 .	\ B (Ċ D	E F	<u>е н</u>	IJK	L
				2	6	5	4	3	2	1
THEODORE H. WEINERT		vey on AUGUST 15, 1996 ,		4		8	9	10	-11	12
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the ourrent manual of ourvoy instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5					18	17	16	15	14	13
above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded			Decree of a	8	1 9	20	21	22	23	- 24
			orded	10 11	30	-29	- 28	27	26	25
on this certificate.				12	31	32	33	- 34	- 35	36
A. Description of original monumulate and Brookfield Set Post at 40 chains f Witnesses Taken: (1) Be 1972, Kenneth L. Ross, fence corner". Witness 5, 1974, Herbert L. Flu Hammar Pipe, RLS Cap, 17334 61.38'. Sam Barnett, RL "3/4" iron pipe." Witness	laid out the Townshi from SW Corner of Sec each, 8", S 50* W, 24 RLS, Filed an LCRC, ses Given: (3) 8" Wh tharty, RLS, filed an I, Witnesses Given: (S tied into this cor	p Lines in 1837 to 1833 25 and 40 chains from l links, (2) unreadable Liber 1, Page 20, Mason ite Pine NE, 39.52', (4) d LCRC, Liber 1, Page 13 3) above, (5) Poplar, 19 ner while completing a	8. m NW Corner , 12", N 28 n County Re 4) 4" White 273, Mason S48•W, 29.4 survey in	e W, cord: Pine Count	13 l: s, Sta e SW, by Rec (6) 6"	ited " 12.72 cords, Mapl	Set] ' Or State e Clus	" pip le Oct ed " F ter, l	e at ober ound 176•W,	

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

The Corner as described above had been destroyed or pulled. Reset by Witnesses, (3) (4) (5) and (6) above.

Witness (5) above has been cut down, but the stump remains in place at this time and fit the corner location.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

Set a 5/8" X 3' Re-rod with a "Standard Mason County Monument Cap" and is accepted as a careful and faithfull reestablishment of the position of the original corner.

Witnesses Taken:

Spike in 6"X/8" Treated Gate Post, S72-W, 13.81' Steel Rail Road Track (Gate Post), S88 E, 15.14 Spike in 8" Pine, N34.W, 57.95' Spike in 12" Pine, N25.E, 40,18' Witness (3) above

3" Steel Post filled with Concrete, S45*E, 2.25' Old Gate Post)

Fence Corner Post, South 1.2'
Witness (2), (4), and (5) above are in good condition.

Date

Surveyor's Michigan License No. 19846

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAM. 28, 1971 REVISED MAY 14, 193 REVISED JAM., 194 ADAPTED FOR WORD PROCESSING MARCH. 199

Kenneth L. Ross

Peer Group Reviewed

4 PAGE

78