තුළතු ඉ. පු එදිදිදිදි

LAND CORNER RECORDATION CERTIFICATE

リエレル ジャー	ψ ₀ Επίτο 00.			
Lay warms		irement of Act 74, Mich.	P.A. 1970 FILED	
For corners in SECTOR Mason ICounty)	Located In:	Corner Code #	AT 3:08 O'CLOCK P	
1. Public Land Survey	T 19N R 17W T R T R	K-9	NOV 2 : 1398 MARY GOLDEN KOLASKI MASON COUNTY	
 Property Controlling in Section Miscellaneous 	TR STR STR		REDICTER OF DEEDS Register of Deeds Stamp & File Number	
Property in Sec.	STR		-	
4. Lot No, Ro	ecorded Plat		1 A B C D E F G H I J K L 2 5 5 4 3 2 1	
			3 2 3 2 2 3	

, in a field survey on October 24, 1998, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

Description of original monument and accessories and/or subsequent restoration:

ORIGINAL GOVERNMENT SURVEY

Section Survey by Sylvester Silbely 1838 to 1839, Set Post (1) Beech, 16", N56°E, 25.74'

(2) Beech, 16", \$24°W, 15.84'

H.B. Johnson, 1894, Book 1, Page 274 Mason County Records. States Section corner, both witness trees standing. No New Witnesses

Kenneth L. Ross, Survey unrecorded, File H-209, 1974 Kenneth L. Found 1" Pipe North side of road

- (3) 16" Maple, N85°E, 104.34'
- (4) 16" Maple, 835°W, 68.05'
- (5) 12" Tw Cherry, N80°W, 3.88'

Randolph Hepworth, LCRC, L Mason County Records, 1989 Liber 3, Page 34

Witness (5) above, distance 3.81'

- (6) 6" Maple, 358°az, 10.00'
- (7) 20" Tr. Maple, 219°az, 68.35°
- (8) 30" Maple, 92°az, 104.19'

Euro Comp. . .

Kenneth L. Ross, 19 Survey, unrecorded.

File No. 97324S

Fd. 1" Pipe, 8" below road surface, 10' North of c/1 Dewey Road.

- (9) P.P. SO5°W, 41.92'
- (10) Triple Maple, 10-10-18", N60°W, 83.50'
- (11) 12" Maple, N60°E,88.80'
- (7) 20" Maple, \$38°W,68.45'

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 1" X 18" Pipe, 12" below the road surface on North side of Road.

Condition of record witnesses as follows: (1) gone, (2) gone, (3) gone, (4) gone, (5) gone, (6) gone, (7) good condition, (8) good condition, (9) good condition, (10) good condition, (11) gone,

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

I replaced the 1" X 18" pipe in the exact location with a 4" X 20" Harrison Monument stamped " Mason County Monument"

12" below the road surface. This corner is accepted as a careful and faithful re-establishment of the original corner.

EX "B.T." (7) 20" Maple, S 38°W, 68.45 feet, (60d spike SE side)

EX "B.T." (8) 30" Maple, S 88° E, 104.19 feet, (60d spike North side)

EX "B.P." (9) P.P. S 05°W, 41.91 feet, (60d spike East side)

EX "B.T. (10) Triple Maple 10-10-18, N60°W, 83.50 feet, (60d spike SW side)

Ex "B.P." (9) P.P. S 05°W, 41.91 feet, (60d spike East side)
Ex "B.T. (10) Triple Maple 10-10-18, N60°W, 83.50 feet, (60d spike SW side)

(12) Hepworth iron and cap North 33.00 feet

Signed by enne 1

OF LAND SURVEYORS
REVISE
REV
OCESSY

Surveyor's Michigan License No. 17634

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975
REVISED MAY 14, 1975
REVISED JAN., 1983
ADAPTED FOR WORD PROCESSING MARCH, 1993

Approved by Peer Review Group On_ Kenneth L. Ross, County Representative

//-/9-98 ve