

DEC 1 8 1995

COMMISSION

## LAND CORNER RECORDATION CERTIFICATE

		Filing Require	ment of Act 74, Mich.	P.A <del>. 1970</del> —						-		
For corners in				1	FILED							
MASON		Located In:	Corner Code ## AT _	AT 3:3	7	010	+ 001		$\wedge$			
(County)				AI		<u> 0.0</u>	LOC	<u> </u>	<del>-</del>	M		
1. Publi	ic Land Survey	T <u>19 N</u> R <u>17 W</u> T R	L-13			EP						
in Se	erty Controlling ection cellaneous erty in Sec.			} }	M/ REGI	ISON Ster	COL OF	DEED	S	Numi	<b>ber</b>	
4. Lot N	No	, Recorded Plat			<u>^</u>	вс	D	E F	G Н   Т	- <u>  -</u>   -	K !	
do hereby in lines 1 current m Managem above we Court of expresses NOTE:	certify that under and 2 above were anual of survey intent or by a decree re in conformance. Law; established below:  Not more than 4 on this certification of origin.	al monument and accessories and ner for Secti on 36, T19N, R17N	of 1970, the corner points ment is rules therefore as required nent of the Interior, Bureau opoints mentioned in lines 3, Land Surveyors or by a Deconumented, recovered, for drange, may be recorded.	ntioned of in the of Land 4 and 5 ree of a und as  d  in	3 4 5 5 6 1 7 7 8 8 9 9 0 1 1 2 2 3 3 3 5	9	-20-29-32-	9		23		-24
	1838, Mullett Set Wood Post	& Brookfield, G.L.O, Boundary	No Date, M Iron set i									

#1 Hemlock 14" N47°E 231ks.(15.18')

#2 Birch 6" N 55°W 321ks.(21.12")

Note; Undated , Unsigned Survey, Book 1, Page 36, show a distance of 2632.081 to the SW cor. Sec. 36 and 2640.00' to the SE cor, Sec. 36.

1983, L. Slater RLS7439

Found 1/2" Iron

#4 Poplar 7" N 46° E 62.27'

#5 Maple 4" N 08° W 60.47'

#7 Poplar 7" N28ºE 54.22' #8 1/2" Iron Pipe East

#6 Poplar 14" N 07º E 68.76

4.971

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

South 1/4 Corner for Section 36, I19N, R17W. 1..13

> On September 5, 1995, I could not find 1/2" Iron as record by L. Slater, I believe the Iron was remove by the excavation of the road for a North-South Culvert, possibly by Mason County Road Commission, I set a new Re-rod from L.Slater's found witnesses and from record distance(4.97') to found North 1/4 Corner Section 1, I18N, R17W, I found no other evidence to dispute this location.

Condition of Recorded Witnesses is; #1 Gone #2 Gone #5 Found in good cond. #6 Found dead, still standing #7 Found in good cond. #8 Found in good cond.

NO # 3 USED

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

## South 1/4 Corner for Section 36, T19N, R17W. L-13

I set a 5/8" Re-rod, 24" long, with an aluminum cap cap( $2\frac{1}{2}$ " in dia.), stamped MASON COUNTY MONUMENT I placed Monument 0.5 feet below gravel road in center-line, and is accepted as a careful and reestablishment of the position of the original corner.

N 08° E 60.52'(60d spike in NE side of tree) OBT # Red maple

OBT #6 Poplar 16" N 07° 68.76'( M.D.O.T. shiner & 60d spike in West side of tree)

OBT #7 Poplar 13" N 28° E 56.56'(60d spike in NW side of tree)
Power Pole S 76° E 141.47'( fd. 060d spike in North side of Pole)

North End, Top-center of culvert, North

Sammy & Bornet

Peer Group Reviewed Pate 9-8-9

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 BEVISER MAY 54, 1975

SAMMY S.

BARNETT

PROFESSIONAL URVEYOR No.

16923

Mason County Surveyor

Surveyor's Michigan License No. 16923

LIBER

Kenneth L. Ross