MAR 1 6 1998	LAND COR	NER RECORDATION CEI	RTIFICATE		
	Filing Req	uirement of Act 74, Mich.	. P.A. 1970	FILED	
For corners ISECTION MASON	Located In:	Corner Code #	AT	1/35 O'CLOCK_	<u>~</u> M
(County) 1. Public Land Survey	T_20N_R_15W TR TR	M-8		OCT 7 1997 MARY GULDEN KOLASI MASON COUNTY	Kı
2. Property Controlling S S In Section S S S Property in Sec. S	T R T R T R T R T R T R T R T R T R T R		Regist	PEGISTER OF DEEDS	———J

__, Recorded Plat 4. Lot No. 5. Private Claims

I, Kenneth L. Ross In a field survey on September 12, 1997.

do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- Description of original monument and accessories and/or subsequent restoration:
 - H-8 East 1/4 Corner for Section 24, T20N, R15N, on the Township Line,

1838, Mullett & Brookfield, GLO, boundary survey Set Wood Post

N 38° W 81ks. (5.28') 5 42° W 291ks. (19.14') #1 White Oak 10" #2 White Pine 8"

10 30

11

12 31

1981, Robert A. Griffin, RLS #13584
Set 5" sq. x 36" long cond. monument w/ brass cap
#3 White Oak 8" N 84" % 54.44'
#4 White Pine 25" S 23" R 119.45'
#5 White Oak 8" S 31" W 69.64'
#6 Pine Post North 1.57'

C В

7

18

10

2

D

Ś

8

17

20

27

32

ó

16

21

28

10

15

22

27

11

1/

23

26

35

12

13

24 1

25

36

Recovered this corner by proportional measurement and on a straight line between controlling corners as of L. 02, P. 437, Lake Co. Register of Deeds

- Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - M-8 East 1/4 Corner for Section 24, T20N, R15W, on the Township Line,

On September 12, 1997,I Ken Ross and Kevin Pritchard (survey tech.) found a 5" square cond. monument with a 3" brass cap, to identify this monument as the 1/4 corner. This corner sets 20 feet west of the center-line of Tyndall Poad, one foot below the surface of the ground. I found no evidence to dispute this location for the

Condition of recorded witnesses are:

#1 Gone #2 Gone

#3 Found in good condition

Found in good condition

#6 Found in good condition

- Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H-8 East 1/4 Corner for Section 24, 120N, R15W, on the TOWNSHIP LLED,

I accepted Robert Griffin's 5" sq. concrete monument as substantial marker for this corner and is the original corner. September 1

(ext. BT #3) White Oak 12" (ext. BT #5) White Oak 13" (new BT) Black Oak 18" Pine Post 4" x N 84° W 54.44′ [10" dock spike in North side of tree) 8 31° W 69.64′ [10" dock spike in NE side of tree) N 81° W 10.65′ [60 d spike in North side of tree) 4′ North 1.57′ 16 p. nail in south side of post

Date

BICHGAN STAYE BOARD OF LAND SURVEYORE, JAN. 28, 1971 REVISED BLAY, 1675 REVISED JAN., 1975 ADAPTED FOR WORD PROCEEDING BLAY, 1973

KENNETH L. ROSS LARIO SURVEYOR No.

LIBER

Surveyor's Michigan License No. __17634

4 PAGE 113

Peer Group Reviewed oct E

Kenneth L. Koss

Mason County Surveyor