1 1 1 0 1 0 0 1 0 0 1 0 0 1 0 0 0 1 0		CORNER RECOR	DATION CERT	TFICATE							
\$EGTION	Filing F	Requirement of Ac	ct 74, Mich. P.	.A. 1970		FILED			_	•	
For corners in		AT			2:58 O'CLOCK P M						
Mason (County)	Located In:	Corner C	Code #	AI		LCCCK		78	141		
1. Public Land Survey T 20N R 17W H-13 T R						NOV 2 / 1998					
	TR TR				MARY GO MASO REGIST	ON COU	NTY				
2. Property Controlling S T R In Section S T R					ister of De						
3. Miscellaneous	S T	R	į	I.e.	jister or D	eeds 30	amp o	rne	Numbe	=1 	
	T R										
4. Lot No, Reco	orded Plat				A B (DE	F G	н	J K	L !	
					2 6	- 5	4	3	2		
l, Kenneth L. Ross	, in	a field survey on Octob	per 24. 1998		3 - 7	8	9	10	11	12	
do hereby certify that under required in lines 1 and 2 above were in controlled	irements of P.A. 74, Michig	gan P.A. of 1970, the co	orner points mention		5					 -	
current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5					6 18	17	16	15	14	13	
above were in conformance with Court of Law; established, re					8 19	20	21	22	23	-24	
expressed below:					9	- 29	28	27	-26	25	
NOTE: Not more than 4 co on this certificate.	mers, all in the same	town and range, ma	ay be recorded		11					-	
A. Description of original	monument and acces	sories and/or subse	quent restoration	n:	13	-32	33	34	35	36	
CRGINAL GOVERNMENT SURVEY Mullett and Brookfield, 1838 to 1839 Mullett and Brookfield					MASON COUNTY ROAD COMMISSION, 1961 Stone and Iron (3) Rd. Name Sign, SE, 45.00' (4) P.P. SW, 69.4' (5) P.P. NW, 47.2' (6) USFS Sign, NW, 52.5'						
Kenneth B. Stephens, 1967 Corner of Section 2, (H-I LCRC Herbert Fluharty, RI States Found Monument Box (7) Project Marker, N28°E (4) P.P. S23°W, 69.8' N1/4 Corner Section 3, T.	t) T.19N., R.17W, 1 LS, Liber 1, Page 2 c, 1, 74.23'	s East 7.23'. <u>69,</u>	en does not st	tate what	was foun	d. Sho	ows th	at th	ie N ¾		
B. Description of corner e	vidence found and/or	method applied in r	estoring or reest	tablishing	corner:						
I found a 1" square boat Road. The boat spike was (H-1) while the 1 " pipe	s bent on top and m	easured 7.30 feet	: West of the N	N1/4 Corr	er of Sec	tion 3	T.19				
Condition of record withe good condition,	esses as follows:	(1) gone, (2) gon	ne) (3) moved,	(4) £ai;	condition	on, ((5)	gone	(6)	gone	(7)	
C. Description of monume	ent for corner and acc	essories established	d to perpetuate l	ocating th	ne position	of the c	orner:				
I replaced the 1" square Monument) inside the 1 4" establishment of the posi Ex "B.T." (4) P.P. S 23°W	' pipe inside the m ition of the origin	onument box. Thi al corner.								nty	
Ex "B.T." (7) Project Mar (8) P.P. N 21° W, 68.95 f	eet (60d spike NE s	side)	Ą		ð	TITE O	ERPOR	CHIC	7.4		
(9) Guy Pole, S 34° E, 49 (10) Corner H-1, T.19N.,	.98 feet (60d spike R.17W., East, 7.23	NW side) feet)					TH L.	ROSS	1=		
Signed by Jane	Ptour		Date	lov.	19,	998	No.	R	30 =		
Surveyor's Michigan License	No. 17634				Ę	A 7 7	7 6 3	4			

Approved by Peer Review Group On __//- 19- 98
Kenneth L. Ross, County Representative ______

4 PAGE 232

LIBER