MAR 1 4 2000

MECOSTA COUNTY REMONUMENTATION PROGRAM

CORNER APPROVED BY PEER GROUP ON December 3, 1999

SECTION

LAND CORNER RECORDATION CERTIFICATE

STATE OF MICHIGAN COUNTY OF MECOSTA RECEIVED FOR RECORD

	rung xequ	mement of Act 74, Mich. P.A.	19/0					
For corners in			' 99	DEC 10	D2 -5	:O		
Mecosta (County)	Located In:	Corner Code #		DEG 10	F Z + J	7		
(county)	Colfax Twp.			ومس				
			(Joanne Brown				
1. Public Land Survey	SEC 31 T 15N R 09W	B-13		REGISTER OF DEEDS				
	TR TR		7	or the contract of the	DE E D 2			
2. Property Controlling	STR							
in Section	SR							
3. Miscellaneous	5IK		Register of D	eeds Stamp	& File !	Vumbe	H	
Property in Sec.	8TR					·····		
4. Lot No.	Recorded Plat							
5. Private Claims			1 / 8	CDEF	6 H I	JK	L M	
			2 6	5 4	3	2	ļ .	
			3					
i, James J. Keller	, in a field survey	on <u>October 6.</u> 19 99 ,	4 - 7 -		1 10	11	12	
do hereby certify that under	requirements of P.A. 74, Michigan P.A	. of 1970, the corner points mentioned	6					
ut sings I and Amoove were	e in conformance with regulations an structions of the United States Depart	nd rules therefore as required in the	6 18	17 16	15	14	13	
Management or by a decree	of a Court of Law and/or that the corne	er points mentioned in lines 3. 4 and 5	7			144	10	
above were in conformance:	with the rules of the Michigan Board of re-established, monumented, re-	of Land Surveyors or by a Decree of a	8 19	20 21	22	23	24	
expressed below:	i, re-communici, manumpired, re-	Tronditioned, recorded, Iddito 25	, , ,					
			10 30	29 28	27	26	26	
NUTE: Not more than on this certific:	2 corners, all in the same town	and range, may be recorded	11	27 20		20	20	
OH MHO GOLDICA	at u .		12 31	32 33	34	35	36	
A. Description of origin	nal monument and accessories a	nd/or subsequent restoration:	13	32 30	34	30	30	
1837, John Hodgson, D	eputy Surveyor GLO "At 40.00	0 ch Set 1/4 Sec. Post" " Pine N71°N 09 links (5,94°)						
May 15, 1991, James J Fnd. Nail 12" Set PK P. Pole Mortgage Loan November 28, 1997, Ja Fd. Hail 17" 1	. Keller, RLS #10693 (FB107- Poplar M54°W 2.15' a 802°W 32.33' Inspection of same data giv	PK Nail W. side P.P. S10' E-W Woven Wire Fence South W P111). "Found Rebar & Cap Fnd. Nail 16" Poplar N42' W.W. Fence South 0.5' es C/L 175th Avenue East 196 Survey L12 P303) "Fd Rebar & Fd. Nail 13" Poplar N54's Wire Fence South 0.5'	ē25862″ °B 2.6′ .75′ Cap ĕ25862 in	group of st	cones#	-		
B. Description of corne	er evidence found andlor method	applied in restoring or reestablish	ina oarner					
•			•					
Woven Wire Fer		138-W P105) "Found 1/2" Rebar Found Nail NE. ed 14' Found 60d N ed Trans:	" Popple N54"W					
C. Description of moni	ument for corner and accessories	s established to perpetuate locating	g the position of	the corner:				
Accepted Rebar and Ca of the origina		ation Monument as a careful a	nd faithful po	expetuation	of the	posit	ilon	
Found 60d and	nce South 0.5' is set 60d and tag above NE. is set 60d and tag above 18" set tag N sd Transformer Po set tag NR sd Service Pole 8	02*W 32.35'	CHELL					
	PY NATICOPTA CO. PEER OROUP	JAMES	J. 72 =					
TH ACCORDA	INCE WITH P.A. 345 of 1990	E C LAND	: ====					
amer s	J. Knapp	= 0 SURVEYOR	, X			•		
CHAIRMAN		三式 No. 1069	93 25					
NATE	DEC. 3, 1999	11,96	EUL'II					
		THE LANG	onini.					
λ.	11.00	SURVEYOR No. 1065	111.					
Signed by Form	J. VIIIe	Date December	er 6, 1999	····	·····		,_,,	
	H_{**}				,			