APPROVED LAND CORNER P.A. 345 OF 1990 MIDLAND COUNTY

For corners in

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

221

	6/6/95	ربو	7	\checkmark
_		/	-	,

Lot Na.

Private Claims ____

	MIDLAND (County)	Located In:	Corner Code ##	STATE OF MICHIGAN MIDLAND COUNTY FILED
1.	Public Land Survey	T1 <u>3N</u> R1 <u>W</u>	H-9	, TE4-E
		T R		19 JUL 95 10:53 A.M.
		T R		w. sam Ch. wa-Am Hatte
		T R		BEVERLY J THAYER
2.	Property Controlling	S T R		REGISTER OF DEEDS
	in Section	S T R		s and a second state of the second se
3.	Miscellaneous	S T R		Register of Deeds Stamp & Fil
	Property in Sec.	S T R		megister of Deeds Statish & Pile II

10

11

	• • •
I, PAUL B. LAPHAM , in a field survey on MAY	
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970), the corner points mentioned
in lines 1 and 2 above were in conformance with regulations and rules	therefore as required in the
current manual of survey instructions of the United States Department of	of the Interior, Bureau of Land
Management or by a decree of a Court of Law and/or that the corner points	s mentioned in lines 3, 4 and 5
above were in conformance with the rules of the Michigan Board of Land	Surveyors or by a Decree of a
Court of Law; established, re-established, monumented, re-monumented	ented, recovered, found as

expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded

on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

H-9: 1/4 Corner common to Sections 22 & 27

___ , Recorded Plat __

1852 AUSTIN BURT, POST, ELM 12" S44°W 36 LKS, BIRCH 14" N57°E 17 LKS.

1901 GIBBS, FOST OLD CORNER WELL PERSERVED

11-09-72 HUNTER, REFERENCE N.-S. 1/4 UNE (132) 1-277

10-28-76 JOHN MARTIN, SET 3/4" IRON PIPE ON € BIT RD. E&W

WITNESS NOTE: Witnesses from above surveys and LCRC's are available in doissier file; which was presented to peer review committee and is on file at the Register of Deeds Office.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

H-9: 1/4 Corner common to Sections 22 & 27

Set 5/8"x36" re-rod in gravel road on line with G-9 & found iron at 1/8 cor. between G-9 & H-9. Meas. G-9 to 1/8 corner, 1329.98 (Gibbs recorded 20.15') set H-9 1329.98' from 1/8 corner. Corner falls 8' South of © road with deep ditch on South side. Local resident says road has been rebuilt with under drain in location of corner. Corner does not fit centerline of road per Martin Survey, but the deep ditch on South side of road supports the location 8' south of centerline.

REMOVE THATION

1995

COMPASSION

Corner, H-9 was approved for remonumentation at a Peer Review Committee Meeting on 6-6

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

H=9: 1/4 Corner common to Sections 22 & 27
Set 5/8" x 18" re-rod with brass cap stamped "Midland Co. Remon. Cor. PS 9433" in Monument Box per survey by Gibbs. Accepted as best available evidence of the accepted position of the corner.

\$78°E 274.03'- N&T IN POWER POLE \$01°E 51.13' - N&T IN POWER POLE \$82°W 322.51' - N&T IN POWER POLE NORTH 28.58' - 2" DIA. GAS LINE VALVE

_ Date 6-/2.95

STE OF MICH PAUL B LAPHAM **PROFESSIONAL** SURVEYOR No. POFESSION FESSION

Surveyor's Michigan License No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975 REVISED JAN., 1983