APPROVED (AMD COT SEL) P.A. 345 OF 1949 MIDLAND COUNTY

JAN 21 1999

MIDLAND County Remonumentation

SECTION

11/24/	18/	N
For corners in		

## LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1	970						38	32			
MIDLAND Located in: Corner Code #		STATE OF HICHIGAN HIDLAND COUNTY									
1. Public Land Survey  T13N R01W  K-3  T R				REM	YUNC	1ENT	AT IO	N & F	ILEI	j	
TR				12/	/16/	199	8 12:	:11:5	6 Př		
2. Property Controlling S T R in Section S T R 3. Miscellaneous S T R Property in Sec. S T R								THAYE DEED			
1 Toperty III Sec. 5 1R		Re	gist	er of	De	eds	Starr	np & f	File f	Numb	)er
4. Lot No, Recorded Plat											
5. Private Claims	1	A 1	в (	C E	E	F	G G	H	I 3	K	Ъ
	2	-	б — 	<u>5</u> 	$\dashv$	— á I	-	-3 — 	ż	-	-1
I, Mark R Robison, in a field survey on September, 1998 do hereby state that un	3 h nder				7		_	+		-	$\dagger$
requirements of P.A. 74, Michigan P.A. of 1970, the corner points mention in lines 1 and 2 above were conformance with regulations and rules therefore as required in the current manual of survey instructions of	e in 4		7	8   	7	9 	+	-10	1:   	-	12 
United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan	d/or				,	16		Ţ-			7
Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumen	gan <sup>o</sup> [ ted, <sub>7</sub> [					10		-15		,	-13
recovered, found as expressed below:	8	1	9	  20		 21:		 -22—	-2:	3——	 -24
NOTE: Not more than 2 corners, all in the same town and range, may be recorded	9 -				_	_ _		$\perp$			$\overline{\downarrow}$
on this certificate	10	ا اِ3	0-		,	 2 <sub>.</sub> 8-	<del> </del> -	 -2,7—		; <del>_</del>  _	-25
	11	_			-		+	+	-	+	+
	12	—3 <sup>1</sup> 2	1-	32  32	+	—3 <sup>1</sup> 3∙		-34-	—3 <sup>l</sup> s	;——	-36 I
A. Description of original monument and accessories and/or subsequent restoration:  K-3: 1852 Burt South 80.13 Cor of Sec 1-2-11-12 Piece of Buggy Axel Wit-1)W. Pine 26" N68E 36 Meas West 40.12 & 2)W. Pine 12" S73W 17  (Survey Sec 1.)	13 L set in South	Sur 1 40	rvey .17	of 18	 §2						
9-13 Gibbs CSR Set 1/2 of Steel Buggy Axel at proportional measurement Meas West 80.02 & North 39.80 (Survey Sec 2.)											
9-29-13 Gibbs CSR (same as 9-13 above) Measured East 39.60 & North 39.80 (Survey Sec 1.)				-							
B. Description of corner evidence found and/or method applied in restoring or reestablishing cor K-3: Found 3/4" x 18" Pinch Pipe. Excavated to three feet and found no other evidence. Measured West 2644.70 (Gibbs 2647.92) feet to 1/4 corner. Measured North 2626 to Fence line (Gibbs 2626.80) but could not find corner. Measured East 2624.02 (Gibbs 2613.6) to 1/4 corner. Accepted pipe for corner.	oroved	l for	rem	onun	nent 98	ation	ı at a	Peer I	Revie	∌W	
C. Description of monument for corner and accessories established to perpetuate locating the p K-3: Set 3/4" x 18" Gas Pipe with Brass Cap stamped "Midland Co. Remon. Cor. P.S.27458" in Monument available evidence of the accepted position of the corner.	ositio Box.	n of Acc	f the epte	e cor	ner: bes	: st					
Witnesses: N62W 89.72', nail & tag, P.P. N51E 48.00', nail & tag, P.P. S24E 72.26', nail & tag, P.P. S42E 75.62', nail & tag, 14" Ash  ROBISON PROFESSIONAL SURVEYOR NO. 27458											
Date -	12.	-0	9.	-9	g						
Surveyor's Michigan License No. 27458											