SURVEY & REMONUMENTATION

APPROVED LAND CORNER P.A. 345 OF 1990 MIDLAND COUNTY

Surveyor's Michigan License No. 29241

OCT 0 3 1996

		REMON	I. COR. C-1, MIDLAND	TWP. COMMISSION 269
	4/18/96 OLG		R RECORDATION CE	
For cor	ners in	Filing Require	ement of Act 74, Mich	MIDLAND COUNTY
MICIAIL	(County)	Located in:	Corner Code #	REMONUMENTATION & FILED
1. Publ	ic Land Survey	T <u>14N</u> R <u>2E</u>	C-1	22 AUG 96 8:06 A.M.
		T R		BEVERLY J THAYER
		T R		REGISTER OF DEEDS
_		TR		
	perty Controlling S	3 T R		
	ection S	{		
	cellaneous S	. — I — K —		
Prof	perty in Sec. S	·— '—-ĸ—		Register of Deeds Stamp & File Number
4. Lot i	No, Recorded Plat			
5. Priva	ate Claims		· · · · · · · · · · · · · · · · · · ·	ABCDEFGHIJKLM
I, RODNEY CLAYPOOL, in a field survey on MAY 1, 19 95, do hereby certify				2 -6 - 5 - 4 - 3 - 2 - 1 - 2
				3 4 7 8 9 10 11 12
in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the 6 18 17 16 15 14 13				
corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established,				8 - 19 - 20 - 21 - 22 - 23 - 24
	nted, re-monumented, recovered,	=		9 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
			•••	10 -30 -29 -28 -27 -26 -25
NOTE:	Not more than 4 corners,	all in the same town	n and range, may be	
	recorded on this certificat			12 -31 -32 -33 -34 -35 -36
				13
A. Description of original monument and accessories and/or subsequent restoration:				
C-1	Corner common to Sections 5 and 6 on north townline			
	Survey by Government, 1830's, s	set post	•	MURVEYON P
	Survey by F. Gibbs, 1917, set iron	n		No
	Survey by MDOT, 1959			29261
	Survey by D. Whittler, 1968, foun			
	Survey by J. Jones, 1982, 1987,			
	Survey by D. Ledy, 1990, found 3	3/4" pipe in mon box		
	LCRC by J. Jones, 1986			
WITNESS NOTE: Witnesses from above surveys and LCRC's are available in dossier file; which was presented to peer review committee and is on file at the Register of Deeds Office.				
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:				
C-1	Corner common to Sections 5 ar	nd 6 on north townline		
	Found 3/4" pipe in mon box, rep	placed pipe with 5/8" rod	and brass cap, per surveys t	by F. Gibbs, D. Whittier, J. Jones, D. Ledy, and LCRC by J. Jones.
Corner <-/ was approved for remonumentation at a Peer Review Committee Meeting on 4/18/96.				
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:				
C-1	Corner common to Sections 5 and 6 on north townline			
	Found 3/4" pipe in mon box, replaced pipe with 5/8" rod and brass cap stamped Midland Co. Remon Cor. PS 29241, per surveys by F. Gibbs, D. Whittier, J. Jones, D. Ledy, and LCRC by J. Jones; and is accepted as the best available evidence of the position of the accepted corner.			
	N 40 Deg E, 42.50', nail and plas S 45 Deg W, 41.64', nail and plas N 45 Deg W, 49.15', nail and plas 8 35 Deg W, 47.19', nail and plas West 10.50', C-13 for Larkin Tow	stic disc in light pole stic disc in guard rail post stic disc in guard rail post		

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971

Revised May 14, 1971

Date 05-10-96

Revised Jan., 1983