GURVEY & REMONUMENTATION

APPROVED LAND CORNER P.A. 345 OF 1990 MIDLAND COUNTY

Q19 2/24/94

NOV 07 1994

COMMISSION

REMON. COR. C-3 INGERSOLL TWP. LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74. Mich. P.A. 1970

	Filir		irement of Act 74, Mich			
For c Midla	corners in	y nequ	mement of Act 74, wich	. P.A. 1970	74	
*******************		ted in:	Corner Code #	, mer 12		
1. Pu	ublic Land Survey T 14N T T	R <u>2E</u> R R R	C-3	HIDL.	OF MICHIGAN AND COUNTY VTATION & FILED	
in 3. Mi	operty Controlling S T Section S T Scellaneous S T S T S T S T S T S T T S T S T T S T S T T S T T S T T S T T S T T S T T S T T S T T S T T S T T S T T S T T S T T S T T S T T S T T S T T T S T T T S T	R R		BEVER!	94 9:03 a.m. Ly J Thayer	
	 `_	R	· · · · · · · · · · · · · · · · · · ·	Register of Deeds Starning	He Number	
				ABCDE	FGHIJI	
that un lines 1 in the c interior corner of the li	NEY CLAYPOOL, in a field survey on DECEMBER ider requirements of P.A. 74, Michigan P.A. of 1970 and 2 above were in conformance with regulation current manual of survey instructions of the Unity, Bureau of Land Management or by a decree of points mentioned in lines 3, 4 and 5 above were Michigan Board of Land Surveyors or by a Decree of mented, re-monumented, recovered, found as expressions.	the corn s and rule ed States a Court of in confor of a Court	ter points mentioned on the state of the set therefore as required as Department of the set of Law and/or that the set of Law; re-established,	2 -6 -5 3 4 -7 - 8 - 5 - 18 - 17 - 7 - 19 - 20 - 9 - 10 - 30 - 29 -	-4 - 3 - 2	13
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.			11	-33-34-35	\vdash	
A. De	escription of original monument and access	sories a	and/or subsequent resto	ration:	N. I.	
C-3	Corner common to Section 5, 6, 7, and 8 Wood post Government survey 1830's Elm 20" S 66 Deg W, 19 L Elm 9" N 87 Deg E, 6 L Beech 20" N 18 Deg E, 7 L Survey by F. Gibbs 1917, fence post for corner Survey by MDOT 1951, not found Survey by A. Courtright 1956, Pheiffer Subd Survey by M. Hunter 1957, Nurmi Estates No. 2	Survey LCRC South North I S 70 D concr N 70 D guard 1/2" ro	y by J. Jones 1979, found mon y by L. McGinnis 1979, found of by J. Jones 1980, found 1/2" r concrete monument 75.0' nail and tag in power pole 57.4 leg E, "+" chiseled in W end of rete guard rail, 83.13' leg E, "+" chiseled in W end of drail, 81.83' of and mon box removed by Coruction 1980's, only mon box	orner rod in mon box 43' South f N City of Midland during road	RODNEY D. CLAYPOOL LAND SURVEYOR No. 29241)
B. De	escription of corner evidence found and/c	r metho	ed applied in restoring or	reestablishing corner:		
C-3	Corner common to Sec. 5, 6, 7, and 8					
	Found mon box (no iron inside) set rod and bra Hunter 1957)	ss cap by	using J. Jones 1979 survey (L	2 P 998) and checked corner w	vith Nurmi Estates No.	2 (by i
Corne	r <u>と-ろ</u> was approved for remonumenta	ition at a	Peer Review Committee	Meeting on FEB	<i>24</i>	19 <i>5</i>
C. De	escription of monument for corner and acc	cessorie	es established to perpetua	ate locating the position o	f the corner:	
C-3	Corner common to Sec. 5, 6, 7, and 8					
	Set 5/8" rod with brass cap in monument box (s McGinnis, J. Jones and LCRC by J. Jones; and North 57.03', nail and plastic disc in power pole N 60 Deg E, 72.38', SW bolt on W end fence NV S 60 Deg E, 73.90', SW bolt on W end fence SW	is accept	ed as the best available evider idge			ər, L.

South 75.0', concrete mon

Date 03-07-94