1993

LAND CORNER RECORDATION CERTIFICATE

For corners in	COMMICS	Filing Ro	REMONUME	FAct 74, Mich. CNTATION her Code ====================================	P.A. 1970		Ñ	ĦI.	DLAN	HICH D COU ATION	NTY				
1. Public Land S	T 14N R 1W I-6 T R T R T R T R T R T R T R T R T R T						30 NOV 93 3:08 P.H. BEVERLY J THAYER REGISTER OF DEEDS								
 Property Conin Section Miscellaneous Property in Section 	S S	T R T R T R T R			Regi	ister (of De	eeds	Stan	np &	File !	Nun 	nber		
4. Lot No							B 7 7 18 19 19 19 19 19 19 19 19 19 19 19 19 19	5 8 17 20	-1	F G	H 3 -10 -15 -22 -22	- 2 - 2	1	12-13-	
expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration:							31	2 ⁹	3	3	-34	3:	5 -	-25 -36	
(1-6) 1/4 Cor Post Pla in 1852 \$37°E 2 N57°W 2	.Sec. 14 & 15, I14 aced by Austin Bur Subd. Resurvey 7 L.(17.82') 12" M 7 L.(17.82') 22" M	N-R1W t lapte apte		equent restorativ											

C.C.R.C. by P. Lapham, Recorded in BK. 1 P. 623,
Found 3/4" Pipe in Mon. Box: N60°E 47.33' 20"
Oak; East 33.0' Capped Rerod; N80°W 51.5' P. Pole.
(Surveys in L. 2, P. 567, L. 4, P. 464)
(Recorded Plat of McConnell Sub., L. G, P. 19)
B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

(1-6) 1/4 Cor. Sec. 14 & 15, T14N-R1W

Found 1" Pipe over 5/8" Re Rod per Bk.1 P. 623, Record Mon. Box apparently destroyed. Placed new Mon. Box.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

1/4 Cor, Sec. 14 & 15, T14N-R1W (1-6)

Found 1" Pipe over 5/8" Re Rod per Bk. 1 .P 623, Placed Mon Box and is accepted as the best available evidence of the position of the original corner.

N76°W 51.47' Power Pole(R) East 32.95' 1/2"Re Rod & cap #9433(R) N75°E 56.00' 8" Oak N23°E 115.64' 8" Oak

Signed by 12018 OF MICH OFESSION

Date _

NOV

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983

Surveyor's Michigan License No. _