SURVEY & REMONUMENTATION

APPROVED LAND CORNER P.A. 345 OF 1990 MIDLAND COUNTY

APR 2 8 1995

COMMISSION

129

11/02/94	

Property in Sec.

LAND CORNER RECORDATION CERTIFICATE

STATE OF MICHIGAN HIDLAND COUNTY REMONUMENTATION & FILED

Filing Requirement of Act 74, Mich. P.A. 1970 For corners in MIDLAND Located In: Corner Code ##

8 NOV 94 9:22 A.M.

T 15N R 1W 1. Public Land Survey _ R _ R _ R _


BEVERLY J THAYER REGISTER OF DEEDS

__ R _ 2. Property Controlling T S ____ R _ in Section S ____ T ___ R ____ Miscellaneous __ R . T _

Register of Deeds Stamp & File Number

, Recorded Plat 4. Lot No. Private Claims _

PAUL B. LAPHAM , in a field survey on _____ JULY do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:



NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

escription of original monument and accessories and/or subsequent restoration:

E-11: Section Corner common to Sections 28, 29, 32 & 33

1852 - Austin Burt, W. Pine 7" S 47°E, 19 lks, W. Pine 14" N 20°W, 27 lks

08/08/99 - Gibbs, Set W. Oak Post in place of old Corner.

10/03/14 - Gibbs Set New W. Oak Post, P. 360-361

03/10/83 - Harvey Gilbert, Found 3/4" Iron pipe, bent North L.C.R.C. #574

(1) NW, 48.36' - 12" Birch
(2) SW, 60.75' - 24" Maple
(3) NE, 41.51' - 21" Oak
(4) NE, 77.25' - Tele. Pole

03/27/91 Jones, Unrecorded Survey & field notes from Ayres Associates.
(5) East 2642.59' (F-11)

(5) East 2642.59' (F-11)

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

E-11: Section Corner common to Sections 28, 29, 32 & 33 Found 3/4" Pipe in 1-1/2" x 24" pipe, Excavated to 3 feet and found no further evidence. Found recorded witnesses 1, 3 & 4. Checked Distance to East (F-11) 2642.80'.

Accepted as best available evidence of the position of the original corner & replaced with Standard Monument.

Corner, E-11 was approved for remonumentation at a Peer Review Committee Meeting on 11-02 C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

E-11: Section Corner common to Sections 28, 29, 32 & 33
Set 5/8" x 36" re-rod with brass cap marked "Midland Co. Remon. Cor. PS 9433"
N 45°E, 42.2' - Nail & Tag in 24" Oak
N 70°E, 77.25' - Nail & Tag in Tele. Pole
S 45°W, 61.90' - Nail & Tag in 42" Oak
S 80°W, 48.23' - Nail & Tag in 18" Oak

of Monion PAUL B. LAPHAM **PROFESSIONAL** SURVEYOR No. 9433 OFESSIONAL STATE

Signed by faul B- Jophur Surveyor's Michigan License No. __