SURVEY & REMONUMENTATION

APPROVED LAND CORNER P.A. 345 OF 1990 MIDLAND COUNTY

11/28/94 950

in Section Miscellaneous

Property in Sec.

APR 2 8 1995

157

COMMISSION LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN MIDLAND COUNTY REMONUMENTATION & FILED

24 A.M.	
HAYER DEEDS	
REGISTER OF DEEDS	EDS

G

Register of Deeds Stamp & File Number

4.	Lot No, Recorded Plat
5.	Private Claims

. R

S ____ T ____ R ____

S ____ R _

_ T ...

S

PAUL B. LAPHAM , in a field survey on NOVEMBER do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

2 6 10 12

A. Description of original monument and accessories and/or subsequent restoration:

1852 AUSTIN BURT PGS. 144-145 OLD POST WIT.-HEMLOCK 8" NORTH 25 LKS. MAPLE 24" S64°W 90 LKS.

10-72 SCHAFER, (132) L.1, PG.231 FOUND CORNER WIT.-MONUMENT 49.7' WEST

10-30-10 UNKNOWN, C.S.R. 300-301 SET PINE ROOT POST FOR CORNER NO WITNESSES

9-26-BO MERRY, (132) L.3, PG.132 FOUND STATE HIGHWAY MARKER

8-14-26 HOMER SNELL, FERRO'S SUBDIVISION (PLAT) L.A. PG.13

12-13-66 M.D.O.T., R/W PLANS. 56-R-2 SEC. CORNER 13.08' W OF @ M-30

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND STATE OF MICHIGAN CAP ON 3' LONG BAR. FOUND PLAT MONUMENT 49.7' WEST OF CORNER. EXCAVATED TO DEPTH OF 3 FEET & FOUND NO FURTHER EVIDENCE.

Accepted as best available evidence of the position of the original corner & replaced with Standard Monument.

Corner, M-7 was approved for remonumentation at a Peer Review Committee Meeting on $\frac{1/-38}{1}$ C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

M-7; Corner common to Sections 13 & 24
Set 5/8" x 18" re-rod with brass cap stamped "Midland Co. Remon. Cor. PS 9433" in Monument Box.
WITNESSES:
N45°E 1.2" - BURRIED CABLE SIGN POST
SOUTH 44.80" - GUARD RAIL POST

WITNESSES:
N45°E 1.2' - BURRIED CABLE SIGN POST
SOUTH 44.80' - GUARD RAIL POST
S30°W 68.40' - NAIL & TAG IN POWER POLE
N30°E 78.00' - NAIL & TAG IN W. PINE
WEST 50.10' - R.O.W. MARKER
WEST 49.70' - CONCRETE PLAT MONUMENT

THE OF MICHIGAN LAPHAM PROFESSIONAL SURVEYOR No. 9433 POFESSION POFESSIONA

Surveyor's Michigan License No.

Date 12-01-94