241

1/18/95 GSG

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

	Filing Require	ement of Act 74, Mich. P./	A. 1970
For corners in MIDLAND (County)	Located In:	Corner Code ##	STATE OF MICHIGAN MIDLAND COUNTY RENONUMENTATION & FILED
Public Land Survey	T1 <u>5N R2W</u> T R	M=5	14 AUG 95 3:04 P.M.
2. Property Controlling	T R T R S T R		BEVERLY J THAYER REGISTER OF DEEDS
in Section 3. Miscellaneous Property in Sec.	S T R S T R S T R		Register of Deeds Stamp & File Number
4. Lot No	, Recorded Plat		
5. Private Claims			3 4 7 8 9 10 11 12
do hereby certify that under in lines 1 and 2 above wer current manual of survey in Management or by a decree above were in conformance Court of Law; establishe expressed below:	, in a field survey on _MAY, requirements of P.A. 74, Michigan P.A. re in conformance with regulations a nstructions of the United States Departure of a Court of Law and/or that the corne with the rules of the Michigan Board d, re-established, monumented, re	nd rules therefore as required in introduction of the Interior, Bureau of her points mentioned in lines 3, 4 and the Surveyors or by a Decre -monumented, recovered, foun	in the f Land 7
NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.			12 31 32 33 34 35 36
M-5 East Sectio 1830 CLARK, T15N, 1946 CONSUMERS		e Common 70 A- Hemlock 12" N75°E 17 LKS., GRATE & HUNK OF IRON FOUNI	n: -5, 7/5 N - R / W ., BURT FOUND OLD CORNER IN 1852.

WITNESS NOTE: Witnesses from above surveys and LCRC's are available in dossier file; which was presented to peer review committee and is on file at the Register of Deeds Office.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

M-5 East Section Corner 12 & 13

Found cabin spike over hunk of Iron, meas. N 1311.98 per Whittier Survey to 1/2" rod in ditch (pipe 33' West) and South 2633.5 feet to A-6.

REVOLUTION

1000 1005

COMMISSION

Corner, M-5 was approved for remonumentation at a Peer Review Committee Meeting on 7-18 19 95.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner.

M-5 East Section Corner 12 & 13
Set 5/8" x 18" re-rod with brass cap stamped "Midland Co. Remon. Cor. PS 9433" in Monument Box per surveys by C.P.Co. and Whittier. Accepted as best available evidence of the accepted position of the corner.

\$45°E 58.4' - FIRE HYD. \$45°W 58.0' - N&T IN POWER POLE \$40°W 47.7' - N&T IN 12" PINE \$57°E 56.0' - N&T IN POWER POLE

N&T IN POWER POLE

Date 9/21/95

PAUL B.
L 6 PE AM
PRIMESSIONAL
SURVEYOR
No.
9433

Signed by

Surveyor's Michigan License No. _

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28. 1971 REVISED MAY 14. 1975

REVISED JAN., 1983