## SURVEY & REMONUMENTATION

## APPROVED LAND CORNER P.A. 345 OF 1990 MIDLAND COUNTY

APR 28 1995

## COMMISSION

## REMON, COR. E-3. LARKIN TWP

143

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970		STATE OF MICHIGAN MIDLAND COUNTY REMONUMENTATION & FILED	
Located in:	Corner Code #	1	28 NOV 94 1:00 P.M.
T 15N R 2E T R T R T R T R T R	<u>E-3</u>		BEVERLY J THAYER REGISTER OF DEEDS
' H			eds Stamp & File Number
	Located in:  T 15N R 2E T R T R T R T R T R	Located in: Corner Code #  T 15N R 2E	Located in: Corner Code #  T 15N R 2E

I, RODNEY CLAYPOOL, in a field survey on FEB 14, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

KI 3 4 10 5 6 15 4 7 8 9 9 10 30 29 28 26 11 12

- A. Description of original monument and accessories and/or subsequent restoration:
- Corner common to Sections 4, 5, 8, and 9 E-3

Government survey 1830's, set wood post Survey by F. Gibbs, 1917 stone for corner. Small iron rod under Survey by M. Hunter, 1953, set 3/4" pipe (from Gibbs 1917 survey)

Survey by J. Schafer, 1976, found 3/4" pipe Survey by J. Jones, 1993, found 3/4" pipe LCRC by P. Lapham, 1983, found 1/2" pipe

WITNESS NOTE: Witnesses from above surveys and LCRC's are available in dossler file; which was presented to peer review committee and is on file at the Register of Deeds Office.

- B. Description of corner evidence found and/or method applled in restoring or reestablishing corner:
- E-3 Corner common to Sections 4, 5, 8, and 9

Found 3/4" pipe (replaced with 3/4" pipe and brass cap) per surveys by F. Gibbs, M. Hunter, J. Schafer, J. Jones, and LCRC by P. Lapham.

Corner <u>E-3</u> was approved for remonumentation at a Peer Review Committee Meeting on <u>Nov. 2/</u>

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- E-3 Corner common to Sections 4, 5, 8, and 9

Found 3/4" pipe (replaced with 3/4" pipe and brass cap stamped Midland County Remon. Cor. PS 29241 in mon box) per surveys by F. Gibbs, Hunter, J. Schafer, J. Jones and LCRC by P. Lapham; and is accepted as the best available evidence of the accepted position of the corner.

N 15 Deg E, 209.74', nail and plastic disc in power pole N 10 Deg W, 216.25', nail and plastic disc in power pole

S 45 Deg W, 41.48', nail power pole

\$ 60 Deg E, 66.02', nail and plastic disc in guy pole

Signed by /hor

Date 1/-28-99

CLAYPOOL yor**s, Alam** 28, 197 Revisua MEY PA 197

Form approved by Michigan State Board of L

Surveyor's Michigan License No. 29241