SURVEY & REMONUMENTATION

APR 2 8 1995

APPROVED LAND CORNER P.A. 345 OF 1990 MIDLAND COUNTY

11/21/94 OLO

COMMISSION

REMON. COR. G-4, LARKIN TWP.	
LAND CORNER RECORDATION CERTIFICATI	_
Filing Requirement of Act 74 Mich P A 1970	=

145

For corners in Midland	Filing Requirement of Act 74, Mich. P.A. 1970			STATE OF MICHIGAN MIDLAND COUNTY
(County)	Located in:	Corner Code #		REMONUMENTATION & FILED
Public Land Survey	T <u>15N</u> R <u>2E</u> T R	<u> </u>		28 NOV 94 1:00 P.M.
	T R -			BEVERLY J THAYER REGISTER OF DEEDS
2. Property Controlling in Section	S T R			And a sected
3. Miscellaneous	s t R			
Property in Sec.	S_T_R_		Register of Deed	ls Stamp & File Number
4. Lot No, Record	ed Plat			
5. Private Claims				

I, RODNEY CLAYPOOL, in a field survey on FEB 15, 19 94, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

ABCDEFGHIJK 3 Ω 10 5 6 ig 7 8 21 Ź2· 9 10 śο 29 28 26 11 12 33 13

- A. Description of original monument and accessories and/or subsequent restoration:
- G-4 Corner common to Sections 9 and 10

Government survey 1830's, set post Survey by F. Gibbs, 1917 set piece of wagon tire, stone around Survey by Dow, 1950's, 3/4" pipe Survey by M. Hunter, 1953, 1958, 1960 found stone and iron

Survey by D. Whittier, found corner Survey by J. Schafer 1974, 1976, 1977 found 3/4" pipe stones around Survey by J. Jones 1981, 1984, 1988, found corner LCRC by P. Lapham ,1983, found 3/8" rebar

WITNESS NOTE: Witnesses from above surveys and LCRC's are available in dossier file; which was presented to peer review committee and is on file at the Register of Deeds Office.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- G-4 Corner common to Sections 9 and 10

Found 3/4" pipe (replaced with 5/8" rod and brass cap) per surveys by Dow, M. Hunter, D. Whittler, J. Schafer, J. Jones and LCRC by P. Lapham.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- Corner common to Sections 9 and 10

Found 3/4" pipe (replaced pipe with 5/8" rod and brass cap stamped Midland County Remon. Cor. PS 29241, in mon box) per surveys by Dow, N Hunter, D. Whittier, J. Schafer, J. Jones and LCRC by P. Lapham; and is accepted as the best available evidence of the accepted position of the corner.

\$ 45 Deg E, 54.00', PK nail in power pole S 50 Deg E, 52.24', nail in power pole

N 45 Deg W, 70.93', nail in 24" Oak S 45 Deg W, 54.67', PK nail in telephone pole

Signed by Showing D.

Date 11-28

RODNEY D. CLAYPOOL

Surveyor's Michigan License No. 29241

Form approved by Michigan State Board of Land