SURVEY & REMONUMENTATION

APPROVED LAND CORNER P.A. 345 OF 1990 MIDLAND COUNTY

OCT 0 3 1996

COMMISSION

4/18/96 950		
1112116 93 4	4/18/96	950

REMON. COR. M-12, LARKIN TWP. LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

256

For corners in Midland			STATE OF MICHIGAN HIDLAND COUNTY
(County)	Located in:	Corner Code #	REHONUMENTATION & FILED
1. Public Land Survey	T <u>15N</u> R <u>2E</u> T R	M-12	22 AUG 96 8:06 A.M.
2. Property Controlling	T R T R T R T R T R T R T R T R T R T R		BEVERLY J THAYER REGISTER OF DEEDS
in Section 3. Miscellaneous Property in Sec.	S T R S T R		Register of Deeds Stamp & File Number
4. Lot No, Recorde	d Plat		

I, <u>RODNEY CLAYPOOL</u>, in a field survey on <u>MARCH 29</u>, 19 <u>95</u>, do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned on lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

K L M 3 5 5 3 6 7 8 9 30 5 10 29 28 11 12 13

- A. Description of original monument and accessories and/or subsequent restoration:
- M-12 East 1/4 cor Section 36

Survey by Government, 1830's, set post Survey by F. Gibbs, 1924, cedar stake Survey by M. Hunter, 1960, set equidistant between M-11 and M-13 1962 found Survey by J. Jones, 1981, found 1/2" pipe RODNEY D.
GLAYPOOL
LAND
BURVEYOR
No.
29241

WITNESS NOTE: Witnesses from above surveys and LCRC's are available in dossier file; which was presented to peer review committee and is on file at the Register of Deeds Office.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
- M-12 East 1/4 corner Section 36

Found 1/2" pipe per surveys by M. Hunter and J. Jones.

Corner M-/ awas approved for remonumentation at a Peer Review Committee Meeting on 4/18/96.

- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
- M-12 East 1/4 corner Section 36

Found 1/2" pipe, (replaced 1/2" pipe with 5/8" rod and brass cap stamped Midland Co. Remon Cor. PS 29241 in mon box) per surveys by M. Hunter and J. Jones; and is accepted as the best available evidence of the position of the accepted corner.

S 35 Deg E, 31.02', pk nail in power pole S 35 Deg W, 30.70', nall in 10" Cottonwood S 75 Deg W, 65.85', nail and disc in power pole S 45 Deg W, 44.42', nail and plastic disc in 8" Ash South 24.54', Bay County Remon Corner L-003, p. 91 N 70 Deg E, 90.79', SW cor house (1960 witness 91')

Signed by Roding a Claysof

Date 05-70-96

Surveyor's Michigan License No. 29241

Form approved by Michigan State Board of Land Surveyors, Jan. 28, 1971

Revised May 14, 1971

Revised Jan., 1983