(*) 1277 B	. ::.	· ·		:		•
RATIFIED BY PEER GROUP	<del>.</del>				y hard to have the standard to	· ·
PARKE OF 1889 MONROS COUNTY, MICHIGAN						•
dote: 9/24/1995	<b>-</b> .	IER RECORDATION IF THE RECORDATION IN THE RECORDATION OF Act 74			્ ઝ્ર	
Cepuity Corners in DA 3000	i iing nequi	rement of Act 14	, MICO, F.A. 197	C C C C C C C C C C C C C C C C C C C		CEVED.
Monroe (58)	Located In:	Corner Code	##		11/	~r <sub>1</sub> ,
1. Public Land Survey	T R	***		बाह्य है। जिस्से हर ज्ञान हुई		3
Exeter Twp.	T <u>5s</u> R <u>8c</u> T <u> </u>	<u>F-8</u>				
O Branch Controlling P	T R				02	
in Section S	T R		75V ž			
3. Miscellaneous S Property in Sec. S	T R	REMONU	ZEY & MENTATION	egister of Deed	is Stamp & File	: Number
. •		\$ 0 <b></b>	3 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		<del></del>	<del></del>
4. Lot No, Record		APR 0	4 1996	- <u>A B C</u>	D E F G H	; J K L
1995 REMONUMENTATION PROGRA	Mi	COM	MISSION	3 - 1 - 1	53-	<del></del>
I, G. B. WARNKE, JR in a		1005	10	<b>\$</b> }-}-	8	
do hereby certify that under requirem in lines 1 and 2 above were in conf	ents of P.A. 74, Michigan P.,	À. of 1970, the corner p	oints mentioned	6 18	17-1-16-15-	13
current manual of survey instruction Management or by a decree of a Cour	s of the United States Depa	artment of the Interior,	Bureau of Land	7	++++	+
above were in conformance with the Court of Law; established, re-esta	rules of the Michigan Board	of Land Surveyors or	by a Decree of a	9	21 - 22 - 22 -	23 24
expressed below:	,			10 30	29	26 25
NOTE: Not more than 4 corner on this certificate.	s, all in the same town :	and range, may be	recorded	12 31	34-	35 36
A. Description of original monu	ment and accessories a	nd/or subsequent r	estoration:	13 [	<del> </del>	<u></u>
Center of Section 21, T5S, 1 Not set by GLC. 1886, old survey book notes 1990, G.B. Warnke LCRC, Lib	stone center Section		' high.			
		•				
				,		
		·	a ar roostablishin	o cornor		•
B. Description of corner eviden	ce toutid and/or method	applied in restorio	y or reestablishin	ig comer.		
0/05 Tourid Oil generate new	t haine El hieb - Jua			had awar fam	the shame	
9/95, Found 8" concrete pos- not found. Used center of 1886 witnesses not found.	post at ground level	as occupied cente	r of Section 21			
			•			
			,	· ·		
			•			
		•			<b>x</b>	
		· · · · · · · · · · · · · · · · · · ·	national cantical	the position of	the correr	
C. Description of monument for					*	
Used center of found 8" congovernment surveyors, this corner and witnesses:  South 89°31'58" West 2639.5	monument is accepted a	as the best avail	able evidence o	f the positio		
(E-8 - 1995 Peer Group North 87°37'46" East 2611.10 east 1/4 corner of Sec	approved & will be refer to brass remon tion 21 (G-8 - 1995 P	emonumented with . cap on 1" x 36" eer Group approve	iron & remon.c iron pipe in m d)	ap in 1996) on. box marki		
South 00°11'31" East 2644.9 corner post marking the South 00°11'31" East 495.88	e south 1/4 corner of	Section 21 (F-9	- 1995 Peer Gro	up approved)		F CONTRACTOR
	<b>≾(, / ~</b>	4	Date1	2/20/1995	fal eso	mon or h
Signed by license No.	19474	7	,		1 1	NEO 12 STO SE
Surveyor's Michigan License No.		7		PROYED BY MICHIGAN ST	ATE BOARD OF LARD SUR	NEVISED MAY 14, 1975 REVISED JAN, 1983
Dossier's Page 6 - F-8,	T5S, R8E, Exeter Twp	· UMB	4 Paul 6	<b>3</b>		101.00 S
						Section 1