SURVEY & REMONUMENTATION

APR 2 8 1995

RATIFIED BY PEER GROUP PA 345 OF MONROE COUNTY, WEGE. 111811994

County Rep. :

stone.

COMMISSION

RECEIVED FOR RECORD

94 DEC 29 AHII: 00

REGISTER OF DEFOS

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

ro	MONROE	Located In: BERLIN	Corner Code =##
	(County)	TWP.	0011101 0000
1.	Public Land Survey	758 R 10 E	B-11
		T R	
	•	T R	
		T R	
2.	Property Controlling	S T R	
	in Section	S T R	
3.	Miscellaneous	S T R	
	Property in Sec.	STR	

Register of Deeds Stamp & File Number

_ , Recorded Plat _ Lot No. _ Private Claims _

1994 MONKOE COUNTY REMONUMENTATION PROGRAM

Peer Group approved corner on 11/8/1994 per Act 345 of 1990.

_ , in a field survey on _ 11/23/1994 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10

A. Description of original monument and accessories and/or subsequent restoration:

B-11, TSS, R10E, Berlin Township, Monroe County - ID No. 58 1/4 Corner Common to Sections 30 and 31 (Labo Road 1/2 mile West of Armstrong Road) 1817, G.L.O. Surveyor Joseph Fletcher set 1/4 section post between Sections 30 and 31 and witnessed: Beech 10 inch North 78° East 9 links, Sugar 12 inch South 15° West 23 links. Detroit Edison witnessed stone. 1966 A.J. Marino notes old PK and cap. 1992, G.B. Warnke notes 1/2 inch iron rod, witnesses probably fit

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

B-11 - Found 1/2 inch iron rod (1951 M.S.H.D. calls for stone) and witnessed as shown below. 11/23/1994, set 1 inch x 36 inch iron pipe with brass remonumentation cap inside momument box to replace rod.

Description of monument for corner and accessories established to perpetuate locating the position of the corner;

B-11 - Set 1 inch x 36 inch iron pipe with brass remonumentation cap inside monument box to replace found 1/2 inch iron rod and is accepted as the best available evidence of the position of the original corner and Witnesses:

North 59° West 153.45 feet to southeast corner of brick house - 4455 Labo

South 83° West 79.80 feet to mail & M.S.H.D. shiner in north face of 22 inch Elm

South 56° West +/- 118.5 feet to centerline of 24 inch Elm (no nail found - M.S.H.D. meas'd 118.50 feet

South 50° West 79.95 feet to nut on hydrant

South 85° West 82.07 feet to nail in north face of electric pole

South 70° East 40.60 feet to R.R. spike in electric pole

West 3.5 feet to west edge of asphalt for Brandon Road North +/- 19 feet to centerline of pavement of Labo Road to east ;

11/23/1994

GEORGE B. WARNKE, JR. LAND SURVEYOR

veyør's Michigan License No-

北總

Date 11 23/1994 NO. 19871
Paul Corm Approved by Michigan State Board of Land's University Jan. 28. 99