BURVEY & REVONUMENTATION

DEC 0 7 1994

RATIFIED BY PEER GROUP PA 345 OF 1990 MONROE COUNTY, MICHIGAN

19.9 County Rep. :

For corners in

COMMISSION

RECEIVED FOR RECORD

94 OCT 12 PH 2: 24

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

REGISTER OF DEEDS MONROE COUNTY, MICH

MONROE (County) Located In: Corner Code =## IDA TWP. T <u>7 S</u> R <u>7 E</u> 1. Public Land Survey G-5 __ R ___ Ť R 2. Property Controlling R in Section ___ T ____ R __ Miscellaneous ... T ._ _ R ____ Register of Deeds Stamp & File Number Property in Sec.

_ , Recorded Plat _

5. Private Claims

1994 MONROE COUNTY REMONUMENTATION PROGRAM Peer Group approved corner on 8/9/1994 per Act 345 of 1990.

I. G.B. WARNKE, JR. , in a field survey on AUGUST 19, 1994 , 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- 3 10 11 12
- A. Description of original monument and accessories and/or subsequent restoration:
 - G-5, T7S, R7E, Section Corner Common to Sections 9, 10, 15 & 16 (Intersection of Jackman & Lulu Roads - tar & large chip)

G.L.O. Surveyor Joseph Wampler in 1820 set a post at corner of Sections 9, 10, 15 & 16 and witnessed W.Oak 15 inch N79°W 13 links. 1972, Case & Fleck Surveys, recorded in Liber 627, Page 660 & Liber 636, Page 189 & Liber 650, Page 488, notes a F.I.P. (found iron pipe). 1976, G.B. Warnke Survey, Job No. 76-193, notes railroad spike 0.3 foot deep & recorded in L.C.R.C., Liber 3, Page 134, to railroad spike. Railroad spike or boat spike is noted in other surveys to present. August of 1994, G.B. Warnke found stone under railroad spike.

- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - G-5 8/2/1994, Found railroad spike 1 inch below surface. Dug 16 inch by 2 foot deep hole and found granite stone 9 inches deep. The high point of stone was 0.20 foot west and 0.17 feet north of railroad spike. No further evidence found under or by stone. Set 1 inch x 36 inch black iron pipe, at high point of stone, in monument box to replace stone. 8/19/1994, set brass remonumentation cap on black iron pipe. Witnessed as shown below.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-5 - Set 1 inch x 36 inch black iron pipe with brass remonumentation cap inside monument box to replace stone and is accepted as the best available evidence of the position of the original corner and Witnesses:

1,0000

North 45° East 36.63 feet found PK nail in northwest face electric pole South 45° East 51.58 feet found nail/washer in west face electric pole

South 60° West 53.31 feet found nail/washer in north face telephone pole

North 50° West 41.90 feet southeast face 2 inch diameter metal sign post

Signed by 19474 Surveyor's Michigan License No.

AUGUST

Warnke, Jr. LAND SURVEYOR NO. 994 19474

FORM APPROVED BY MICHAAN

STATES WELLED TO BE HELD SURVEYORS, JAN. 28, 1971 BEVISED MAY 14 1975

MICHALL OF MICA

GEORGE B.

3 rst 363