SURVEY & REMONUMENTATION

APR 2 8 1995

COMMISSION

HAI	ハトにし	BIPE	En o	NUUF	
	PA 3	345 OF	1990	0	
MONF	ROE C	OUNT'	Y/M	CHICA	M
lato:	91	OUNT LJ	9/90	N-X	

County Rep.

Public Land Survey

5. Private Claims

For corners in MONROE

LAND CORNER RECORDATION CERTIFICAT					
∏Filing	Requirement of Act 74, Mich. P.A. 1970)			
71					
Located In:	IDA TWP. Corner Code =±#				

.___ R ___ 2. Property Controlling in Section __ T <u>--</u>___ R __

Register of Deeds Stamp & File Number

Miscellaneous _ T ___ __ R _ Property in Sec. 4. Lot No. _ _ Recorded Plat ___

T 7 S R 7 E

1994 MONROE COUNTY REMONUMENTATION PROGRAM Peer Group approved corner on 9/6/1994 per Act 345 of 1990. , in a field survey on .

_9/26/1994 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law, established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10 11 12

REVISED MAY 14, 1975

REVISED JAN., 1983

- A. Description of original monument and accessories and/or subsequent restoration;
 - G-13, T7S, R7E, Section Corner Common to Sections 33 & 34 (At Jackman & Rauch Roads - 4 inch ashphalt over 8 inch concrete over sand base) (not common to G-1, T8S, R7E, Bedford)

1820, G.L.O. Surveyor, Joseph Wampler, set post corner of sections 33 & 34 - witnesses: B. Oak 20 inch South 19 East 26 links & B. Oak 16 inch North 6 East 22 links. 1974, M. Fleck recorded L.C.R.C., Liber 1, Page 452, to found valve in concrete pavement and found again in 1975 per survey recorded in Liber 699, Page 676. 1992, G.B. Warnke set PK nail over found auto valve.

- Description of corner evidence found and/or method applied in restoring or reestablishing corner:
 - G-13 11/23/1993 Found PK nail/washer over auto valve 8-31-94 excavated point found auto valve in concrete pavement over 6 inch tile filled with concrete over top/stone (with "+" in top) 20 inches +/- deep, stone about 12 inches long. Another stone 14 inches X 8 inches thick at west edge of "+'ed" stone. No evidence of post found under stone and witnessed as shown below. 8/31/1994, set 1 inch x 36 inch iron pipe inside momment box. 9/26/1994, set brass remonumentation cap on 1 inch iron pipe.
- C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:
 - G-13 Set 1 inch X 36 inches with brass remonumentation cap in monument box at surface to replace found PK nail and washer over auto valve and is accepted as the best available evidence of the position of the original corner and Witnesses:

North 45° West 42.36 feet nail/shiner east side electric pole

South 45° West 35.17 feet nail/shiner east side electric pole

South 52° East 159.90 feet northwest corner of foundation

East 9.65 feet found PK nail at northwest corner Section 3, T8S, R7E (Approved corner in 1993 program)

9/26/1994 Signed by Date 19474 Surveyor's Michigan License No. . FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971