SUFIVEY & REMONLIMENTATION

DEC 0 7 1994

RATIFIED BY PEER GROUP PA 345 OF 1990 MONROE COUNTY, MICHIGAN

County Rep.:

For corners in

COMMISSION

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970 RECEIVED FOR RECORD

94 OCT 12 PH 2: 34

•
1 /1.
1 1100
110. 1 11000
من الرحمة مناسطينية ما ما تأكر المهدار
REGISTER OF DEEDS
MEGRATICAL DEFENSAL
MOURCE COUNTY, MICH
William Parational Construction

			1 4.
MONROE (County)	Located In:	Corner Code =##	Heri allen
,	WHITEFORD	TWP.	MORROE COUNTY, MICH
1. Public Land Survey	т <u>8 S я 6 Е</u>	K-6	ECHULA: COURT 11, 1991
	ĭ R		•
	Ť R		
	T R		
2. Property Controlling	S T R		
in Section			
3. Miscellaneous	S T R		Pagistar of Doods Stown 9 File Number
Property in Sec.	S T R		Register of Deeds Stamp & File Number
5. Private Claims 1994 MONROE COUNTY RE Peer Group approved of G.B. WARNKE, JR.	orner on 8/9/1994 per Act 34	45 of 1990. 22/1994 19	2 6 5 4 3 2 3 4 7 8 9 10 11 12 12 12 13 13 14 15 15 15 15 15 15 15 15 15 15 15 15 15
	quirements of P.A. 74, Michigan P.A.		
	n conformance with regulations an actions of the United States Depar		
•	a Court of Law and/or that the corne		
	ith the rules of the Michigan Board o	•	· 1 19 - 1 - 20 - 1 - 21 - 1 - 22 - 1 - 23 - 1 - 24
Court of Law; established, expressed below:	re-established, monumented, re-r	nonumented, recovered, found	nd as 10 30 29 28 27 26 25
NOTE: Not more than 4 of	corners, all in the same town ar	nd range, may be recorded	11
on this certificate.		ge, may be received	12 31 32 33 34 35 36

- Description of original monument and accessories and/or subsequent restoration: K-6, TBS, R6E, 1/4 Corner Common to Sections 13 & 14 (Whiteford Road at Piehl Road - tarby) G.L.O. Surveyor Joseph Wampler in 1820 set guarter section post and witnessed Hickory Birch 8 inch North 23° West 25 links and Hickory 10 inch South 38° East 30 links. Harry R. Gard, March 18-22, 1902 Survey, notes old stone. 1974, G.B. Warnke, survey recorded Liber 680, Page 249, set I. bolt over stone 1 foot deep and has used the point to present and recorded in L.C.R.C., Liber 2, Page 264, to iron bolt over stone.
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: K-6-7/31/1994 - Found 3/4 inch x 6 inch bolt over limestone (took picture of stone) and broke stone and set 1 inch x 36 inch iron pipe inside monument box and witnessed as shown below. 8/22/94, set brass remonumentation cap on 1 inch x 36 inch iron pipe.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

K-6 - Set brass remonumentation cap on 1 inch x 36 inch iron pipe inside monument box and is accepted as a careful and faithful perpetuation of the position of the original corner and Witnesses:

South 80° East 44.95 feet south end of 12 inch concrete culvert North 45° East 58.73 feet north end of 12 inch concrete culvert

South 85° West 17.90 feet south end of 12 inch concrete culvert

North 55° West 30.05 feet southeast face of metal road sign post, also being

19474

north post of arrow sign

centerline of Piehl Road pavement to east North 16.5 feet

NO. 19374 LAND FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

Signed by .

Surveyor's Michigan License No. _

Date

REVISED MAY 14 1975

MICHIG

GEORGE B.

WARNKE, JP.

LAND BURVEYOR