SURVEY & REMONUMENTATION

RATIFIED BY PEER GROUP PA 345 OF 1990 MONROE COUNTY, MICHIGAN APR 28 1995

COMMISSION

date: 11	٤٦,	1993
County Rep. ;		400

on this certificate.

date: 11/8/1993 -		Con the bank of the value of the state of th			···¬
County Rep.:		ER RECORDATION CERTIFIC		Ç	Ä
For corners in	Filing Requir	ement of Act 74, Mich. P.A.	1970 美宝		T T
MONROE (County)	Located In: WHITEFORI	Corner Code =##	10 E CONTRA SE	: B	8 2
Public Land Survey	T <u>8'S R 6 E</u> T R T R T R	<u>M-8</u>	77, F.O.	MID: 40	RECORD
Property Controlling in Section	S T R S T R				
3. Miscellaneous	S T R S T R		Register of Deeds S	Stamp & Fil	e Number
4. Lot No, Reco 5. Private Claims, 1993 MONROE COUNTY REMONE Peer Group approved corne	JMENTATION PROGRAM	345 of 1990.	A B C D	E F G H	J J K L I
in lines 1 and 2 above were in co- current manual of survey instruction Management or by a decree of a Co- above were in conformance with the Court of Law; established, re-es- expressed below:	ements of P.A. 74, Michigan P.A. informance with regulations and one of the United States Depart out of Law and/or that the cornel arrules of the Michigan Board of stablished, monumented, re-marked.	/1994 , 19	d 6 18 17 17 18 19 19 19 19 19 19 19 19 19 19 19 19 19	9 10 15 21 22 23 27	11 12 13 14 13 24 26 25 25
NOTE: Not more than 4 corns	ers all in the came town on		ا ا ا ا ا ا	1 1 1 7	1717

A. Description of original monument and accessories and/or subsequent restoration:

M-8, T8S, R6E, 1/4 Corner Between Section 24, T8S, R6E, & Section 19, T8S, R7E (At Intersection of Consear & Adler Roads) (Also A-8, T8S, R7E) G.L.O. Surveyor set 1/4 post on east range line of Town 8 South, Range 6 East. / Road survey in 1924 indicates a stone. / Concrete pavement in place since approximately 1929. / J.W. White survey (1920's?) indicates a stone. / Case & Fleck survey in May of 1950 indicates a spike. / G.B. Warnke surveys No. 77-42, 81-73 & 83-271 indicates a 1/2 inch iron pipe over a bolt.

Description of corner evidence found and/or method applied in restoring or reestablishing corner. M-8 - 9/8/1993, found a 1/2 inch iron pipe at road surface. Warnke references fit well. 8/24/1994, dug 18 inch x 36 inch deep hole, found 1/2 inch x 3 inch iron pipe over 1 inch x 3 inch hex holt, and probed in all directions but no stone or post found. Found 1 inch x 24 inch iron pipe approximately 12 inches below surface and 0.6 feet east of 1/2 inch x3 inch iron pipe. Set brass remomumentation cap on 1 inch x 36 inch iron pipe inside monument box to replace 1/2 inch iron pipe over bolt. Witnessed as shown below.

Description of monument for corner and accessories established to perpetuate locating the position of the corner: M-8 - Brass remonumentation cap on 1 inch x 36 inch iron pipe inside monument box to replace found iron pipe over holt and is accepted as the best available evidence of the position of the original corner and witnesses: South 75° West 74.54 feet to found nail/shiner in north face of telephone pole North 40° West 37.48 feet to found nail/shiner in south face of electric pole

North 45° Fast 48.58 feet to found nail/shiner in southeast face of telephone pole South 50° Fast 47.17 feet to found nail/shiner in north face of telephone pole

19474

Signed by ∋urveyor's Michigan License No.

8/24/1994

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

3 Mat. 390 1119

REVISED JAN, 1983