[m] j... [m] j...

SECTION

A. - 2 2006

## LAND CORNER RECORDATION CERTIFICATE Filing Regulrement of Act 74, Mich. P.A. 1970

|  | ement of Act /4, Mich. P.A., 1   | 1970 92 希  |
|--|--|--|
| For corners in  MONROE (58)  County)  Located In: BEDFORD TWP.   | Corner Code #  | RECEIVED FOR RECORD  99 OCT 14 AM 9: 16  99 OCT 14 AM 9: 16  REGISTER OF DEEDS REGIS |
| 1. Public Land Survey T 8S R7E R  2. Property Controlling S T R  | A-6  | D FO   |
| in Section STR3. Miscellaneous STR   |  | ENTY AN R. R.  |
| Property in Sec. S T R   |  | SEES 9:  |
| 4. Lot No, Recorded Plat   |  | <b>5 6</b> 88  |
| 1998 & 1999 G.B. Warnke Remonumentation Private Corn   | ner  |  |
| I, George B. Warnke, Jr., in a field survey on 1998 - 1999   | do horoby state that walls   | Register of Deeds Stamp & File Number  |
| above were in conformance with regulations and rules therefore as re   | mentioned in lines 1 and 2   |  |
| of survey instructions of the United States Department of the Interior,<br>or by decree of a Court of Law and / or that the corner points mention  | Purezu of Land Management  | 1 A B C D E F G H I J K L  |
| were in conformance with the rules of the Michigan Board of Land Su  | Interiors or his a Decree of   | 2 - 6 5 3 2 1  |
| a Court of Law; established, re-established, monumented, recovered NOTE: Not more than 2 corners, all in the same town and range,  | i, tound as expressed below:<br>may be recorded on this certificate.   | 3  |
| A. Description of original monument and accessories an   |  | 4 7 8 9 10 11 11 12  |
| GLO did not set corner. ? - Old, John W. VanDeventer found fence running S at co   |  | 5  |
| 1971, Case & Fleck witness card iron pipe witnesses:   | intect point   | 7  |
| N30°W to iron 3.27'<br>S10°E 122.45' to NW. cor. 1 sty. Brick  |  | 8 19 20 21 22 23 24  |
| S45°W 32.83' to PK in power pole<br>1973, G.B. Warnke Survey 73-80, recorded in Liber 654, Pag   | 020 Fd   Fb  | 9  |
| 557"VV 32.75" PK E tace CP (Consumers Power) pole  | ge 639 – Fa. I. Pin – Witnesses;   | 10 - 30 - 29 - 28 - 27 - 26 - 25   |
| N51°E 56.56' SW face mt'l (metal) fence cor. post S69°E 102.44' PK SW face PT (utility) pole   |  | 11   |
| 1982, G.B. Warnke Survey 82-113 – 1/2" iron rod – witnesses: S57°W 32.75' PK nail in E face of elec pole   | •  | 12 31 32 33 34 35 36   |
| S70°E 102.44' PK nail in SW face of utility pole   |  |  |
| 1988, G.B. Warnke Survey 82-1\$3-2 - ¾" iron rod - witnesse S57°W 32.75' PK nail in E. face of elec. pole  | es:  |  |
| S70°E 102.44' PK nail in SW face of utility pole   | • • • • • • •  |  |
| 1990, G.B. Warnke Survey 90-393 - ¾" iron rod - found ¼" ir<br>1991, G.B. Warnke Survey 90-777 - found ¾" iron rod - with  | ron rod 1.5' W & 2.8' N<br>esses:  |  |
| S45W 32.38' nail in NE face utility pole<br>S30E 102.48' PK nail in S. face tele, pole   |  |  |
| N45E 47.80' nail in S. face S. trunk of triple trunk tree  |  |  |
| N45W 48.89' N. end of 24" metal culvert<br>1996, G.B. Warnke Survey 73-73, recorded in Liber 1507, Pa  | ae 0885 – found %" iron rod – with   | <u></u>  |
| S45°E 32.38' nail in NE face utility pole<br>S30°E 102.48' PK nail in S. face tele. pole   | ac cocc . Ioniu va IIon Ion - Milli  | 100000   |
| N45°E 47.80' nail in S. face S. trunk of tri-trunk tree  |  |  |
| N45°W 48.89' N. end of 24" metal culvert   |  |  |
|  |  |  |
| B. Description of corner evidence found and/or method ap<br>Corner is located on Piehl Road (E-W) in gravel tarby betw<br>12/7/98 – found 3/8" x 1.2' rebar bent to the south 0.50' below<br>with no further evidence found. Set 1" x 36" pipe with brass re | veen Summerfield and Whiteford the top of the tarby. Excavated a   | Roads.   |
| RATIFIED BY PEER GROUP, PA 345 OF 1990, MONROE CO  | UNTY, MICHIGAN, DATE 12/8/19   | 98, COUNTY REP. S F  |
| This position was not established by original government the position of the corner.   | surveyors. This monument is  | accepted as the best available evidence of   |
| C. Description of monument for corner and accessories es<br>Set 1" x 36" pipe with brass remonumentation cap in set monu   | ment box to replace found 3/8" ret   | g the position of the corner:<br>par & Witnesses:  |
| South 10° East 122.30 feet to northwest corner of brick resouth 45° East 32.38 feet to found PK nail in northeasterly South 65° East 102.45 feet to found PK nail in southerly factor to reset nail with set remonumer                                       | y face of utility pole<br>ace in utility pole  | southérly trunk of tri-trunk tree Marole   |
| MINIMUM OF MICE  | The state of the s |  |
| Signed by  | B  | Date_September 7, 1999   |
| Surveyor's Michigan License No. 1944 PROFESSIO   | NAL X  |  |
| SURVEYO<br>No.<br>19474  | OR S   |  |
| 19474  | FORM APPROVED BY   | MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971<br>REVISED MAY 14, 1975  |
| Milling ROFESSIO   | NAL STATEMENT FORM APPROVED BY   | REVISED JAN., 1983<br>REVISED OCT., 1994   |
| TOFESSION TOFESSION  | Illum.   | a contract of the contract of  |

 $4~\mathrm{Fast}\,,\,500$ 

· 1