

Section A continued

G.B. Warnke - 9/22/75 (survey #75-84) notes "RR spike" & witnesses:

N65°W 92.30' bonnet bolt on fire hydrant & N50°E 27.80' nail SW'ly face tel pole &

S65°E 85.24' nail NW face Consumers Power pole;

6/18/76 (survey # 76-85) & 1/15/79 (survey # 79-8 & LCRC, L.2, P.348) & 1979 (survey #79-172) & 1987 (#87-249) used R.R. spike" with same witnesses as shown above (ref. #75-84);

12/4/85 (survey #85-309) & 1989 (survey #89-191) & 3/23/94 (survey #94-0046) notes "found R.R. spike" & witnesses: N65°W 92.30' top nut on hydrant & N50°E 29.13' nail NW face of tel. pole & S65°E 85.24' nail NW face of elec. pole & South 29.47' nail N. face 36" tree (Oak)