## SURVEY & REMONUMENTATION

BATIFIED BY PEER GROUP PA 245 05 1930

3 Miscellaneous

Property in Sec.

APR 28 1995

## LAND CORNER RESORDATION CERTIFICATE

County Rup. Filing Requirement of Act 74, Mich. P.A. 1970 For corners in

• • • • • • • • • • • • • • • • • • • •			
_	MONROE (County)	Located In: BEDFORD TWP.	Corner Code =##
1.	Public Land Survey	T 8 S R 7 E	G-7
		T R T R	
2.	Property Controlling in Section	S T R ′ S T R	

Register of Deeds Stamp & File Number

\_\_ , Recorded Plat \_\_\_ 4. Lot No. . 1994 MONROE COUNTY REMONUMENTATION PROGRAM Peer Group approved corner on 9/20/1994 per Act 345 of 1990.

11/10/1994 \_ , in a field survey on \_ do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10 12

A. Description of original monument and accessories and/or subsequent restoration:

G-7, T8S, R7E, Bedford Township, Monroe County - ID No. 58 Section Corner Common to Sections 15, 16, 21 & 22

(Intersection of Jackman & Temperance Roads - 2" tarby over 6" concrete over mixed sand) 1820, G.L.O. Surveyor, Joseph Wampler, set post Sec. corner, witnesses: W. Oak 11 (inch) S.50°N. 288 links & W. Cak 28 (inch) S.21°W. 353 links. 1902, T.A. Steiner found old stone. M.C.R.C. (date?) notes stone. 1925. (source?) witnesses refer to stone. 1972. M.R. Fleck set "T" iron. 1979. G.B. Warnke recorded LCRC. Liber 2, Page 363, to PK nail at "T" iron. Later, set shank of railroad spike.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

G-7 - 9/20/1994, excavated in tarby & concrete pavement and found stone 14 inches deep under railroad spike. No other evidence found; no post found under stone. Set 1 inch x 36 inch iron pipe in monument box to replace railroad spike over stone and witnessed as shown below. 11/10/1994, set brass remonumentation

cap on 1 inch x 36 inch iron pipe inside monument box.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

G-7 - Set 1 inch x 36 inch iron pipe with brass remonumentation cap inside monument box to replace stone & shaft and is accepted as the best available evidence of the position of the original corner and Witnesses:

North 45° East 49.96 feet to found nail/shiner in northwest face of utility pole

South 45° East 44.80 feet to found PK nail in northwest face of utility pole

South 30° West 55.91 feet to found PK nail in northeast face of cable pole

North 45° West 46.25 feet to found nail/shiner in southwest face of utility pole

South 45° West 43.96 feet to top nut of hydrant

Signed by 2 19474 Surveyor's Michigan Lice\se No.

Date 11/10/1994

Warnke, Jr. AND SURVEYOR NO.

OF MICHIG

GEORGE B.

STATE BOARD OF LAW

3 Pai 447

REVISED MAY 14, 19 REVISED JAN., 19