## SURVEY &

RATITIOD BY CIER GROUP	REMONUMEN	STATION					
MONRO_ 1590  MONRO_ 17, MICHIGAN  date: 11-16-93	DEC 0 7 19	194		RECEN	'ED Foi	RRECC	)RD
County Rep.:	LAND CORNER REGORE Filing Requirement of	MATION CERTIFICAT	E	94 001			
For corners in	i iiiig nequirement of	ACI 74, MICH. P.A. 197	U	1.	а		
MONROE_ (County)	Located In: Corne	er Code =##		Ler REGIS MONDO	TER OF DE COURT	EEOS	
Public Land Survey	T_8 S R 7 E	M-11		7	u obliki j	r, Mich	
in Section S _ 3. Miscellaneous S _	T R	R	egister of	Deeds Stan	no & File	Numbe	<b>e</b> r
4. Lot No, Record 5. Private Claims			- A B	CDE			
1993 MONIKOE COUNTY REMONUME Peer Group approved corner	NTATION PROGRAM on 11/16/1993 per Act 345 of 19	90.	3 6-	54	3-		
do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:			4 7 5 18 7 8 19 9 10 30		15	1114	13
NOTE: Not more than 4 corners on this certificate.	, all in the same town and range, m	ay be recorded	11 12 31-	32 33	34-	35	36
M-II, TBS, R/E, Section Corr (On Sterns Road - Nor 1820, G.L.O. Surveyor Joseph N.46°E. 13 links & Ash 10 in N.79°E. 146.52 feet to 24 in 2 witnesses. / 1981 & 1982,	ment and accessories and/or subsequer Common to Sections 25 & 36 th of Chesapeake & Ohio Railroad wampler set post at corner of sch S.25°W. 11 links. / 1886, Winch Cottonwood. / A.J. Marino, de MDOT Survey on M-125 (Dixie Hwy xox per LCRC, Liber 2, Page 435.	d - hard surface) Sections 25 & 36 and Illis Baldwin noted st Nated May 1970, notes	one and w	itness 3 feet dee	p with		

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: M-11 - Found 1/2 inch iron rod inside monument box and witnessed. On 8/29/1994, 1/2 inch rod could not be removed. Placed remonumentation cap on rod and witnessed as shown below.



C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: M-11 - Found 1/2 Tuch Iron Rod Inside Monument Rox and Set Remonumentation Cap on Rod and is accepted as the best available evidence of the position of the original corner and witnesses: South 20° West 30.12 feet nail/shiner (MDOT) in northwest face of guy pole North 20° West 45.30 feet nail/shiner (MOOT) in east face of electric pole North 84°19'31" West 2660.75 feet PK nail/washer at South 1/4 corner, Section 25, 78S, R7E South 89°53'30" East 2659.85 feet broken concrete monument in monument box at South 1/4 corner, Section 30, T8S, R8E

Signed by	
Surveyor's Michigan License No	19474

Aug 29, 1994

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971

REVISED MAY 14, 1975 REVISED JAN , 1983