burivey a REMONUMENTATION

DEC 07 1994

RATIFIED BY PEER GROUP PA 345 OF 1990 MONROE COUNTY, MICHIGAN

COMMISSION

RECEIVED FOR RECORD

LAND CORNER RECORDATION CERTIFICATE 94 OCT 12 PM 2: 45 Filing Requirement of Act 74 Mich D.A. 1

For corners in	rung nequit	entent of ACL 74, Micsi. P.A.	. 1970
MONROE (County)	Located In: ERIE TV	Corner Code =##	REGISTER OF DEEDS MONROE COUNTY, MICH
Public Land Survey	T <u>8 S R 8 E</u> T R T R T R	A-11	
2. Property Controlling in Section	S T R S T R		
Miscellaneous Property in Sec.			Register of Deeds Stamp & File Number
5. Private Claims 1994 MONROE COUNTY REA Peer Group approved co G.B. WARNKE, JR. do hereby certify that under rec in lines 1 and 2 above were in current manual of survey instri Management or by a decree of above were in conformance wi Court of Law; established, re expressed below:	in a field survey onAUGU quirements of P.A. 74, Michigan P.A. n conformance with regulations an actions of the United States Depart a Court of Law and/or that the corne the the rules of the Michigan Board of re-established, monumented, re-n	ST 29, 1994 19 19 of 1970, the corner points mentioned rules therefore as required in the ment of the Interior, Bureau of Lair points mentioned in lines 3, 4 and of Land Surveyors or by a Decree of nonumented, recovered, found in	2 6 5 4 3 2 1 1 1 1 1 2 1 1 1 1 1 1 1 1 1 1 1 1
A. Description of original A-11, T8S, R8E, Corner	monument and accessories and of Sections 30 & 31, T85, 1	d/or subsequent restoration: R8E, and 25 & 36, T8S, R7E	13

(On Sterns Rd. - North of Chesapeake & Chio Railroad) (Also M-11, T8S, R7E - Approved in 1993) 1820, G.L.O. Surveyor Joseph Wampler set post at corner of Sections 25 & 36. Witnesses: Hickory 11 inch N.46°E. 13 links & Ash 10 inch S25°W 11 links. / 1886, Willis Baldwin noted stone. Witness: N.79°E. 146.52' to 24 inch Cottonwood. / A.J. Marino, dated May of 1970, notes old iron 3 feet deep with 2 witnesses. / 1981 & 1982, MDOT Survey on M-125 (Dixie Hwy.), Glen Hobgood (#21571) for M.S.H.D. excavated & witnessed 1/2 inch iron rod & placed monument box per LCRC, Liber 2, Page 435. / 1992, G.B. Warnke found 1/2 inch iron rod in monument box.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A-11 - On 7/25/1992, found 1/2 inch iron rod in monument box and witnessed. On 8/29/94, 1/2 inch iron rod could not be removed, placed remonumentation cap on rod and witnesses as shown below.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A-11 - Found 1/2 inch Iron Rod with Set Remonumentation Cap in Monument Box & is accepted as a careful and faithful perpetuation of the position of the original corner & Witnesses: South 20° West 30.12' nail/shiner (MDOT) in northwest face of guy pole North 20° West 45.30' nail/shiner (MDOT) in east face of electric pole North 84°19'31" West 2660.75' PK nail/washer at South 1/4 Corner of Section 25, T8S, R7E South 89°53'30" East 2659.85' broken concrete monument in monument box at South 1/4 MICHIGA

19474

Corner of Section 30, T8S, R8E

Surveyor's Michigan License No.

Signed by

9/29/1994

FORM APPROVED BY MICH

GEORGE B. wannke, Jr. LAND SURVEYOR

ED LAND

-NO-19474

3 Park 379 LUC