## SURVEY & REMONUMENTATION

FEB 1 9 1998

## MONTCALM COUNTY REMONUMENTATION PROGRAM

## LAND CORNER RECORDATION CERTIFICATE

SECTION

MONTCALK COUNTY

12

Filing Requirement of Act 74, Mich. P.A. 1970 STATE OF MICHIGAN For corners in Montcalm (County) RECORDED Located in: Corner Code # Douglass Township 26 Dec 1997 3:41:07 PM 1. Public Land Survey T 11 NR 7 W H-13, S 1/4 LORI A. WILSON REGISTER OF DEEDS R 2. Property Controlling in Section 3. Miscellaneous R Register of Deeds Stamp & File Number Property in Sec. Lot No. , Recorded Plat DEFGHIJKL 5. Private Claims 2 3 William Tingley a field survey on August 29th 4 ٠ġ 10 -11 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land 5 6 18 17 16 15 14 13 Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as 7 19 21 22 24 20 23 Я expressed below: Ç NOTE: Not more than 2 corners, all in the same town and range, may be recorded 10 30 29 28 27 25 26 on this certificate. 11 12 31 32 33 34 35 Description of original monument and accessories and/or subsequent restoration: December 9, 1836, Noah Brookfield, GLO Notes Calls out 20" Pine as Corner. No witnesses given. 1884, H.M. Caulkin, County Surveyor, Book 1, Page 375, Record of Minutes of Survey Reestablished and set fire clay monument (blacksmith cinder) 200.20 chains from Southeast Corner of 36 and 40.04 chains from Corner 33 and 34 South boundary; and on straight line between Corner 3 and 4 North Boundary T10N-R7W; and corners 33 & 34 South Boundary T11N-R7W; **New Bearing Tree:** Pine Stump 20" N44-1/2°W 69 links September 13, 1909, J.E. Youdan, Field Book 11-7, Page 72-73 Reestablished and set 1-1/4" gas pipe, 4 feet long. No witnesses given. 1939, R.D. McNutt Has same witnesses as above on his records Found Iron Pipe Maple 6" Northeast ACCEPTED BY THE MONTCALM COUNTY SURVEY F 44.0 feet Cherry 6" GROUP AS THE OFFICIAL CORNER UNDER M North 35.6 feet PUBLIC ACT 345 OF 1990 AT A MEETING HELD 12/10 1939, Michigan State Highway Department Plans, Project 59-32 1-1/2" Iron Pipe FOW. 6" Maple Northeast 44.0 feet William Tingley, PS, Chairman 6" Cherry North 35.6 feet 0.48 Left of Sta. 52 + 86.81 Stump Fence North, 52 + 84.0 126.8 feet West of Corner Section 3 and 4, T10N-R7W Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found 30 d Nail under bituminous pavement 2 feet North of Centerline Road. On Stump Fence North. Dug 3 feet deep and found no more evidence. Measurements to Section Corners are 2641.41 to East and 2641.59 feet to West (Youdan's measurements were 2643.63 East and West in 1909.) Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set Remonumentation Monument in place of spike. Set Nail and Tag in Northeast Side Power Pole S45°E 58.60 feet Set Nail and Tag in East Side Power Pole North 53.50 feet 47.75 feet Set Nail and Tag in South Side 30" Maple N45°E Set Nail and Tag in East Side 6" White Oak N20°W 31.92 feet This corner is accepted as a careful and faithful perpetuation of the position of the original corner. Signed by William & Tru Date 12/00 Surveyor's Michigan License No. 30104

STATE OF MICHIGAN REVISED MAY 14, 197 WILLIAM G. TINGLEY 30104 POFESSIONP