DEC 1 9 2000

I HARDING TOT

MONTCALM COUNTY REMONUMENTATION PROGRAM

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

SECTION

Houses all Covery Maple Valley Township The Third Third Township The Third	For come: Montcal		Located In:		Corner Code #	·	1	STATE	OF MIC	DUNTY			
Public Land Survey Sec. 31,36 T 11 BR 09 B T 11 R 10 BB 13 BE 13 BE 268 3154 BW 128 BW	MOILCA.		sample Valley Tr	weship		ļ		חטוז	RECORD	EB			
Public Land Survey Sec. 91,36 T 11 N R 00 N T 11 R 10 N M 13			Mable valley is	эмпэгир			00	RIN :	วดติต 9	:34:07	AM ,		
T. T. R. 1.0 T. R. R. 1.0 T. R. R. Register of Deeds Stamp & File Number Register of Deeds St							1 20	יוטני נ		ITI COM	,		
2. Proporty Controlling S T R R Register of Deeds Stamp & File Number In Section S T R R Register of Deeds Stamp & File Number In Section S T R R Register of Deeds Stamp & File Number In Section S T R R Register of Deeds Stamp & File Number In Section S T R R Register of Deeds Stamp & File Number In Section S T R R Register of Deeds Stamp & File Number In Section S T R R Register of Deeds Stamp & File Number In Section S T R R Register of Deeds Stamp & File Number In Section S Register In Section S Register of Deeds Stamp & File Number In Section S Register In Secti	1. Public	Land Survey Sec. 3	! <u>_11</u> _ K	10		- 	Ļ	LC REG	RI A. I ISTER O	DEEGS	<u></u>		
2. Property Controlling S T R R										÷			
in Section S T R Maccellaneous S T R A B C S F G H I J K L N Lot No. Recorded Plat I R R R R R R R R R	2 Prope	rty Controlling S					anietor	of Do	ode St	amp &	File N	lumbe	г
Property in Sec. S T K 1. Lot No. Recorded Plat Recorded Re			7 8			'``	egistei	0. 00		<u></u> -			
the theory certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points maniformed of the theory certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points maniformed of the theory of the th	Prope	rty in Sec. S_	T F			· · ·							
the theory certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points maniformed of the theory certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points maniformed of the theory of the th	4 Lot No	Recor	ded Plat				, А	8 (; D &	F G	; H 1	J_K	į. M
1. William G. Tingley in a field survey on Noy 3, 2000 4 4 7 8 9 10 11 12 4 7 8 9 10 11 12 4 7 8 9 10 11 12 4 7 8 9 10 11 12 4 7 8 9 10 11 12 5 10 10 11 12 5 10 10 11 12 5 10 10 11 12 5 10 10 11 12 5 10 10 11 12 5 10 10 11 12 5 10 10 11 12 5 10 10 11 12 5 10 10 11 13 5 10 10 11 13 5 10 10 11 13 5 10 10 11 13 5 10 10 11 13 5 10 10 11 13 5 10 10 11 13 5 10 10 11 13 6 11 17 10 15 14 13 6 15 14 13 6 15 17 10 15 14 13 6 15 17 10 15 14 13 6 15 17 10 15 14 13 6 15 17 10 15 14 13 6 15 17 10 15 14 13 6 15 17 10 15 14 13 6 15 17 10 15 14 13 6 17 10 15 14 13	5. Privati	e Claims					- 1	6	5	4	3	2	3
in lines 1 and 2 above wells at store, wells at the line of States Department of the Interior. Bureau of Land current manual of survey and store that the comer points mentioned in fises 3,4 and 5 an			•				ì				10	11	12
in lines 1 and 2 above wells at store, wells at the line of States Department of the Interior. Bureau of Land current manual of survey and store that the comer points mentioned in fises 3,4 and 5 an	ı, Wil	lliam G. Tingley		in a field su	rvey ол <u>Мау 3, 2</u>	er points mentioned		1	8	_	10	''	12
Management of by a decree of a conformance with the bles of the Michigan Board of Land Surveyers or by a Decree of a blook were in conformance with the bles of the Michigan Board of Land Surveyers or by a Decree of a blook were in conformance with the bles of the Michigan Board of Land Surveyers or by a Decree of a blook were in conformance with the bles of the Michigan Board of Land Surveyers or by a Decree of a blook was a surveyer or by a Decree of a blook was a surveyer or by a Decree of a blook was a surveyer or by a Decree of a blook was a surveyer or by a Decree of a blook was a surveyer or by a Decree of a blook was a surveyer or by a Decree of a blook was a surveyer or by a Decree of a blook was a surveyer or by a Decree of a blook was a surveyer or by a blook was a surveyer or	in lines 1	and 2 above were in	Comomission in	Chaire Done	ement of the Interi-	or Bureau of Land	6	18	17	16	15	14	13
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A Description of original monument and accessories and/or subsequent restoration: 1. December 11, 1836, Noah Brookfield, Deputy Surveyor, GLO notes, West on south side section 31 2. Set post corner of Ranges 9 and 10 North Town 11 North 2. Birch 10" NSO'W 27 links (7.26 feet) 3. December 18, 1903, Henry M. Caukin, County Surveyor, Record of Survey Book 2-A Page 44 All SW corner of section, put down piece of sleigh shoe 22 inches long 3. December 28, 1903, Henry M. Caukin, County Surveyor, Record of Survey Book 1-A Page 84 and Book 3 Page 100 3. Pocember 28, 1903, Henry M. Caukin, County Surveyor, Record of Survey Book 1-A Page 84 and Book 3 Page 100 3. Pocember 28, 1903, Henry M. Caukin, County Surveyor, Record of Survey Book 1-A Page 84 and Book 3 Page 100 3. Pocember 1886 and remains of one Bearing Tree. Put big pine root stake 2 rods north. (Both entries are the same) 4. No date, R.D. McNutt card file T11N-R10W #132 SE corner Section 36 at Tingley and Associates office 5. December 1988, Glen S. Hackbardt # 25844, LCRC T11N-R10W M-13 Liber 002 Page 239 Sleigh shoe 5. Segn'W 187.50 feet Maple 36" Sagn'W 187.50 feet Most 1889, William R. Byl # 23502, Survey 22-Mile Road Right of Way MI Bell cable placement Found sleigh shoe in two pleces 11" below the road surface. The second plece was 16" below grade on the west side of the first. Both pieces were approximately 9" long. Found evidence of wood at the bottom of the hole. C. Description of corner evidence found and/or method applied in restoring or reestablishing corner. Set remonumentation pipe in place of sleigh shoe pieces. Set one piece on the east side of the pipe and the other piece on the set side. Set NT N/S maple 36" S88"W 187.52 feet Set NT SM power pole N86"W 167.60 feet Set NT SM power pole N86"W 167.60 feet Set NT FLS quad etn 6" S88"W 187.52 feet Set NT FLS quad etn 6" S88"W 187.52 feet Set NT FLS quad etn 6" S88"W 187.55 feet	Managem	ent or by a decree or a	Court of Law and	Millian Dog	d of Land Surveyor	s or by a Decree of a	8	19	20	21	22	23	24
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. A. Description of original monument and accessories and/or subsequent restoration: 1. December 11, 1836, Noah Brookfield, Deputy Surveyor, GLO notes, West on south side section 31 1. December 11, 1836, Noah Brookfield, Deputy Surveyor, GLO notes, West on south side section 31 1. December 11, 1836, Noah Brookfield, Deputy Surveyor, GLO notes, West on south side section 31 1. December 11, 1836, Noah Brookfield, Deputy Surveyor, GLO notes, West on south side section 31 2. July 1895, Henry M. Caukin, County Surveyor, Record of Survey Book 2-A Page 44 All SW corner of section, put down piece of sleigh shoe 22 inches long No witnesses given 3. December 28, 1903, Henry M. Caukin, County Surveyor, Record of Survey Book 1-A Page 84 and Book 3 Page 100 Found my iron of 1896 and remains of one Bearing Tree. Put big pine root stake 2 rods north. (Both entries are the same) 1895 sleigh shoe	expressed	d below:						40	~	20	27	24	25
A Description of original monument and accessories and/or subsequent restoration: 1. December 11, 1836, Noah Brookfield, Deputy Surveyor, CLO notes, West on south side section 31 Set post comer of Ranges 9 and 10 North Town 11 North Birch 10" N47"E 11 finks (7.28 feet) Birch 10" N50"W 27 links (17.82 feet) Found my irno of 1896 and remains of one Bearing Tree. Put big pine root stake 2 rods north. (Both entries are the same) 1. December 28, 1903, Henry M. Caukin, County Surveyor, Record of Survey Book 1-A Page 84 and Book 3 Page 100 Found my irno of 1896 and remains of one Bearing Tree. Put big pine root stake 2 rods north. (Both entries are the same) 1. No date, R.D. McNutt card file T11N-R10W #132 SE corner Section 36 at Tingley and Associates office 1895 sheigh shoe 1. December 1988, Glen S. Hackbardt # 25844, LCRC T11N-R10W M-13 Liber 002 Page 239 Sleigh shoe 1. Description of corner evidence found and/or method applied in restoring or reestablishing corner. 1. Description of corner evidence found and/or method applied in restoring or reestablishing corner. 2. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set remonumentation pipe in place of sleigh shoe to vidence of wood at the bottom of the hole. 2. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set remonumentation pipe in place of sleigh shoe widence of wood at the bottom of the hole. 2. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set remonumentation pipe in place of sleigh shoe pieces. Set one piece on the east side of the pipe and the other piece on the vest side. Set NT NS maple 36" Set NT INS m	NOTE:	Not more than 2 co	rners, all in the	same town	and range, may t	e recorded	- 1	30	29	20	27	20	20
Set post corner of Ranges 9 and 10 North Town 11 North Set post corner of Ranges 9 and 10 North Town 11 North Birch 10° Birch 10° Birch 10° N47°E 11 links (7.26 feet) Birch 10° PUBLIC ACT 345 OF 1990 AT A MEETING HELD LIVE RECOVER 11 Surveyor, Record of Survey Book 2-A Page 44 At SW corner of section, put down piece of sleigh shoe 22 inches long No witnesses given 3. December 28, 1903, Henry M. Caukin, County Surveyor, Record of Survey Book 1-A Page 84 and Book 3 Page 100 Found my iron of 1896 and remains of one Bearing Tree. Put big pine root stake 2 rods north. (Both entries are the same) 4. No date, R.D. McNutt card file T11N-R10W #132 SE corner Section 36 at Tingley and Associates office 1895 sleigh shoe 5. December 1988, Gien S. Hackbardt # 25844, LCRC T11N-R10W M-13 Liber 002 Page 239 Sleigh shoe Ash 15° N05°W Ash 16° N80°W 167.80 feet N80°W 167.80 feet No witnesses given 6. 1989, William R. Byl # 23502, Survey 22-Mile Road Right of Way MI Bell cable placement Found sleigh shoe No witnesses given 6. Description of corner evidence found and/or method applied in restoing or reestablishing corner: Found sleigh shoe in two pieces 11° below the road surface. The second piece was 16° below grade on the west side of the first. Both pieces were approximately 9° long. Found evidence of wood at the bottom of the hole. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set NTT IN/S maple 36° S88°W 187.62 feet Set NT IN/S maple 36° S88°W 187.62 feet No "Y" S80 feet No" Y" S80	NOTE.	on this certificate.	·				Į.	31	32	33	34	35	36
Set post corner of Ranges 9 and Not 10 Not 1	A. De	scription of original m	nonument and ac	cessories and	d/or subsequent reverse. GLO notes	estoration: s, West on south s	ide sec	tion 3	11				
Birch 10" N37"E 11 links (7:28 feet) PUBLIC ACT 315 OF 1930 AT A MEETING HELD C/F. Birch 10" N50"W 27 links (17:92 feet) PUBLIC ACT 315 OF 1930 AT A MEETING HELD C/F. PUBLIC ACT 315 OF 1930 AT A MEETING HEL	1. De	cember 11, 1836, N	f Ranges 9 and 1	0 North Tow	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1					ONTCA	LM COL	INTY SI	URVEY I
2. July 1895, Henry M. Caukin, County Surveyor, Record of Survey Book 2-A Page 44 Al SW corner of section, put down piece of sleigh shoe 22 inches long No witnesses given 3. December 28, 1903, Henry M. Caukin, County Surveyor, Record of Survey Book 1-A Page 84 and Book 3 Page 100 Found my iron of 1896 and remains of one Bearing Tree. Put big pine root stake 2 rods north. (Both entries are the same) 4. No date, R.D. McNutt card file T11N-R10W #132 SE corner Section 36 at Tingley and Associates office 1895 sleigh shoe 5. December 1988, Glen S. Hackbardt # 25844, LCRC T11N-R10W M-13 Liber 002 Page 239 Sleigh shoe Ash 15' N05°W 24.00 feet Ash 15' N05°W 167,80 feet Ash 15' N05°W 167,80 feet Maple 36' N80°W 167,80 feet N80°W 167,80 feet N80°W 167,80 feet Found sleigh shoe in two pieces 11" below the road surface. The second piece was 16" below grade on the west aide of the first. Both pieces were approximately 9" long. Found evidence of wood at the bottom of the hole. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner. Set remonumentation pipe in place of sleigh shoe pieces. Set one piece on the east side of the pipe and the other piece on the west side. Set N/T N/S maple 36' S88'W 187,62 feet Set N/T S/S power pole N86°W 187,65 feet Corner E/S cable marker N04°E 37,95 feet T/C east end CM/P S60°W 38.68 feet T/C east end CM/P S60°W 38.68 feet T/C east end CM/P S60°W 38.68 feet T/C cast end CM/P S60°W 38.68 feet T/S corner is accepted as the careful and faithful perpetuation of the position of the original corner. Bearings given are magnetic. Standard remonumentation pipe consists of a Berntsen stainless steel 2 3/8" x 30" pipe with a brase cap stamped "MONTCALM COUNTY REMONUMENTATION, P.S. # 30104"		Set post corner of Birch 10	,	N4/ E	1111100 (1.50)	eet)	COLUB	AS T	HE OFF	ICIAL C	ORNER	I UNDE	R.MICH
At SW comer of section, put down piece of slergin shoe 22 holds only No witnesses given 3. December 28, 1903, Henry M. Caukin, County Surveyor, Record of Survey Book 1.A Page 84 and Book 3 Page 100 Found my fron of 1896 and remains of one Bearing Tree. Put big pine root stake 2 rods north. (Both entries are the same) 4. No date, R.D. McNutt card file T11N-R10W #132 SE corner Section 36 at Tingley and Associates office 1895 sleigh shoe 5. December 1988, Gien S. Hackbardt # 25844, LCRC T11N-R10W M-13 Liber 002 Page 239 Sleigh shoe Ash 15' N05"W 24.00 feet Ash 15' N80"W 167.80 feet N80"W 167.60 feet No.0. No.		Birch 10	27	N50°W	27 links (17.821	eet)	PUBLIC	ACT 3	15 UF 19	SUAIA	MEE!IN	ig Herr	61.71
4. No date, R.D. McNutt card file T11N-R10W #132 SE corner Section 36 at Tingley and Associates office 1895 sleigh shoe 5. December 1988, Glen S. Hackbardt # 25844, LCRC T11N-R10W M-13 Liber 002 Page 239 Sleigh shoe Ash 15' N05°W 24.00 feet		At SW corner of s	section, put dowr esses given	piece or sier	gir siloe 22 inones	, iong			-	•		y, PS, C	hairman
 4. No date, R.D. McNutt card file T11N-R10W #132 SE corner Section 36 at Tingley and Associates office 1895 sleigh shoe 5. December 1988, Glen S. Hackbardt # 25844, LCRC T11N-R10W M-13 Liber 002 Page 239 Sleigh shoe Ash 15" N05°W 24.00 feet Ash 16" N08°W 167.80 feet Maple 36° Sa0°W 168.00 feet Maple 36° N80°W 167.80 feet CMP N80°W 167.80 feet No witnesses given 6. 1989, William R. By! # 23502, Survey 22-Mile Road Right of Way MI Bell cable placement Found sleigh shoe No witnesses given B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found sleigh shoe in two pieces 11" below the road surface. The second piece was 16" below grade on the west side of the first. Both pieces were approximately 9" long. Found evidence of wood at the bottom of the hole. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set remonumentation pipe in place of sleigh shoe pieces. Set one piece on the east side of the pipe and the other piece on the set side. Set N/T N/S maple 36" S88°W 187.52 feet Set N/T S/S power pole N86°W 167.60 feet Set N/T S/S power pole N86°W 37.95 feet Center E/S cable marker N04°E 37.95 feet N04°E 37.95 feet N04°E 37.95 feet Set N/T E/S quad elm 6" S60°W 38.68 feet This corner is accepted as the careful and faithful perpetuation of the position of the original corner. Bearings given are magnetic. Standard remonumentation pipe consists of a Berntsen stalnless steel 2 3/8" x 30" pipe with a brase cap stamped "MONTCALM COUNTY REMONUMENTATION, P.S. # 30104" 	3. De	ecember 28, 1903, H	lenry M. Caukin	, County Sur	veyor, Record of aring Tree. Put big	Survey Book 1-A	Page 8 ods nor	4 and th. (E	Book toth en	3 Page tries ar	e 100 e the s	ame)	
Sleigh shoe December 1988, Glen S. Hackbardt # 25844, LCRC T11N-R10W M-13 Liber 002 Page 239 Sleigh shoe Ash 15' N05°W 24.00 feet Maple 36° S80°W 188.00 feet CMP N80°W 167.80 feet Found sleigh shoe No witnesses given B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found sleigh shoe in two pieces 11" below the road surface. The second piece was 16" below grade on the west side of the first. Both pieces were approximately 9" long. Found evidence of wood at the bottom of the hole. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set remonumentation pipe in place of sleigh shoe pieces. Set one piece on the east side of the pipe and the other piece on twest side. Set N/T N/S maple 36" S88°W 187.52 feet Set N/T S/S power pole N86°W 167.60 feet T/C east end CMP N38°E 40.16 feet Set N/T E/S quad elm 6" S60°W 38.68 feet T/C east end CMP Set N/T E/S quad elm 6" S60°W 38.68 feet This corner is accepted as the careful and faithful perpetuation of the position of the original corner. Bearings given are magnetic. Standard remonumentation pipe consists of a Berntsen stainless steel 2 3/8" x 30" pipe with a brase cap stamped "MONTCALM COUNTY REMONUMENTATION, P.S. # 30104"	4. N	o date, R.D. McNutt	card file T11N-l	R10W #132	SE corner Sectio	n 36 at Tingley and	Asso	ciates	office	_		_	
Sleigh shoe Ash 15' Maple 36' CMP N80'W 167.80 feet CMP N80'W 167.80 feet Found sleigh shoe No witnesses given B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found sleigh shoe in two pieces 11" below the road surface. The second piece was 16" below grade on the west side of the first. Both pieces were approximately 9" long. Found evidence of wood at the bottom of the hole. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set remonumentation pipe in place of sleigh shoe pieces. Set one piece on the east side of the pipe and the other piece on the west side. Set N/T N/S maple 36" Set N/T S/S power pole N86'W 167.60 feet Y/C east end CMP Set N/T S/S cable marker N/4'E 37.95 feet T/C east end CMP N38'E 40.16 feet Set N/T E/S quad elm 6" Set N/T S/S power pole N38.68 feet This corner is accepted as the careful and faithful perpetuation of the position of the original corner. Bearings given are magnetic. Standard remonumentation pipe consists of a Berntsen stainless steel 2 3/8" x 30" pipe with a brase cap stamped "MONTCALM COUNTY REMONUMENTATION, P.S. # 30104"		1895 sleigh shoe							_	,E	OF MIC	3/1/2	
Ash 15" N05"W 188.00 feet CMP N80"W 167.80 feet CMP N80"W 167.80 feet 1989, William R. Byl # 23502, Survey 22-Mile Road Right of Way MI Bell cable placement Found sleigh shoe No witnesses given B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found sleigh shoe in two pieces 11" below the road surface. The second piece was 16" below grade on the west side of the first. Both pieces were approximately 9" long. Found evidence of wood at the bottom of the hole. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set remonumentation pipe in place of sleigh shoe pieces. Set one piece on the east side of the pipe and the other piece on twest side. Set N/T N/S maple 36" S88"W 187.52 feet Set N/T S/S power pole N86"W 167.60 feet Center E/S cable marker N04"E 37.95 feet T/C east end CMP N38"E 40.16 feet Set N/T E/S quad elm 6" S60"W 38.68 feet This corner is accepted as the careful and faithful perpetuation of the position of the original corner. Bearings given are magnetic. Standard remonumentation pipe consists of a Bermtsen stalnless steel 2 3/8" x 30" pipe with a brass cap stamped "MONTCALM COUNTY REMONUMENTATION, P.S. # 30104"	5. De	ecember 1988, Glen Sleigh shåe	S. Hackbardt#	25844, LCR		13 Liber 002 Page	239			ZAN.	ILLIAM	G.	
CMP N80°W 167.80 feet 1989, William R. Byl # 23502, Survey 22-Mile Road Right of Way MI Bell cable placement Found sleigh shoe No witnesses given B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found sleigh shoe in two pieces 11" below the road surface. The second piece was 16" below grade on the west side of the first. Both pieces were approximately 9" long. Found evidence of wood at the bottom of the hole. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set remonumentation pipe in place of sleigh shoe pieces. Set one piece on the east side of the pipe and the other piece on the west side. Set N/T N/S maple 36" S88°W 187.52 feet Set N/T S/S power pole N86°W 167.60 feet T/C east end CMP N38°E 40.16 feet Set N/T E/S quad elm 6" S60°W 38.68 feet This corner is accepted as the careful and faithful perpetuation of the position of the original corner. Bearings given are magnetic. Standard remonumentation pipe consists of a Berntsen stainless steel 2 3/8" x 30" pipe with a brass cap stamped "MONTCALM COUNTY REMONUMENTATION, P.S. # 30104"		Ash 15"							*	•			*
Found sleigh shoe No witnesses given B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found sleigh shoe in two pieces 11" below the road surface. The second piece was 16" below grade on the west side of the first. Both pieces were approximately 9" long. Found evidence of wood at the bottom of the hole. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set remonumentation pipe in place of sleigh shoe pieces. Set one piece on the east side of the pipe and the other piece on to west side. Set N/T N/S maple 36" Set N/T S/S power pole N86°W 167.60 feet Center E/S cable marker N04°E 37.95 feet T/C east end CMP N38°E 40.16 feet Set N/T E/S quad elm 6" Set O'W 38.68 feet This corner is accepted as the careful and faithful perpetuation of the position of the original corner. Bearings given are magnetic. Standard remonumentation pipe consists of a Berntsen stainless steel 2 3/8" x 30" pipe with a brase cap stamped "MONTCALM COUNTY REMONUMENTATION, P.S. # 30104"				NOO9A/	167 AD feet					S	URVEY		5
Found sleigh shoe No witnesses given B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found sleigh shoe in two pieces 11" below the road surface. The second piece was 16" below grade on the west side of the first. Both pieces were approximately 9" long. Found evidence of wood at the bottom of the hole. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set remonumentation pipe in place of sleigh shoe pieces. Set one piece on the east side of the pipe and the other piece on to west side. Set N/T N/S maple 36" Set N/T S/S power pole N86°W 167.60 feet Center E/S cable marker N04°E 37.95 feet T/C east end CMP N38°E 40.16 feet Set N/T E/S quad elm 6" Set O'W 38.68 feet This corner is accepted as the careful and faithful perpetuation of the position of the original corner. Bearings given are magnetic. Standard remonumentation pipe consists of a Berntsen stainless steel 2 3/8" x 30" pipe with a brase cap stamped "MONTCALM COUNTY REMONUMENTATION, P.S. # 30104"	c 41	CMP Son William R Rvii	# 23502. Survey	22-Mile Roa	d Right of Way N	il Bell cable place	ment		1	•			- T
 B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found sleigh shoe in two pieces 11" below the road surface. The second piece was 16" below grade on the west side of the first. Both pieces were approximately 9" long. Found evidence of wood at the bottom of the hole. C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set remonumentation pipe in place of sleigh shoe pieces. Set one piece on the east side of the pipe and the other piece on the west side. Set N/T N/S maple 36" S88°W 187.52 feet Set N/T S/S power pole N86°W 167.60 feet Center E/S cable marker N04°E 37.95 feet T/C east end CMP N38°E 40.16 feet Set N/T E/S quad elm 6" S60°W 38.68 feet This corner is accepted as the careful and faithful perpetuation of the position of the original corner. Bearings given are magnetic. Standard remonumentation pipe consists of a Berntsen stainless steel 2 3/8" x 30" pipe with a brase cap stamped "MONTCALM COUNTY REMONUMENTATION, P.S. # 30104" 	6. 1	Found steigh sho	oe						1	PRO	****** FE 0 G O	NAL GU	
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Set remonumentation pipe in place of sleigh shoe pieces. Set one piece on the east side of the pipe and the other piece on twest side. Set N/T N/S maple 36" Set N/T S/S power pole N86°W 167.60 feet Set N/T S/S power pole Center E/S cable marker N04°E 37.95 feet T/C east end CMP N38°E 40.16 feet Set N/T E/S quad elm 6" S60°W 38.68 feet This corner is accepted as the careful and faithful perpetuation of the position of the original corner. Bearings given are magnetic. Standard remonumentation pipe consists of a Berntsen stainless steel 2 3/8" x 30" pipe with a brass cap stamped "MONTCALM COUNTY REMONUMENTATION, P.S. # 30104"	B. D	escription of corner e	vidence found a	nd/or method	applied in restorir	ng or reestablishing second piece was	corner: 16" be	low g	rade o	n the v	vest si	ide of 1	the
Set remonumentation pipe in place of sieign since pieces. Set on pieces side. Set N/T N/S maple 36" Set N/T N/S maple 36" Set N/T S/S power pole N86°W 167.60 feet Center E/S cable marker N04°E 37.95 feet T/C east end CMP N38°E 40.16 feet Set N/T E/S quad elm 6" Se0°W 38.68 feet This corner is accepted as the careful and faithful perpetuation of the position of the original corner. Bearings given are magnetic. Standard remonumentation pipe consists of a Berntsen stainless steel 2 3/8" x 30" pipe with a brase cap stamped "MONTCALM COUNTY REMONUMENTATION, P.S. # 30104"	fic	st. Both pieces we	re approximate	iy 9° long. F	Office Auderine in	,, ,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,							
Set N/T N/S maple 36" Set N/T S/S power pole N86°W 167.60 feet Center E/S cable marker N04°E 37.95 feet T/C east end CMP N38°E 40.16 feet Set N/T E/S quad elm 6" S60°W 38.68 feet This corner is accepted as the careful and faithful perpetuation of the position of the original corner. Bearings given are magnetic. Standard remonumentation pipe consists of a Bermtsen stainless steel 2 3/8" x 30" pipe with a brass cap stamped "MONTCALM COUNTY REMONUMENTATION, P.S. # 30104"	S	et remonumentation	ent for corner an n pipe in place	d accessories of sleigh she	oe pieces. Ger or	erpetuate locating the ear	e positi st side	on of of the	the corr pipe :	ner: and the	e othe	r piece	e on th
Center E/S cable marker N04°E 37.95 feet Center E/S cable marker N04°E 40.16 feet T/C east end CMP N38°E 40.16 feet Set N/T E/S quad elm 6" S60°W 38.68 feet This corner is accepted as the careful and faithful perpetuation of the position of the original corner. This corner is accepted as the careful and faithful perpetuation pipe consists of a Berntsen stainless steel 2 3/8" x 30" pipe with a brass cap stamped "MONTCALM COUNTY REMONUMENTATION, P.S. # 30104"	**	Set N/T N/S ma	ple 36"	-					LIBER 4	1	PAG	E 249	
T/C east end CMP N38°E 40,16 feet Set N/T E/S quad elm 6" \$60°W 38.68 feet This corner is accepted as the careful and faithful perpetuation of the position of the original corner. This corner is accepted as the careful and faithful perpetuation of the position of the original corner. Bearings given are magnetic. Standard remonumentation pipe consists of a Bermsen stainless steel 2 3/8" x 30" pipe with a brass cap stamped "MONTCALM COUNTY REMONUMENTATION, P.S. # 30104"		Set N/I S/S pov	e marker		37.95 feet	(1816) 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	IL(1)		general I	•	,		
Set N/T E/S quad elm 6" \$60°W \$50.00 reet. This corner is accepted as the careful and faithful perpetuation of the position of the original corner. Bearings given are magnetic. Standard remonumentation pipe consists of a Berntsen stainless steel 2 3/8" x 30" pipe with a brass cap stamped "MONTCALM COUNTY REMONUMENTATION, P.S. # 30104"		T/C east end C/	MP	N38°E									
Bearings given are magnetic. Standard remonumentation pipe consists of a Berntsen stainless steel 2 3/8" x 30" pipe with a brass cap stamped "MONTCALM COUNTY REMONUMENTATION, P.S. # 30104"		Set N/T E/S qua	ad elm 6"	S60°W	38,68 feet metuation of the	position of the or	iginal c	orner					
cap stamped "MONTCALM COUNTY REMORGINERY ATTON," 1817	This C	orner is accepted a	s the careful ar	ia taitintui pe	themanyn or me	bearings at any	-					•	
	Bearin	ngs given are magn	etic. Standard	remonument	tation pipe consi ATION, P.S. # 301	sts of a Berntsen s 104"	stainles	s ste	el 2 3/8	" x 30'	' pipe	with a	brass
	cap st	tamped "MON FCAL	IN COON I RE	.,									
						/ /	1111	/ <u>`</u>			*		

Surveyor's Michigan License No.