MONTCALM COUNTY REMONUMENTATION PROGRAM

LAND CORNER RECORDATION CERTIFICATE

SECTION

For corners in

Filing Requirement of Act 74, Mich. P.A. 1970

<u>M</u>	ontcalm (County)	Located In: Home Township	Corner Code #			MONT	OF MIC CALM CO RECORDS	UNTY			
1. F	Public Land Survey Sec 21 & 28	TR	F-09			27 OCT 1 LOR REGIS	999 12 II A. W STER OF	ILSON	PM		
ii 3. N	Property Controlling S In Section S Aliscellaneous S Property in Sec. S	TR _TR _TR _TR		R	egister of	Deeds S	Stamp	& File I	Numbe	r	
4. L 5. F	ot No, Recorded	Plat			1 A B	C D	E F	Б Н	IJK	L M	
					2 6	5	4	3	2·	i	
l,	William G. Tingley ereby certify that under requirem	a field su nents of P.A. 74, Michigan P.A	. of 1970, the come	ber 29, 1998,	4 7	8	9	10	11	12	
in lines 1 and 2 above were in conformance with regulations and rules therefore as required in current manual of survey instructions of the United States Department of the Interior, Bureau of La Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 are above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree Court of Law; established, re-established, monumented, re-monumented, recovered, found expressed below:					6 18	3 17	16	15	14	- 13	
					8 19	20	21	22	23	24	
САРІС	ssee below.				9 10 30	29	28	27	26	25	
NOT	E: Not more than 2 corners on this certificate.	s, all in the same town ar	nd range, may be	erecorded	11 31	32	33	34	35	36	
A. Description of original monument and accessories and / or subsequent restoration: 1. November 1837, John Milroy, Deputy Surveyor, G.L.O. Notes. West corrected between 21 + 28 39 87% (2631 42 feet) Set % Section post 79 75 (5263 50 feet) set section corner GROUP AS THE OFFICIAL CORNER UNDER MI										RVEY PE	
39.87½ (2631.42 feet) Set ½ Section post, 79.75 (5263.50 feet) set section corner Beech 8" N74°W 4 Links Maple 6" S62°E 23 Links 2. June 19 th & 20 th , 1874, F.A. Palmer, County surveyor notes, Book 1, Page 19. Drawing shows F09 as being 39.74 (2,622.84′) east of E09 and 39.97 (2,638.02′) north of F10 Notes do not say what was found at corner 3. May 24 th , 1880, F.A. Palmer, County surveyor notes, Book 1, Page 221. Drawing shows F09 as being 40.13 (2,648.58′) west of G09 Notes do not say what was found at corner 4. September 19 th , 1881, F.A. Palmer, County surveyor note, Book 1, Page 247. Drawing Shows F09 as being 40.16 (2,650.56′) west of G09 Notes do not say what was found at corner (Continued on Back)											
В.											
C.	Description of monument for	scription of monument for corner and accessories established to perpetuate locating the position of the corner									
	Top Bolt of Hydrant Found MSHD Nail and	l Tag in NE side power pol	N35°W North	ox. 51.43 Feet 29.60 Feet 47.05 Feet 83.08 Feet		Miletalatti tanish was	* PH	WILLIAN TINGL OFESS SURVEY NO. 30104	OR OR	A ROS	
	ings given are magnetic. Stan stamped "Montcalm County R			n Stainless Steel 3	0" x 2 3/8"	pipe with	n a Bra	TES101 Vesta, n. 1 SS	(1) h/v 3		
Signe	ed by Wille	Class I	Date	8-18	, 1999						
Surv	eyor's Michigan License No	30104			PROVED BY MICH	IGAN STATE B	OARD OF L		REVISED N		
				LIBER 4	PAGE 168	}					

2501100

Continued from Section A.

5. August 2nd – 4th, 1898, H.M. Caulkin, County surveyor notes, Book 2, Page 71.

Drawing shows F09 as being south 39.96 (2,637.36') of F08

At ¼ post S. side of sec. On road bed fill 8 feet deep. Took range of both sides of Main street of Edmore ran then east to ¼ post, found at 80 ft wide. Fence post on north side appears to be placed a stake of village plat survey, east ¼ post 40 ft south of it.

6. August 12th, 1912, E.D.Y. County Surveyor, Survey Notes.

1/4 post 21+28 - Found remains of H.M.C.s Fence post. Drove solid steel bar 1 1/4" x 24" and took N.B.T.

Elm 8 (n.m.) N01°E 68 Feet, 10 Inches

7. No Date, R.D. McNutt, note card file #82

1/4 post 21-28

 Beech 8"
 N74°W
 4 Links

 Maple 6"
 \$62°E
 23 Links

H.M.C. 1898 fence post 40 ft north

E.D.Y. 1912 steel bar 11/4" x 24"

Elm 8(n.m.) N01°E 68 Feet, 10 Inches

Found stone and iron set by F.A. Palmer

8. No Date, County Road Commission Card, Note card file #111.

1/4 corner 21-28 Home Township

telephone pole S.E. 48.09 Feet center top of hydrant N.W. 93.29 Feet 9. 2/19/64, Norman Caldwell, #12018, Found ½" angle iron in Monument Box

Telephone Pole S53°E 48.09 Feet
Center Top Fire Hydrant N70°W 93.29 Feet
Telephone Pole N06°W 29.70 Feet

10. 8/2/74, F.E. Spicer, Registration #7877, L.C.R.C., Liber 1, Page 141.

Found "U" shaped iron in mon box and accepted as corner

Nail-tag NE side MBT pole S50°E 48.20 Feet Spk NW side MBT pole S65°W 83.13 Feet Nail-tag SW side CP pole N05°W 29.58 Feet

11. April 14, 1978, John A. Merdzinski, Registration #10697, Certificate of Survey, Liber 512, Page 1216.

N1/4 corner section 28, T12N-R6W "U" iron in mon box

Nail & tag N.E. side telephone pole S50°E 48.20 Feet Spk. NW side telephone pole S65°W 83.13 Feet Nail & tag in W. Side power pole N05°W 29.58 Feet

12. May 19th, 1983, Allan L. Meyer, Registration #15406, Certificate of Survey.

N1/4 corner – "U" iron in mon box

Nail & tag N.E. side telephone pole S50°E 48.20 Feet Spk. NW side telephone pole S65°W 83.13 Feet Nail & tag in W. Side power pole N05°W 29.58 Feet 13. January 11th, 1988, William B. Ruddell, Certificate of Survey, Liber 613, Page 1246.

N1/4 corner section 28 T12N-R6W, Home Township, Montcalm County, Michigan, Found mon box

MSHD in power pole North 29.55 Feet MSHD in telephone pole SE 48.3 Feet Nail and Cap in telephone pole WSW 83.1 Feet Centerline fire hydrant WNW 93.4 Feet

14. January 21st, 1988, William B. Ruddell, registration #14769, L.C.R.C., Liber 2, Page 186.

F-9 mon box

MSHD in power pole North 29.55 Feet MSHD in telephone pole SE 48.3 Feet Nail and Cap in telephone pole WSW 83.1 Feet Centerline fire hydrant WNW 93.4 Feet

15. 6/10/88, Thomas J. Mueller, Registration #25861, Certificate of Survey.

Found Monument Box

Telephone poleSE48.27 FeetPower poleNorth29.57 FeetTelephone poleWSW83.05 FeetTop centerline hydrantWNW93.26 Feet

16. 6/17/88, Thomas J. Mueller, Registration #25861, L.C.R.C., Liber 2, Page 234.

F-9 found monument box

Telephone poleSE48.27 FeetPower poleNorth29.57 FeetTelephone poleWSW83.05 FeetTop centerline hydrantWNW93.26 Feet

17. 6/13/89, William G. Tingley, Registration #30104, Certificate of Survey.

South 1/4 corner, section 21, T12N-R6W,

As recorded in L 1 Pg. 141

18. 6/24/92, William G. Tingley, Registration #30104, Certificate of Survey.

N1/4 corner section 28, T12N-R6W, Found 1" IP in Mon Box

MSHD in power pole

MSHD in telephone pole

MSHD in telephone pole

Nail and Cap in telephone pole

Centerline fire hydrant

North

SE

48.3 Feet

WSW

83.1 Feet

WNW

93.4 Feet

19. 5/5/94, Duane F. Wood, Registration #24625, Certificate of Survey, Liber 720, Page 698.

North 1/4 corner section 28, T12N-R6W, Found "U" shaped iron in mon box

MSHD Tag in power pole Az. 0° 29.60 Feet MSHD Tag in telephone pole Az. 128° 48.25 Feet Top nut centerline on hydrant Az. 305° 77.99 Feet MSHD Tag in telephone pole Az. 256° 83.13 Feet