SUMVEY & REMONUMENTATION

SECTION

For corners in

4. Lot No. ___

LAND CORNER RECORDATION CERTIFICATE

Filing Requirement of Act 74, Mich. P.A. 1970

LIBER **3121** PAGE **64**5

Lotte V
STATE OF MICHIGAN
COUNTY OF MUSTEGEN
RECEIVED FOR RECORD

200 DEC 20 PM 1: 48


Marky	27	in Silver
REGISTER	OF	DEEDS

Muskegon (County)	Located In:	Corner Code #	
1. Public Land Survey	T <u>9N</u> R <u>14W</u> T R T R	<u>B-6</u>	
2. Property Controlling S in Section S	T R T R		·
3. Miscellaneous S. Property in Sec. S.	TR TR		Register of D

Deeds Stamp & File Number

5. Private Claims			
Stephen V. Vallier , in a field survey on <u>November 7</u> , 20 00 do hereby set under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in line and 2 above were in conformance with regulations and rules therefore as required in the current anual of survey instructions of the United States Department of the Interior, Bureau of Lanagement or by a decree of a Court of Law and /or that the corner points mentioned in lines and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or becree of a Court of Law; established, re-established, monumented, recovered, found as expressions:	rent and 3, 4		

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.



Description of original monument and accessories and/or subsequent restoration:

Corner was not set by G.L.O.

____, Recorded Plat

1934 Muskegon County Road Commission set a 2" wood stake by occupation.

43.70 Pine Stump **NNW** 4" White Cherry NNE 36.10 SE 60.47 8" Red Oak

Stan Shackelford of Westshore Consulting found a 20d penny spike at the occupation line South. Checks with two out of 1990 three witness from 1934. Corner position was accepted because the occupation in the section is based upon this location. True center of section would be approximately 16.5' North and 39.0' West of the found corner. Corner recorded in L.C.R.C., Liber 1547, Page 677.

S 50° E 61.52' 30" Oak N 42° W 49.82' 3" Oak N 09° W 34.85' Telephone Pole N 32° E 50.92' 12" Oak S 48° W 145.84' NW Corner of House No. 921	S	27° W	7 29.98'	Telephone Pole
N 09° W 34.85' Telephone Pole N 32° E 50.92' 12" Oak	S	50° E	61.52'	30" Oak
N 32° E 50.92' 12" Oak	N	42° W	7 49.82	3" Oak
	N	09° W	7 34.85 ^t	Telephone Pole
S 48° W 145.84' NW Corner of House No. 921	N	32° E	50.921	12" Oak
5 46 W 145.64 1 W Comer Of House No. 521	S	48° W	7 145.84'	NW Corner of House No. 9219


RECORDED CORNER REVIEWED & RATIFIED BY MUSKEGON COUNTY PEER GROUP IN ACCORDANCE WITH P.A. 345, OF 1990

Description of corner evidence found and/or method applied in restoring or reestablishing corner:

A 4"x 30" cast-iron monument containing a "County Surveyors" cap was found on the occupation line to the South. Witnesses check with L.C.R.C. recorded in Liber 1547, Page 677. A 2" iron at the East 1/8 corner has been destroyed. Position of the existing corner accepted du to historical usage and documentation.

Description of monument for corner and accessories established to perpetuate locating the position of the corner:

A 4" x30" cast-iron monument containing a "County Surveyors Cap" was found. 09° W Found nail on E side N 34.85 Telephone Pole 48° W S 145.84 NW Corner of House No. 9219 32° E N 53.92' 12" Oak Found nail on E side 50° E 30" Oak Found nail on N side 61.521 S 6" Oak Found nail on NE side 49.82'



Signed by

28428 Surveyor's Michigan License No.

A2113