\bigcirc	SIETS
To rai	NOTHING TON

£28 0 € 1999

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN COUNTY OF MUSKEGEN RECEIVED FOR RECORD

For corners in SECTION Muskegon (County)	Located In:	Corner Code #	
1. Public Land Survey	T <u>9N</u> F T F T F T F		
 Property Controlling In Section Miscellaneous Property in Sec. 	S T F S T F S T F		

1998 DEC 23 AM 8: 11 Parrie Carter

IBER 2187 PAGE 889

Register of Deeds Stamp & File Number

41.5

, in a field survey on December 9 I, Stephen V. Vallier do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and /or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below:

NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate.

__, Recorded Plat

1998

7

بارار POSITION OF SAID

RECORDED CORNER

REVIEWED & RATIFIED

BY MUSKEGON COUNTY PEER GROUP IN ACCORDANCE

WITH P.A. 345, OF 1990

Description of original monument and accessories and/or subsequent restoration:

1837

5. Private Claims /

G.L.O. set corner.

58° W Ν

6 Links

8" Beech

44° S

E

22 Links

12" Beech

1936

E. Scharmer found an iron pipe.

NE 75.70 5" Cherry

44.10 SE

8" Tree

2652.28 N 2640.42 Section Corner

S

Section Corner

1970

F. Smith reset corner by single proportionate measure, section (I -9) corner to 1/2 corner, 2,645.80'; 1/2 corner of section (1 - 7) corner, 2,645.79'.

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found a 1/2" iron rod set by F. Smith in 1970. In 1936, corner was found by E. Scharmer, computes 6' South of 1/2" iron rod. No evidence of corner. Prorated position of obliterated corner by E. Schirmer's dimension of 1936. Reset 21/2"x30" cast-iron monument 6.23' South of 1/2" iron rod. The boundary occupation to the East is an old and new fence line 1' North of obliterated corner. Fence line to the West is an ancient fence line lying on the ground 2.5' North of obliterated corner.

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Set 23/4" x 30" cast-iron monument with surveyors cap. 11/2" iron pipe with cap N 77° W 33.20 W 86° Power pole W 37.27 21.35 Guy pole S 89° Ε Found 1/2" iron rod 6.33' Ν Gate post 36.33" 38° E 87° Fence corner 26.70 Ē S 18" Ash 59.53 N 20° Ε 289.97 Power pole 10° S w

Nail set on North side Nail set on South side Set by F. Smith

Nail in south side Nail in west side Nail in west side



Signed by . Surveyor's Michigan License No.