LIBER 2324 PAGE 880

REMONUMENTATIO:

FEB 0 9 2000

SECTION

Surveyor's Michigan License No.

1999 DEC 16 AM II: 03

FORM APPROVED BY MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, REVISED MAY 14
REVISED JAN., REVISED JAN., REVISED OCT.,

Muskegen County Register of Deeds Muskegen, Michigan

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

Abstract	For corners	in		•		
T R R R R R R R R R R R R R R R R R R R			Located In:	Corner Code #		
2. Property Controlling S T R R IN Section 1. Section S S T R R R 3. Miscellaneous S T R R R 4. Lot No. Recorded Plat 5. Private Claims 1. Stochen V. Valler 1. Shorten V.	1. Public L	and Survey	T R _ T R _			
1. Stephen V. Vattler do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 shove were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interios, Bureau of Land Management or by a discrete of a Court of Law and not that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decrete of a Court of Law and lot that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decrete of a Court of Law and lot that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decrete of a Court of Law and lot that the corner points mentioned in lines 3, 4 and 5 above were in conformance satabilished, re-established, mornium-mented, recovered, found as expressed below with the rules of the Michigan Board of Land Surveyors or by a Decrete of a Court of Law with the rules of the Michigan Board of Land Surveyors or by a Decrete of a Court of Law and lot that the corner points mentioned in lines 3, 4 and 5 above were in conformance as a count of the Michigan Board of Land Surveyors or by a Decrete of a Court of Law and lot that the corner end accessories and/or subsequent restoration: 1837 G.L.O. (John Mullett) set corner post. Note that the G.L.O. from TSN, R14W intersected the north boundary at post. 1837 G.L.O. (John Mullett) set corner post. Note that the G.L.O. from TSN, R14W intersected the north boundary at post. 1839 S. S.D. S. S.D. S. S.D. S.S. S.D. S.S. S.D. S.S. S.D. S.S. S.D. S.S. S.D.	In Section 3. Miscella	on S. ineous S.	T R _		Register of Deeds S	Stamp & File Numbe
I, Stechen V. Valler do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law; and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law; and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, recovered, found as expressed below: NOTE: Not more than 2 cornere, all in the seme town and range, mey be recorded on this conflictet. 1837 G.L.O. (John Mullett) set corner post. Note that the G.L.O. from TSN, R14W intersected the north boundary at post. N 15' W 19 Links 3' Sugar N 15' W 19 Links 1' Sugar N	4. Lot No.	, Re	ecorded Plat			
in a field survey on November 19.98. do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 gbove were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with required to the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, remumented, recovered, found as expressed below: NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this cordificate. NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this cordificate. NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this cordificate. NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this cordificate. NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this cordificate. NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this cordificate. NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this cordificate. NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this cordificate. NOTE: Not more than 2 corners and accessories and/or subsequent restoration. NOTE: Not more than 2 corners and accessories and/or subsequent restoration. NOTE: Not more than 2 corners and accessories and all in the corner and accessories and all in the corners and accessories. Set all all in the corner side. NOTE: Not mor					T ABCDEF	GHIJKI
NOTE: Not more than 2 corners, all in the same town and range, may be recorded on this certificate. 1837 G.L.O. (John Mullett) set corner post. Note that the G.L.O. from T8N, R14W intersected the north boundary at post. N 40° E 23 Links 12' Sugar N 15° W 19 Links 8' Sugar 1950's M.C.R.C. witness tie book - iron bolt SE 35.00' Street Sign NW 81.50' Power Pole NE 63.55' 20" Maple ENE 95.20' 15" Elm WSW 72.35' Power Pole G.L.O. from T8N, R14W intersected the north boundary at post. B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found a 2 %"x 30' cast-iron Monument with a county surveyors cap in monument box at the road intersection. No evidence of closing corner flank (W.C.) Accepted the position of found corner from historical usage. Un supportive documentation of G.L.O. perpetuation. N 33° E 63.36' 50" Maple C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Accepted the found 2½"x30" cast-iron Monument with county surveyors cap in a monument box at the intersection of G.L.O. perpetuation. N 33° E 63.36' 18" Twin Locust Set a 20d nail in the east side N 70° E 77.47' 10" Maple Set a 20d nail in the southeast side S 50° W 121.35' 12" Poplar Set a 20d nail in the cast side N 56° W 81.14' Power Pole Found P.K. nail in the south side S 484.28	do hereby a points mentherefore a Department and for the with the ru	state that under re- tioned in lines 1 and is required in the co t of the Interior, Bur t the corner points les of the Michigan	quirements of P.A. 74, I d 2 above were in confi- current manual of survey reau of Land Managemer mentioned in lines 3, 4 Board of Land Surveyors	Michigan P.A. of 1970, the co ormance with regulations and r r instructions of the United Sta at or by a decree of a Court of I and 5 above were in conforma s or by a Decree of a Court of L	1 2 6 5 4 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9	10 11 1
A. Description of original monument and accessories and/or subsequent restoration: 1837 G.L.O. (John Mullett) set corner post. Note that the G.L.O. from TSN, R14W intersected the north boundary at post. N 40° E 23 Links 12° Sugar N 15° W 19 Links 8° Sugar 1950's M.C.R.C. witness tie book - iron bolt SE 35.00° Street Sign NW 81.50° Power Pole BY MUSKEGON COUNTY PEER GROUP IN ACCORDANCE WITH P.A. 345, OF 1990 1900 My 72.35° Power Pole G.L.O. from TSN, R14W intersects north boundary at post B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found a 2 ½" x 30° cast-iron Monument with a county surveyors cap in monument box at the road intersection. No evidence of closing corner TSN, R14W (common by G.L.O.) Accepted the position of found corner from historical usage. Un supportive documentation of G.L.O. perpetuation. N 33° E 63.38° 50" Maple C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Accepted the found 2½"×30° cast-iron Monument with county surveyors cap in a monument box at the intersection of road. N 24° W 63.86° 18" Twin Locust Set a 20d nail in the east side N 70° E 77.47' 10" Maple Set a 20d nail in the southeast side S 50° W 121.35' 12" Popular Set a 20d nail in the cast side N 70° E 77.47' 10" Maple Set a 20d nail in the south side Surveyor No. 284.28.						22 23 2
A. Description of original monument and accessories and/or subsequent restoration: 1837 G.L.O. (John Mullett) set corner post. Note that the G.L.O. from T8N, R14W intersected the north boundary at post. N 40° E 23 Links 12" Sugar N 15° W 19 Links 8" Sugar 1950's M.C.R.C. witness tie book - iron bolt SE 35.00° Street Sign NW 81.50° Power Pole NE 63.55' 20" Maple ENE 95.20' 15" Elm WSW 72.35' 20" Elm WSW 72.35' Power Pole G.L.O. from T8N, R14W intersects north boundary at post B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found a 2 ½" x 30' cast-iron Monument with a county surveyors cap in monument box at the road intersection. No evidence of closing corner T8N, R14W (common by G.L.O.) Accepted the position of found corner from historical usage. Un supportive documentation of G.L.O. perpetuation. N 33° E 63.38' 50" Maple C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Accepted the found 2½" x30" cast-iron Monument with county surveyors cap in a monument box at the intersection of road. N 24° W 63.86' 18" Twin Locust Set a 20d nail in the east side N 70° E 77.47' 10" Maple Set a 20d nail in the southeast side S 50° W 121.35' 12" Poplar Set a 20d nail in the cast side N 70° E 77.47' 10" Maple Set a 20d nail in the south side N 56° W 81.14' Power Pole Found P.K. nail in the south side N 28428.			, all in the same town and r	ange, may be recorded	'	
A. Description of original monument and accessories and/or subsequent restoration: 1837 G.L.O. (John Mullett) set corner post. Note that the G.L.O. from T8N, R14W intersected the north boundary at post. N 40° E 23 Links 12° Sugar N 10° W 19 Links 8° Sugar 1950's M.C.R.C. witness tie book - iron bolt SE 35.00' Street Sign NW 81.50' Power Pole NE 63.55' 20° Maple ENE 95.20' 15° Elm SW 58.15' 20° Elm WSW 72.35' Power Pole G.L.O. from T8N, R14W intersects north boundary at post B. Description of corner evidence found and/or method applied in restoring or reestabilishing corner: Found a 2 ½"x 30' cast-iron Monument with a county surveyors cap in monument box at the road intersection. No evidence of closing corner 18N, R14W (common by G.L.O.) Accepted the position of found corner from historical usage. Un supportive documentation of G.L.O. perpetuation. N 33° E 63.38' 50" Maple C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Accepted the found 2½"x30" cast-iron Monument with county surveyors cap in a monument box at the intersection of road. N 24° W 63.86' 18" Twin Locust Set a 20d nail in the east side N 33° E 63.38' 50" Maple Found nail in the east side N 70° E 77.47' 10" Maple Set a 20d nail in the cast side N 70° E 77.47' 10" Maple Set a 20d nail in the couths side S 50° W 121.35' 12" Poplar Set a 20d nail in the cost side N 56° W 81.14' Power Pole Found P.K. nail in the cost side Found P.K. nail in the south side S 11 Power Pole Set 20d nail in the cast side Found P.K. nail in the south side S 23428 C. 23428 C.					11 31 32 33	34 35 3
N 40° E 23 Links 12" Sugar N 15° W 19 Links 8" Sugar 1950's M.C.R.C. witness tie book - iron bolt SE 35.00' Street Sign NW 81.50' Power Pole NW 81.50' Power Pole SW 58.15' 20" Maple ENE 95.20' 15" Elm WSW 72.35' Power Pole G.L.O. from T8N, R14W intersects north boundary at post B. Description of corner evidence found and/or method applied in restoring or reestablishing corner: Found a 2 ½" x 30' cast-iron Monument with a county surveyors cap in monument box at the road intersection. No evidence of closing corner T8N, R14W (common by G.L.O.) Accepted the position of found corner from historical usage. Un supportive documentation of G.L.O. perpetuation. N 33° E 63.38' 50" Maple C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Accepted the found 2½" x30" cast-iron Monument with county surveyors cap in a monument box at the intersection of road. N 24° W 63.86' 18" Twin Locust Set a 20d nail in the east side N 70° E 77.47' 10" Maple Set a 20d nail in the southeast side S 75° E 187.67' Power Pole Set a 20d nail in the cast side N 70° E 77.47' 10" Maple Set a 20d nail in the cost side S 50° W 121.35' 12" Poplar Set a 20d nail in the cost side S 50° W 121.35' 12" Power Pole Found P.K. nail in the south side S 284.28 S 284.28 S 284.28	A. Descrip	tion of original mor	nument and accessories a	and/or subsequent restoration:	/	
Found a 2 ½"x 30' cast-iron Monument with a county surveyors cap in monument box at the road intersection. No evidence of closing corner T8N, R14W (common by G.L.O.) Accepted the position of found corner from historical usage. Un supportive documentation of G.L.O. perpetuation. N 33° E 63.38' 50" Maple C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Accepted the found 2¾"x30" cast-iron Monument with county surveyors cap in a monument box at the intersection of road. N 24° W 63.86' 18" Twin Locust Set a 20d nail in the east side N 33° E 63.38' 50" Maple Found nail in the west side N 70° E 77.47' 10" Maple Set a 20d nail in the southeast side S 75° E 187.67' Power Pole Set a 20d nail in the north side S 50° W 121.35' 12" Poplar Set a 20d nail in the cast side N 56° W 81.14' Power Pole Found P.K. nail in the south side S 28428 C 28428	`	N 40° E 2: N 15° W 19 M.C.R.C. witness t SE 35.00' NW 81.50' NE 63.55' ENE 95.20' SW 58.15' WSW 72.35'	3 Links 12" Sugar 9 Links 8" Sugar ie book - iron bolt Street Sign Power Pole 20" Maple 15" Elm 20" Elm Power Pole	POSITI REGO REVIE BY MI PEER WITH	TION OF SAID RDED CORNER WED & RATIFIED 7/13 USKEGON COUNTY GROUP IN ACCORDANCE	
T8N, R14W (common by G.L.O.) Accepted the position of found corner from historical usage. Un supportive documentation of G.L.O. perpetuation. N 33° E 63.38' 50" Maple C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Accepted the found 2½"x30" cast-iron Monument with county surveyors cap in a monument box at the intersection of road. N 24° W 63.86' 18" Twin Locust Set a 20d nail in the east side N 33° E 63.38' 50" Maple Found nail in the west side N 70° E 77.47' 10" Maple Set a 20d nail in the southeast side S 75° E 187.67' Power Pole Set a 20d nail in the north side S 50° W 121.35' 12" Poplar Set a 20d nail in the cast side N 56° W 81.14' Power Pole Found P.K. nail in the south side No. 28428	B. Descript	ion of corner evider	nce found and/or method	applied in restoring or reestabli	shing corner:	-
C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: Accepted the found 2½"x30" cast-iron Monument with county surveyors cap in a monument box at the intersection of road. N 24° W 63.86' 18" Twin Locust Set a 20d nail in the east side N 33° E 63.38' 50" Maple Found nail in the west side N 70° E 77.47' 10" Maple Set a 20d nail in the southeast side S 75° E 187.67' Power Pole Set a 20d nail in the north side S 50° W 121.35' 12" Poplar Set a 20d nail in the cast side N 56° W 81.14' Power Pole Found P.K. nail in the south side No. 28428	T8N, R1 perpetua	4W (common by G.I tion.	L.O.) Accepted the position			
Accepted the found 23/4"x30" cast-iron Monument with county surveyors cap in a monument box at the intersection of road. N 24° W 63.86' 18" Twin Locust Set a 20d nail in the east side N 33° E 63.38' 50" Maple Found nail in the west side N 70° E 77.47' 10" Maple Set a 20d nail in the southeast side S 75° E 187.67' Power Pole Set a 20d nail in the north side S 50° W 121.35' 12" Poplar Set a 20d nail in the cast side N 56° W 81.14' Power Pole Found P.K. nail in the south side No. 28428	14, 33	. UJ.JG	oo maho	•		
N 24° W 63.86' 18" Twin Locust Set a 20d nail in the east side N 33° E 63.38' 50" Maple Found nail in the west side N 70° E 77.47' 10" Maple Set a 20d nail in the southeast side S 75° E 187.67' Power Pole Set a 20d nail in the north side S 50° W 121.35' 12" Poplar Set a 20d nail in the cast side N 56° W 81.14' Power Pole Found P.K. nail in the south side N 50° W 81.14' Power Pole Found P.K. nail in the south side S 81.14' Power Pole Found P.K. nail in the south side N 50° W 81.14' Power Pole Found P.K. nail in the south side						•
N 33° E 63.38' 50" Maple Found nail in the west side N 70° E 77.47' 10" Maple Set a 20d nail in the southeast side S 75° E 187.67' Power Pole Set a 20d nail in the north side S 50° W 121.35' 12" Poplar Set a 20d nail in the cast side N 56° W 81.14' Power Pole Found P.K. nail in the south side N 50° W 81.4' Power Pole Found P.K. nail in the south side No. 28428					ent box at the intersection of ro	на.
28428	N 33° N 70° S 75° S 50°	E 63.38' E 77.47' E 187.67' W 121.35'	50" Maple Four 10" Maple Set Power Pole Set 12" Poplar Set	and nail in the west side a 20d nail in the southeast side a 20d nail in the north side a 20d nail in the cast side	VALLIER Land	
ADMINISTRATE OF THE PROPERTY O	Signed by	/_	A Man	Data		t.