REMUNUMENTATIO

LILLE 2326 PAGE 776

FEB 0 9 2000

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN COUNTY OF MUSKEGON

i NL O	CIVE	9) (IN IN	100	ΝŪ
939	חבר	27	OH	ın.	11 1

For corners in SECTION CT DEC 27 PM 12: 44 Corner Code # Located in: Muskegon (County) <u>9N</u> R 14W 1. Public Land Survey R R R T 2. Property Controlling Ţ In Section R 3. Miscellaneous Register of Deeds Stamp & File Number Property in Sec. , Recorded Plat

5. Private Claims in a field survey on December I, Stephen V. Vallier do hereby state that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and for that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law;

NOTE: Not more than 2 comers, all in the same town and range, may be recorded on this certificate.

established, re-established, monumented, recovered, found as expressed below:

1					
2 - 6-	\$ +		— 3 − 	2	— <u>1</u> —
3					- -
4 - 7 -	\$ 	þ -	10-	11	—12—
5					
6 -18-	-17-	16	15	-14-	13
7					
8 -19-	20	21	22	23	2'4
9					
10-30-	-29-	28	27	26	25
11					
12-31-	32-	33	34-	35	36-
13			<u> </u>		

A. Description of original monument and accessories and/or subsequent restoration:

G.L.O. (John Mullett) set the quarter section post.

W 8 Links 12" Maple

10° E Ν

4. Lot No.

9 Links

10" Elm

1950's M.C.R.C. notes a found iron in witness tie book.

MARK F. FAIRCHILD MUSKEGON COUNTY Register of Deeds Recorded Copy!

C.F. Lewandowski found a 3/4" iron pipe, reset with a 4" x 30" cast-iron monument recorded in L.C.R.C., Liber 1301,

Page 607. S

53.22

Power Pole

50° W S

116.50 25.50

Telephone Pole

45° W

Telephone Pole

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 4" cast-iron monument on tree row to the south. The corner is approximately 2' north of the north edge of an asphalt road and also appears to be the point of intersection of the roads. Accepted the position of corner due to historical usage and documentation. Evidence of

corner being a perpetuation of the original G.L.O. position is non-supportive.

53.22' 116.501 Power Pole

s 50° W

Power Pole

Found nail on north side

N 45° W

1984

25.50

Telephone Pole

Found nail on northwest side

POSITION OF SAID RECORDED CORNER REVIEWED & RATIFIED BY MUSKEGON COUNTY PEER GROUP IN ACCORDANCE WITH P.A. 345, OF 1990

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner:

Found a 4" cast-iron monument with county surveyor's cap. Corner is approximately 2' north of the north edge of asphalt road.

53.221 S

Power Pole

s .50° W 116.50 N 45° W 25.50

Power Pole Telephone Pole Found nail on north side

Found nail on northwest side

MICHIO STEPHEN VALÈIER Lend Surveyor No. 28428 LABO

Surveyor's Michigan License No.

form approved by michigan state board of professional surveyors, Jan. 26