APR 2 8 1995

Private Claims

COMMISSING

LIBER 1810 FACE 612

LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN COUNTY OF MUSKEGEN RECEIVED FOR RECORD

1994 DEC 29 AM 10: 17

Carrie Carter REGISTER OF DEEDS

A1636

Register of Deeds Stamp & File Number

For corners in Muskegon Located In: Corner Code ## т<u>9</u> R <u>15</u> 1. Public Land Survey R __ R . 2. Property Controlling T R ___ T ____ R _ in Section Miscellaneous Property in Sec.

____ , Recorded Plat _

I. Stephen V. Vallimer field survey on November do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

- 11 12 13
- A. Description of original monument and accessories and/or subsequent restoration:
 - GLO set corner 1837
 - E. Glaza L.C.R.C. Liber 1026 Page 895 1977
 - C.F. Lewandowski L.C.R.C. Liber 1242 Page 289 Found 1 1/2" iron Pipe also found 3/4" iron pipe 80.65' S (L. 1026, P. 895). Reset 1 1/2" iron pipe with 4" x 30" cast iron monument with County Survey Cap 1982
- B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

Found 4" cast iron monument with County survey Cap. Also found 3/4" iron pipe 80.65' South of this corner. Neither corner can be traced to origins of perpetuation. Based on Glaza L.C.R.C. one cannot determine if corner was lost, obliterated or found. After review of evidence decision to hold cast iron monument as correct position due to GLO corelation to creek calls.

POSITION OF SAID Supt 9, 1993 RECORDED CORNER REVIEWED & RATIFIE BY MUSIKEGON COU REVIEWED & RATIFIED BY MUSICEGON COUNTY PEER GLIOUP IN ACCORDANCE WITH P.A. 815, OF 1990

STEPHEN

VALLIER

Land

Surveyer

No. 28428 CAND

| G. | Description | of monument | for corner and | accessories es | tablished to perpe | tuate locating the pe | osition of the corner: |
|----|-------------|-------------|----------------|----------------|--------------------|-----------------------|---|
| | 4" Cast | Iron mor | nument wit | h County | Survey Cap | | 一种,一种,一种,一种,一种,一种,一种,一种,一种,一种,一种,一种,一种,一 |
| | S | 86.65' | 3/4" iror | pipe (L: | iber 1026 P | age 895) | OF MICH |

3/4" iron pipe (Liber 1026 Page 895) S 86.65'

36.45' 14" maple (dead) with nail 10 deg E

21" maple with nail S 55 deg E 24.63'

N 85 deg E 43.48' 20" Maple

79.30' 22" Maple

_____ Date ___ Du 27,1994 Signed by _

Surveyor's Michigan License No. 28428

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983