-SURVEY & REMONUMENTATION

LIBER 1810 PAGE

APR 2 8 1995

LAND CORNER RECORDATION CERTIFICATE

AS NO BLES PAR CONT.

___ , Recorded Plat _

Filing Requirement of Act 74 Mich PA 1070

Located In:	Corner Code =##			7 M	MICH MICH MICH MICH MICH MICH MICH MICH
⊤ 9N p 15W		1 . mil	<i>≅6</i>	7,11	
T R T R	E-11	Alsst	DEEDS T	II: 42	HIGAN HIGAN HIGAN
T R T R		Register of Dec	eds Stamp &	File !	Number
	T R T R T R T R T R T R T R R T R T R R T	T R T R T R T R T R T R T R T R T R T R	T R T R T R T R T R T R T R T R T R T R	T R T R T R T R T R T R T R T R T R T R	TR

, STEPHEN V. VALLIER, in a field survey on DECEMBER do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a

Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below: NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

12

Description of original monument and accessories and/or subsequent restoration:

1837 GLO SET SECTION CORNER N 42° E 11 LINKS 12" 1 N 53° W 10 LINKS 12" 1 HEMLOCK 12" HEMLOCK 12" HEMLOCK 1990 R. VANRIPER LBR. 1542, PG. 362 STAN SHACKELFORD FOUND "T" IRON OVER 1" X 2" PIPE

1950'S M.C.R.C. N 70.8' 4" CHERRY SE 112.53 10" W.O. SW 51.79' 3RD FENCE POST

Private Claims

Description of corner evidence found and/or method applied in restoring or reestablishing corner: FOUND 4" CAST IRON MONUMENT WITH COUNTY SURVEY CAP — ACCEPTED POSITION OF CORNER DUE TO HISTORICAL USAGE AND CONSISTENT DOCUMENTATION

N 54° E 51.78' NAIL S. SIDE 10" ASH
N 9° E 55.81' NAIL E. SIDE P. POLE
S 24° E 34.60' NAIL E. SIDE 4-6" TIWN ELM
S 55° E 66.72' NAIL N. SIDE 8" ELM
S 33° E 74.76' NAIL W. SIDE 4-6" TWIN ELM

ang 2, 1994 POSITION OF SAID RECORDED CONNER REVIEWED & CATELED BY MUSICEGON COUNTY PHER GROUP IN ACCORDANCE WITH F.A. 845, OF 1999

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: FOUND 4" CAST IRON MONUMENT WITH COUNTY SURVEY CAP

NAIL S. SIDE 10" ASH
NAIL E. SIDE P. POLE
NAIL E. SIDE 4-6" TWIN ELM
NATT N. SIDE 8" ELM
TWIN ELM 54° I 9° E 24° I 55° I 33° I 51.78' 55.81' 34.60' 66.72' NAIL N. SIDE 8" ELM NAIL W. SDIE 4-6" TO TWIN ELM

Signed by _

Surveyor's Michigan License No.

Land Surveyo No.

28428

Date

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 197

REVISED MAY 14, 19: