## um 1744 mm 556

STATE OF MICHIGAN

## COMMISSION

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

COUNTY OF MUSKEGEN RECEIVED FOR RECORD

1993 DEC 29 PH 4: 03

Carri	المار ال	2000
	CER OF DE	-

MUSKEGON (County)		Located In:		Corner Code //	Carrier Cartier
Public Land Survey		T9	N <sub>R</sub> 15W	F-2	
		T	R R		
2. Property Controlling	S	Т	R		•
in Section	S	Ţ	A		
3. Miscellaneous	S	Τ.	R	_	
Property in Sec.	S	T	R		Register of Deeds Stamp & File Number

I, STEPHEN V. VALLIER in a field survey on NOVEMBER 11, 1993 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below:

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

10 11 12 13

16" OAK

A. Description of original monument and accessories and/or subsequent restoration:

CORNER NOT SET BY G.L.O. SURVEY

29.85

6" OAK

10" OAK

Private Claims

1/2" IRON ROD SET BY L.F. LEWANDOWSKI, OCT. 1980

RECORDED LIBER 1211, PAGE 143

1 1/4" IRON PIPE M.C.R.C. 1955 NORTH NW NE SOUTH 29.90' 78.88

LOCATED 54.47' EAST AND 4.36' NORTH OF 1 1/4 PIPE N20°W N48°E S37°W

9" OAK

33.001 1/2" IRON

S47°E 33.00' 58.301

53,851 10" OAK

14" TWIN ROD

OAK

B. Description of corner evidence found and/or method applied in restoring or reestablishing corner:

FOUND 1/2" IRON ROD RECORDED IN LIBER 1211, PAGE 143

23.45

18" OAK

54.47' WEST AND 4.36' SOUTH OF FOUND 1/2" IRON ROD 1 1/4" IRON PIPE

S 40°W S 45°E 53.79' 58.231 10" TWIN OAK 16" OAK

HISTORICAL USAGE, DOCUMENTATION & EVIDENCE OF DOUBLE CORNERS REVIEWED BY MUSKEGON COUNTY PEER GROUP. AFTER EXAMINING THE EVIDENCE, IT WAS THE DECISION TO ACCEPT CENTER OF SECTION SET BY C.F. LEWANDOWSKI (INTERSECTION OF 1/4 LINES). CORNER LOCATION RATIFIED NOV. 16, 1993

C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: SET 4" X 30" CAST IRON MONUMENT WITH COUNTY SURVEY CAP IN PLACE OF 1/2" IRON ROD RECORDED IN LIBER 1211, PAGE 143.

1 1/4" PIPE 54.47' WEST AND 4.36' SOUTH

NORTH S 20°E N 32°E S 40°W N47°W · S 45°E 33.35' 52.13' 37.60' 53.791 63.73 58.237 FACE 4' 8" OAK 6" OAK 10" TWIN OAK 6" OAK 16" OAK RAILROAD TIE (FOUND NAIL (FOUND NAIL (FOUND NAIL (FOUND NAIL (FOUND SE'LY SIDE) E'LY SIDE) NW'LY SIDE) NAII. SW'LY

Signed by STEPHEN V. VALLIER

Surveyor's Michigan License No. 28428

≒ Ďate Su: vayo:  $M_{\odot}$ 

23423

Des 28, 1993

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975 REVISED JAN., 1983