### SURVEY & REMONUMENTATION

APR 0 3 1998

For corners in SECTION

## LIREP 2052 PAGE 635

### LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHIGAN COUNTY OF MUSKEGEN RECEIVED FOR RECORD

1797 DEC 30 PH 3: 24

REGISTER OF DEEDS

Register of Deeds Stamp & File Number

10

Muskegon		Located In:	Corner Code =	l
	(County)	LOURING III,	Comer Code 77	l
1.	Public Land Survey	T T9N R 16W	E-7	
		T R		l
		T R		
		T R		ļ
2.	Property Controlling	S T R		
	in Section	S T R		
3.	Miscellaneous	S T R		
	Property in Sec.	S T R	·	L

\_\_\_ , Recorded Plat 5. Private Claims \_

Stanley H. Shackelford, P.S. April 28, . in a field survey on 19 do hereby certify that under requirements of P.A. 74, Michigan P.A. of 1970, the corner points mentioned in lines 1 and 2 above were in conformance with regulations and rules therefore as required in the current manual of survey instructions of the United States Department of the Interior, Bureau of Land Management or by a decree of a Court of Law and/or that the corner points mentioned in lines 3, 4 and 5 above were in conformance with the rules of the Michigan Board of Land Surveyors or by a Decree of a Court of Law; established, re-established, monumented, re-monumented, recovered, found as expressed below

NOTE: Not more than 4 corners, all in the same town and range, may be recorded on this certificate.

A. Description of original monument and accessories and/or subsequent restoration:

E-7 GLO MAY 1837 SET POST S 07°W 3.96' 12" HEMLOCK S 05°E 10.56' 12" HEMLOCK

1950'S Muskegon County Road Commission witness Book-physical corner not described.

93.35' N.E. **SW Corner House** 28.75 South Face Fence Post S:W. 103.20 **NE Corner Shed** N N/W 73.15 Apple

(See Attached)

B. Description of corner evidence found and/or method applied in restoring or reestablishing ceme

E-7 FOUND 4" X 30" CAST IRON COUNTY SURVEY MONUMENTS

S. 76° E 123.66 Center of Fire Hydrant S. 41° E Found Spike-NE. Side 6" Spruce 40.721 S. 25° W 39.20' Found Spike-SW Side Clump Chinese Elm S. 55° E 116.69 N.W. Corner House No. 809 N. 66° W 49.92' Centerline-Man hole S. 82°W 177.72 Set Spike North Side Utility Pole

POSITION OF SAID RECORDED CORNER REVIEWED & RATIFIED BY MUSKEGON COUNTY PEER GROUP IN ACCORDANCE WITH P.A. 345, OF 1990

STANLEY ACKELFORD

LAND

SURVEYOR

NO.

30100

REVISED JAN., 1983

NOTE: RECENT CONSTRUCTION REMOVED MOST PREVIOUSLY USED WITNESSES

F. MICHIGANINA C. Description of monument for corner and accessories established to perpetuate locating the position of the corner: OF MICHIGA

#### E-7 FOUND 4" X 30" CAST IRON COUNTY SURVEY MONUMENT

S. 76°E 123.66 Center of Fire Hydrant Found Spike NE Side 6" Spruce S. 41°E 40.72 Found Spike SW Side Clump Chinese Elm S. 25°W 39.20 N. 66°W 49.92 Centerline of Manhole S. 82°W Set Spike North Side Utility Pole 177.72 S. 55°E 116.69 N.W. Corner House No. 809

Signed by <u>30100</u>

Date

Surveyor's Michigan Licéns No.

FORM APPROVED BY MICHIGAN STATE BOARD OF LAND SURVEYORS, JAN. 28, 1971 REVISED MAY 14, 1975

# SURVEY & REMONUMENTATION

LIBEP 2052 PAGE 636

APR 0 3 1998

TAN RIGW E-7

SECTION

1974	L1046 , P743 N.W. N.E. N.E. S.S/E. S.	Found P.K. Nail 69.25' 54.80' 45.60' 15.27' 33.00'	Spike in 12" poplar Spike in 26" Maple Spike in Telephone Pole Spike in Power Pole Concrete Monument
1980	L1199, P518 N.E. N.E. S.S/E S	Found Railroad Spike 54.84' 45.60' 15.23' 33.00'	26" Maple Telephone Pole Power Pole Concrete Monument
1989	L1481,P186 Set 4" X 30" Cas N. 45° E S. 10° E S. 75° E S. 55° E S. 80° W N. 75° E	Found Railroad Spike st Iron County Survey Monu 45.60' 15.27' 85.36' 116.69' 117.92' 133.63'	ment  Found Spike in Telephone Pole Found Spike in Power Pole Found Spike in 26" Maple N.W. Corner House No. 809 Set Nail in Maple Set Nail in Telephone Pole

Check Plat of Seng's Airport Subdivision