## SURVEY & REMONUMENTATION

JAN 3 1 2001

## LAND CORNER RECORDATION CERTIFICATE Filing Requirement of Act 74, Mich. P.A. 1970

STATE OF MICHGAN COUNTY OF MUSAEGON RECEIVED FOR RECORD

For corner	s in SEC	TION			TAIL DEC Z 1 PM IZ: 28
<del></del>	Muskegon (County)	Located	In: Cor	ner Code #	Mark For Ill
1. Public	Land Survey	T <u>10N</u> 1 T F T F		-11	REGISTER OF DEEDS
in Sect 3. Miscell		T I	3		Register of Deeds Stamp & File Number
4. Lot No.	, R	ecorded Plat	· · · · · · · · · · · · · · · · · · ·		— A B C D E F G H I J K L N
5. Private Claims					1
-	-				2 6 5 4 3 2 1 1 3 4 7 8 9 10 11 12 12
that under r and 2 abov manual of Managemer and 5 abov	equirements of I e were in confo survey instructi nt or by a decree e were in confo	, in a field survey on P.A. 74, Michigan P.A. or mance with regulations ons of the United State of a Court of Law and /mance with the rules of stablished, re-established	of 1970, the corner point and rules therefore as as Department of the li- or that the corner points the Michigan Board of	nts mentioned in lines in required in the curren nterior, Bureau of Land mentioned in lines 3, 4 Land Surveyors or by a	8 -19 - 20 - 21 - 22 - 23 - 24 - 9
	t more than 2 con this certificate.	omers, all in the same to	wn and range, may be r	ecorded	11 12 31 32 33 34 35 36 13
A. Descrij 1837 1950's	John Mullett S 16° W N 35° E	I monument and acces (G.L.O.) set post. 6" Beech 12" Hemlock ounty Road Commission	9 Links 16 Links		<b>,</b>
13200	NE 48. SE 82. NW 43.	62' 36" Maple 30' Power Pole	is withess sheet hotes.	a i mon pipe.	
1986	Stanley Shack N 42° W S 45° E N 70° E S 35° W	xelford of Westshore Co 41.30' 82.30' 100.00' 80.70'	nsulting found a 3/4" in Street Sign Power Pole 18" Maple Power Pole	ron pipe, unrecorded s	POSITION OF SAID RUGGED RECORDED CORNER 10/3/100 REVIEWED & RATIFIED BY MUSKEGON COUNTY PEER GROUP IN ACCORDANCE WITH P.A. 345, OF 1990
3. Descri	ption of corner	evidence found and/o	r method applied in re	estoring or reestablish	ing corner:
A ½" i accept	iron rod was fou ted due to the hi	and in the centerline of t storical usage and docu	he road intersection. C		een destroyed. Position of the existing corner was
C. Descrip	etion of monume	nt for corner and accessori	es established to perpetua	te locating the position of	the corner:
The ½ N 38 N 50	8° W 41.48			ing a "County Surveyor	STEPHEN
N 78	8° E 99.59	' 36" Maple	Set 20D nail or		VALLIER Land ¥
	5° E 65.27	Power Pole	Set 20 D nail o	on East side	Surveyor
South S 77	29.27 7° W 69.0'	' Power Pole 10" Poplar'	Set 20 D nail o Set 20 D nail o		No. 28428
	1	18/1/11			SO CAND SURV
Signed by	120/	VVM		Date/	7/19/04
urveyor's Mi	chigan License N	o. <u>2842</u>	<u> </u>	FORM APPROVED BY	MICHIGAN STATE BOARD OF PROFESSIONAL SURVEYORS, JAN. 28, 1971 REVISED MAY 14,1975 REVISED JAN., 1983 REVISED OCT., 1995